Name	Order (in 2008)	7967 2006		Outage/dredg s schedule		Cost	Service	Liner nates	Comments	YAD priority	YAD Year
Joket 29 Ast; Impoundment 2			2007	2007	7	1,1	gg/t				
Jolet 29 Ash Impoundment 1	į	21	2006	2008	-7	1,1	mh			i	
W-II County South Ash Impoundment 3	:		2008	(dredged every yr)	.7	0.6	ash	12" Pat-Q-Pitt, poor cond.	We'r needs work, (risk of another TVA?)	Α.	2009
REDACTED REDACTED		-	_								
Will County South Ash Impoundment 2 REDACTED			2006	(dredged every)r)	.7	06	ach	12" Poz-O-Pac, poor cond.	Welr needs work, (risk of another TVA7)	A	2009
Powerton Bypasa Basin				in 2006, 6 yr cycle, done with surge	.9	03	ash, regen, metal cleaning	Unknown	Recommend borings to determine ther, Small, needs made.	A	2011, coord with Powerton surge beein?
Powerton Secondary Ash Setting Basin			2010	not dredged in 14 ym	9	l	secondary setting sets, regen, metal deaming	nona	Weir needs work, (risk of another TVA?) Have solide accumulated? What is water quality (sheady equalized)?	A	2010
REDACTED									·		
Powerton Ash Surge Basin	11		2011			2.5	ash, regen, metal cleaning	12" Poz-O-Pac, poor cond. Hypolon on sides (freq mrt req)		A	2011, coord with Powerlan bypass basin?
Jolist 29 A&h Impoundment 3 REDACTED	12			2012 (based on outage schedule?)	٠,	0.7	Polishing/esh	12" Poz-O-Pac, poor cond.	How do we know the liner cond is poor? Should testing be done to verify need? What is water quality (after equalization)?	В	2012 If needed
REDACTED		-									
		-									
REDACTED		1									
REDACTED		-									
DACTED		-									
ACTED		-									
IACTED											1
Will County South Ash Impountment 1	20		2015		-1	0.5	sing		How do we know the liner cond is poor? Should testing bu done to verify need? Welr needs work. Fix weir skip liner replacement?	с	Fir weir, postpone liner?
REDACTED											
REDACTED		<u> </u>									1
Will County North Ash Impoundment	23		2016		1	06	ودنع	17' Poz-O-Pac, poor cond.	How do we know the liner cord to poor? Should lasting be done to verify need? Welr needs work, Fix weir stop liner replacement?	c	Flx wet, postpone liner?

MWG13-15_142

