



RE: Liner Replacement Permit - J29 Ponds 1 and 2 

Brian DelCorio to: James DiCola

Cc: Elsie Briette, "Frendt, Richard", Thomas Hiebert

07/16/2012 07:32 AM

Jim,

I do not know the original liner thickness since there was very little liner left when the new liners were installed.

Pond liners for 1 and 2 were installed April through October 2008.

Brian Delcorio, PE
ICE Specialist
Joliet Station
1800 Channahon Road
Joliet, IL 60436
Tel: 815 207-5440
Cell: 815 671-2293

James DiCola/Joliet/EMG/EIX




James DiCola/Joliet/EMG/EIX

07/14/2012 12:22 PM

To "Frendt, Richard" <RFrendt@patrickco.com>, Brian DelCorio/Joliet/EMG/EIX@EME,
Elsie Briette/Joliet/EMG/EIX@EME

cc Thomas Hiebert/Mostardi Platt Environmental/Joliet/EMG/EIX@EME

Subject RE: Liner Replacement Permit - J29 Ponds 1 and 2 

Rick,

Pond 3 does not contain a HDPE liner.

Brian and Elsie, Do you know off hand the thickness of the original clay liners in ponds 1 and 2?

Jim

James J. DiCola

MWG13-15_18047

Comp. Ex. 51

Environmental Specialist
Joliet Station
Midwest Generation, LLC
Phone (815) 207-5489
Cell (815) 671-0164
jdicola@mwgen.com

"Frendt, Richard"

Thanks, Jim.

07/14/2012 10:50:55 AM

From: "Frendt, Richard" <RFrendt@patrickco.com>
To: James DiCola <jdicola@mwgen.com>
Date: 07/14/2012 10:50 AM
Subject: RE: Liner Replacement Permit - J29 Ponds 1 and 2

Thanks, Jim.

We don't need the detailed specification for the liners just yet, but stay tuned. I assume there are no construction details of the original clay liners in 1 and 2 (thickness)? And is it fair to say that pond 3 does not contain a liner?

Regards,
Rick

Richard M. Frendt, P.E.
PATRICK ENGINEERING INC.
4970 Varsity Drive
Lisle, Illinois 60532-4101
Tel: 630.795.7464
Cell: 708.359.0806

From: James DiCola [mailto:jdicola@mwgen.com]
Sent: Friday, July 13, 2012 3:54 PM
To: Frendt, Richard
Cc: Brian DelCorio; Thomas Hiebert; Xinying Wang
Subject: Liner Replacement Permit - J29 Ponds 1 and 2

MWG13-15_18048

Rick,

The liner replacement permit is attached. The original liner was a clay liner in ponds 1 and 2. It was in place from the time the ponds were originally installed. The HDPE liners installed in ponds 1 and 2 in the 2007-2008 time frame (the attached permit is dated July 2007) were the first HDPE liners installed in ponds 1 and 2. Pond 3 is not lined with a HDPE liner.

Brian, does the installation time frame of 2007 - 2008 sound right?

I have draft technical specifications for the pond 2 liner replacement and the construction permit application. You are welcome to come to the station and review this information.

Jim

James J. DiCola
Environmental Specialist
Joliet Station
Midwest Generation, LLC
Phone (815) 207-5489
Cell (815) 671-0164
jdicola@mwgen.com