



Paul Pratapas <paulpratapas@gmail.com>

---

## Lexington Trace 2 SWPPP Approval Issues

---

Paul Pratapas <paulpratapas@gmail.com>

Thu, Jan 5, 2023 at 11:12 AM

To: Kristine Hocking <khocking@warrenville.il.us>

Cc: Patrick McPartlan <patrick.mcpartlan@kanedupageswcd.org>, Todd Bennett <todd.bennett@illinois.gov>, Molly Kordas <Molly.Kordas@ilag.gov>

Kristine,

Here is the drainage plan for the site. See all the arrows leaving the driveways? The water will move that way with gravity. If all the curbs are flat, which they are, a curbside BMP would be necessary until that area is stabilized. Or you get all the sediment laden water/pollutants going into the existing inlets, and retention pond which has not been seeded to filter via infiltration. This plan should never have been approved.

Kind Regards,

Paul Pratapas  
630.696.2843

[Quoted text hidden]

[Quoted text hidden]

2. These roads are at grade. Nowhere near flat and the only sediment control is perimeter silt fence. The minimum. All those curbs are flat to the ground, so all sediment and sediment laden water should have be known tombe uncontrolled.

3. Fake news sequence plan

4. This was 1,000% predictable from the plans and SWPPP and ignored why?

5. Zero curbside protection again

Paul Pratapas  
630.696.2843

---

### 3 attachments




Image 1-5-23 at 11.06 AM.jpeg  
252K



**IMG\_7747.JPG**  
3656K



**IMG\_7750.JPG**  
4338K