



*State of Illinois*  
**ENVIRONMENTAL PROTECTION AGENCY**

*Dave*

**MEMORANDUM**

DATE: October 17, 1997  
TO: OCS/ERU File  
FROM: Cheryl Kelley, Collinsville OCS-ERU *CK*  
SUBJECT: Marion Co/Wamac-Pryor Oil Company - Crude Oil Spill  
IEMA #971314


On September 11, 1997, this inspector conducted a site visit at the Pryor Kalver Kamp #1 Tank Battery. Two inches of crude oil was pooled within the soil containment berm. Crude oil residue was not visible in Fulton Creek from the above referenced incident. OCS Photograph Roll #202 shows the Kalver Kamp #1 Tank Battery with crude oil in a 30 feet by 40 feet area.

On October 17, 1997, this inspector called John Pryor of Pryor Oil Company. Mr. Pryor said that he had removed the crude oil from this containment area and planned to remove the oily straw surrounding the Tank Battery.

**PEOPLE'S  
EXHIBIT**

12

PLB 02-177



TEMA#971314  
relation Co/Wanner  
Pryor Oil Company  
Crude Oil Spill  
Prepared by:  
C. Kelley  
Photographs for:  
11/11/60



# INSPECTION PHOTOS

DATE: 9-11-1997	SITE #:	CO.: MARION/WAMAC
TIME: 3:30	SITE NAME: PRYOR OIL COMPANY	

PHOTOGRAPH TAKEN

BY: CLK

*Cheryl Kelley*

COMMENTS: Pictures taken  
toward:

IEMA # 971314

-----  
-----  
-----  
-----  
-----

ROLL#: OCS 202

PHOTO#: 1



DATE: 9-11-1997

TIME: 3:30

PHOTOGRAPH TAKEN

BY: CLK

*Cheryl Kelley*

COMMENTS: Pictures taken  
toward:

IEMA # 971314

-----  
-----  
-----  
-----  
-----

ROLL#: OCS 202

PHOTO#: 2

