BEFORE THE POLLUTION CONTROL BOARD OF THE STATE OF ILLINOIS

EVELYN M. PAGE TRUST, WAYNE A.)	
PAGE, AND KENNARD PAGE,)	
SUCESSOR TRUSTEES,	Ĵ	
Petitioners,)	
)	
V.)	PCB 2019-053
)	(LUST Appeal)
ILLINOIS ENVIRONMENTAL)	
PROTECTION AGENCY,)	
Respondent.	Ĵ	

NOTICE

Don Brown, Clerk Illinois Pollution Control Board James R. Thompson Center 100 West Randolph, Suite 11-500 Chicago, IL 60601 don.brown@illinois.gov Carol Webb, Hearing Officer Illinois Pollution Control Board 1021 North Grand Avenue East P.O. Box 19274 Springfield, IL 62794-9274 <u>carol.webb@illinois.gov</u>

Robert L. Potts, Esq. WHITNEY & POTTS, 118 West Main Street P.O Box 368 Elmwood, IL 61529-0368 cori@whitneyandpotts.com

PLEASE TAKE NOTICE that I have today filed with the office of the Clerk of the Pollution Control Board an **APPEARANCE**, the **ADMINISTRATIVE RECORD** and a **CERTIFICATE OF RECORD ON APPEAL**, copies of which are herewith served upon you.

Respectfully submitted,

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY, Respondent

Melanier

Melanie A. Jarvis Assistant Counsel Division of Legal Counsel 1021 North Grand Avenue, East P.O. Box 19276 Springfield, Illinois 62794-9276 217/782-5544 866/273-5488 (TDD) Dated: November 6, 2020

BEFORE THE POLLUTION CONTROL BOARD OF THE STATE OF ILLINOIS

EVELYN M. PAGE TRUST, WAYNE A.)	
PAGE, AND KENNARD PAGE,)	
SUCESSOR TRUSTEES,)	
Petitioners,)	
)	
v.)	PCB 2019-053
)	(LUST Appeal)
ILLINOIS ENVIRONMENTAL)	
PROTECTION AGENCY,)	
Respondent.)	

APPEARANCE

The undersigned, as one of its attorneys, hereby enters her Appearance on behalf of

the Respondent, the Illinois Environmental Protection Agency.

Respectfully submitted,

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY, Respondent

Melanie

Melanie A. Jarvis Assistant Counsel Special Assistant Attorney General Division of Legal Counsel 1021 North Grand Avenue, East P.O. Box 19276 Springfield, Illinois 62794-9276 217/782-5544 866/273-5488 (TDD) melanie.jarvis@illinois.gov Dated: November 6, 2020

BEFORE THE ILLINOIS POLLUTION CONTROL BOARD

)
)
)) PCB 2019-053) (LUST Appeal)
j , n ,
)
)

CERTIFICATE OF RECORD ON APPEAL

Pursuant to 35 Ill. Adm. Code 105.116(b) and 105.410, the following constitutes an index of documents comprising the record:

PAGES	DOCUMENT(S)	DATE
R0001-R0002	Hazardous Materials Incident Report	February 7, 2017
R0003	IEPA Request to Comply	February 10, 2017
R0004-R0024	20-Day Certification	March 28, 2017
R0025-R0080	45-Day Report	April 13, 2017
R0081-R0089	Technical Review Notes	August 8, 2017
R0090-R0103	NFR letter	August 9, 2017
R0104-R0110	Recorded NFR letter	August 14, 2017
R0111-R0133	Claim Review Notes	June 29, 2018
R0134-R0166	Reimbursement Claim	March 1, 2018
R0167-R0173	IEPA Determination Letter	June 25, 2018

I, Brian Bauer, certify on information and belief that the entire record of the Respondent's decision, as defined in 35 Ill. Adm. Code 105.410(b), is hereby enclosed.

e By:

Brian Bauer, Project Manager Leaking Underground Storage Tank Section Illinois Environmental Protection Agency

Date: 1/00 4, 2020

This filing submitted on recycled paper.

CERTIFICATE OF SERVICE

I, the undersigned attorney at law, hereby certify that on November 6, 2020, I

served true and correct copies of an APPEARANCE, the ADMINISTRATIVE RECORD and a

CERTIFICATE OF RECORD ON APPEAL, via the Board's COOL system and email, upon the

following named persons:

Don Brown, Clerk Illinois Pollution Control Board James R. Thompson Center 100 West Randolph, Suite 11-500 Chicago, IL 60601 <u>don.brown@illinois.gov</u> Carol Webb, Hearing Officer Illinois Pollution Control Board 1021 North Grand Avenue East P.O. Box 19274 Springfield, IL 62794-9274 carol.webb@illinois.gov

Robert L. Potts, Esq. WHITNEY & POTTS, 118 West Main Street P.O Box 368 Elmwood, IL 61529-0368 cori@whitneyandpotts.com

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY, Respondent

Melanies

Melanie A. Jarvis Assistant Counsel Division of Legal Counsel 1021 North Grand Avenue, East P.O. Box 19276 Springfield, Illinois 62794-9276 217/782-5544 866/273-5488 (TDD) melanie.jarvis@illinois.gov



			nterials Incident port 1438185	5006 - Peorla
Incident #:	H-2017-0100		Pase Evel	Yn M. trust
Entered By:	Kattner, Paul (IEMA)	on		
Data Input Status:	Open		1 1/ 1	
Leaking Underground Storage Tank (LUST):	Yes		Leaking US	Tech File
Caller:	Allan Green			
Call Back #:	309/925-5551			
Caller Represents:	Midwest Environmental			
Hazmat Incident Type:	Leak or spill	-		
	INCID	ENT	LOCATION	
Incident Location:	23907 West Farmington R	td		· .
County: Peoria	Fulton 6156	4	City:	Trivoli
Primary IEMA Region:	6	4	Secondary IEMA Region:	Not Applicable
Full Address:	23907 West Farmington R	ld, Tr	rivoli, IL	·
Latitude:	40.698094		Longitude:	-89.929451
Milepost:	N/A		Sec:	N/A
Twp.:	N/A		Range:	N/A
Area Involved:	Fixed Facility			• · · ·
Media or medium into which the release occurred:	Ground			
· · · · · · · · · · · ·	WEATH	ER I	NFORMATION	

WEATHER INFORMATION				
Temp (deg F):	54 Degrees	Wind Dir/Speed m.p.h: W 10 MPH		

MATERIALS INVOLVED				
Material Name:	Diesel Fuel	Material Type:	Liquid	
CHRIS Code:	Unknown	CAS #:	Unknown	
UN/NA #:	Unknown			
Is this a 302(a) Extremely Hazardous Substance?	Unknown			
Is this a RCRA Hazardous Waste?	Unknown		-	
Is this a RCRA regulated facility?	Unknown			
Container Type:	Under ground storage tank	Container Size:	1 X 10,000 Gallons (Diesel)	
Amount Released:	Unknown	Rate of Release/min:	Unknown	
Duration of Release:	Unknown			
Cause of Release:	Piping Leak	<u> </u>	EPA-DEMISION OF RECORDS MANAGEME	
Estimated Spill Extent:	Unknown	Spill Extent Units:		
			FEB 1 7 2017	

Date/Time Occured:	(Date/Time Unknown)	(Date/Time Unknown)		
Date/Time Discovered:	2017-02-06 10:00			
Number Injured:	0	Where Taken:	N/A	
Number Killed:	0	# Evacuated:	0	
On Scene Contact:	Allan Green	On Scene Phone #:	309/925-5551	
Proper safety precautions to None	ake as a result of the release, inclu	iding evacuation:		
Assistance needed from State None	e Agencies:			
Containment/Cleanup action: Tank will be removed and so		mental (Contractor) will coordinate	cleanup and remediation.	
Responsible Party:	Evelyn M./ Page Trust			
Contact Person:	Wayne Page		<u> </u>	
Callback Phone Number:				
Facility Manager:	Wayne Page			

Emergency Units Contacted	Contacted	On Scene	Agencies Contacted
ESDA			None
Fire		· ·	None
Police			None
Sheriff			None
Other			None

AGENCIES OR PERSONS NOTIFIED					
Agency Date/Time Name of Person Notification Action					
IEPA, OSFM, NRTP, & IEMA Region #6	2017-02-07 14:50	E-mailed	Report.Sent		

.

.

Narrative:

Follow-Up Information:

Attachments:

ILLENONS ENVIRONMENTALE PROTOCTIVO AD AGENCY



 1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397

 BRUCE RAUNER, GOVERNOR

 ALEC MESSINA, ACTING DIRECTOR

217/524-3300

February 10, 2017

Page, Evelyn M Trust Attn: Wayne Page 24 Rutledge Avenue Bartonville, IL 61607

> IEPA-DIVISION OF RECORDS MANAGEMENT RELEASABLE

Re: LPC #1438185006 -- Peoria County Trivoli/Page, Evelyn M Trust 23907 West Farmington Road Leaking UST Incident No. 20170100 Leaking UST Technical File

FEB 1:7 2017

REVIEWER: JKS

Dear UST Owner or Operator:

The Illinois Environmental Protection Agency (Illinois EPA) received notification from the Illinois Emergency Management Agency that a release from an underground storage tank system(s) has occurred at the above-referenced site. As a result of this release, the owner or operator of the underground storage tank(s) is required to comply with the Leaking Underground Storage Tank (Leaking UST) Program requirements, including the submittal of applicable documentation on forms prescribed and provided by the Illinois EPA.

To obtain copies of the forms, as well as additional information regarding the Illinois EPA's Leaking UST Program, please visit our Web page at <u>http://www.epa.state.il.us/land/lust/index.html</u>.

- 1. The direct link to the technical forms page is http://www.epa.state.il.us/land/lust/forms/technical-forms/index.html.
- 2. If you intend to seek reimbursement from the Illinois Underground Storage Tank Fund for costs incurred, the direct link to the budget and reimbursement forms page is: <u>http://www.epa.state.il.us/land/lust/forms/budget-forms/index.html</u>.

If you do not have access to the Internet and/or have questions about the Leaking UST Program requirements, please contact the Leaking UST Program project manager on call at 217/524-3300. Sincerely,

Gregory W. Dunn, Manager Leaking Underground Storage Tank Section Division of Remediation Management Bureau of Land

GWD: JW\

c: BOL File

4302 N. Main St., Rockford, IL 61103 (815) 987-7760 595 S. State, Elgin, IL 60123 (847) 608-3131 2125 S. First St., Champalgn, IL 61820 (217) 278-5800 2009 Mail St., Callinsville, IL 62234 (618) 346-5120 9511 Harrison St., Des Plaines, IL 60016 (847) 294-4000 412 SW Washington St., Suite D, Peorla, IL 61602 (309) 671-3022 2309 W. Main St., Suite 116, Marion, IL 62959 (618) 993-7200 100 W. Randolph, Suite 10-300, Chicago, IL 66601

The Agency is authorized to require this information under Section 4 and Title XVI of the Environmental Protection Act (415 may result in a civil penalty of not to exceed \$50,000 00 for the violation and an additional civil penalty of not to exceed \$10 (415 LCS 5/42). Any person who knowingly makes a false material statement or representation in any label, manifest, remaintained or used for the purpose of compliance with Title XVI commits a Class 4 felony. Any second or subsequent offen: 5/5/17). This form has been approved by the Forms Management Center.

Illinois Environmental Protection Agency Leaking Underground Storage Tank Program 20-Day Certification

1438185006 – Peoria County Page, Evelyn M Trust Incident # 20170100 Leaking UST Technical File

IEPA-DIVISION OF RECORDS MANAGEMENT RELEASABLE

APR 06 2017

REVIEWER: JKS

A. Site Identification

IEMA Incident # (6- or 8-digit): 201701	00 IEPA LPC# (10-digit): _	1438185006
Site Name: <u>Evelyn M Page Trust</u>	· · · · · · · · · · · · · · · · · · ·	
Site Address (Not a P.O. Box): 23907	West Farmington Road	
City: <u>Trivoli</u>	County: Peoria	_ ZIP Code: 61569
Leaking UST Technical File		

B. Initial Abatement

- 1. I am/we are the owner and/or operator of the underground storage tank system(s) from which a release was reported under the IEMA incident correctly identified above;
- 2. As much of the regulated substance as necessary to prevent further release into the environment has been removed;
- Any aboveground releases or exposed below ground releases have been visually inspected;
- 4. Further migration of the released substance into surrounding soils and groundwater has been prevented;
- 5. Monitoring and mitigation of any fire and safety hazards posed by vapors or free product that has migrated from the UST excavation zone and entered subsurface structures (such as sewers or basements) will continue;
- 6. Hazards posed by contaminated soils that are excavated or exposed as a result of release confirmation, site investigation, abatement, or corrective action activities have been remedied;
- 7. If the remedies included treatment or disposal of soils, the owner or operator has complied with 35 III. Adm. Code 722, 724, 725, and 807 through 815;
- 8. Measurement for the presence of a release has been conducted where contamination was most likely to be present at the UST site. In selecting sample types, sample locations and measurement methods, the nature of the stored substance, type of backfill, depth to groundwater, and other factors as appropriate for identifying the presence and source of the release have been considered; and
- 9. An investigation to determine the possible presence of free product has been conducted, and, if applicable, free product removal is being conducted in accordance with 35 III. Adm. Code 731.164, 732.203, or 734.215.

IEPA/BOL

MAR 28 2017

C. Signatures

All plans, budgets, and reports must be signed by the owner or operator and list the owner's or operator's full name, address, and telephone number.

UST Owner or Operator	Consultant
Name: Evelyn M Page Trust	Company: M.E.C.R.S., Inc.
Contact: Mr. Wayne Page	Contact: Mr. Allan Green
Address: 24 Rutledge Avenue	Address: 22200 Illinois Route 9, P.O. Box 614
City: Bartonville	City: Tremont
State: Illinois	State: Illinois
ZIP Code: 61607	ZIP Code:
Phone: (309) 573-2367	Phone: (309) 925-5551
Signature: Wayner Ture	Signature:
Date: 3-1-2017	Date: 3-1-2017

I certify under penalty of law that all activities that are the subject of this report were conducted under my supervision or were conducted under the supervision of another Licensed Professional Engineer or Licensed Professional Geologist and reviewed by me; that this report and all attachments were prepared under my supervision; that, to the best of my knowledge and belief, the work described in this report has been completed in accordance with the Environmental Protection Act [415 ILCS 5], 35 III. Adm. Code 731, 732, or 734, and generally accepted standards and practices of my profession; and that the information presented is accurate and complete. I am aware there are significant penalties for submitting false statements or representations to the Illinois EPA, including but not limited to fines, imprisonment, or both as provided in Sections 44 and 57.17 of the Environmental Protection Act [415 ILCS 5/44 and 57.17].

Licensed Professional Engineer or Geologist

Name: Penny Silzer
Company: M.E.C.R.S., Inc.
Address: 22200 Illinois Rt. 9, P.O. Box 614
City: Tremont
State:
ZIP Code: 61568
Phone: (309) 925-5551
III. Registration No.: <u>196-000256</u>
License ExpirationDate: 03/31/17
Signature: Jehn Artic
Date: 3-1-2017



L.P.E. or L.P.G. Seal



IEPA/BOL

20-Day Certification 2 of 2



Office of the Illinois State Fire Marshal

4/7/2017

Evelyn Page Trust 24 Rutledge Avenue Bartonville, IL 61607

In Re: Facility No. 3000721 IEMA Incident No. 20170100 Evelyn Page Trust 23907 W. Farmington Rd. Farmington, Fulton, IL 61531

Dear Applicant:

The Reimbursement Eligibility and Deductible Application received on April 06, 2017 for the above referenced occurrence has been reviewed. The following determinations have been made based upon this review.

It has been determined that you are eligible to seek payment of costs in excess of \$5,000. The costs must be in response to the occurrence referenced above and associated with the following tanks:

Eligible Tanks

Tank 2 10000 gallon Diesel Fuel

You must contact the Illinois Environmental Protection Agency to receive a packet of Agency billing forms for submitting your request for payment.

An owner or operator is eligible to access the Underground Storage Tank Fund if the eligibility requirements are satisfied:

- 1. Neither the owner nor the operator is the United States Government,
- 2. The tank does not contain fuel which is exempt from the Motor Fuel Tax Law,
- 3. The costs were incurred as a result of a confirmed release of any of the following substances:

"Fuel", as defined in Section 1.19 of the Motor Fuel Tax Law

Aviation fuel

Heating oil

Kerosene

Used oil, which has been refined from crude oil used in a motor vehicle, as defined in Section 1.3 of the Motor Fuel Tax Law.

- 4. The owner or operator registered the tank and paid all fees in accordance with the statutory and regulatory requirements of the Gasoline Storage Act.
- 5. The owner or operator notified the Illinois Emergency Management Agency of a confirmed release, the costs were incurred after the notification and the costs were a result of a release of a substance listed in this Section. Costs of corrective action or indemnification incurred before providing that notification shall not be eligible for payment.
- 6. The costs have not already been paid to the owner or operator under a private insurance policy, other written agreement, or court order.
- 7. The costs were associated with "corrective action".

2

This constitutes the final decision as it relates to your eligibility and the set deductible. We reserve the right to change the deductible determination should additional information that would change the determination become available. An underground storage tank owner or operator may appeal the decision to the Illinois Pollution Control Board (Board), pursuant to Section 57.9 (c) (2). An owner or operator who seeks to appeal the decision shall file a petition for a hearing before the Board within 35 days of the date of issuance of the final decision, (35 Illinois Administrative Code 105.504(b)).

For information regarding the filing of an appeal, please contact:

Clerk Illinois Pollution Control Board State of Illinois Center 100 West Randolph, Suite 11-500 Chicago, Illinois 60601 (312) 814-3620

The following tanks are also listed for this site:

Tank 1 10000 gallon Gasoline

Your application indicates that there has not been a release from these tanks under this incident number. You may be eligible to seek payment of corrective action costs associated with these tanks if it is determined that there has been a release from one or more of these tanks. Once it is determined that there has been a release from one or more of these tanks you may submit a separate application for an eligibility determination to seek corrective action costs associated with this/these tanks.

If you have any questions, please contact our Office at (217) 785-1020.

Sincerely,

Deanne Lock Division of Petroleum and Chemical Safety

Electronic Filing: Received, Clerk's Office 11/5/2020 Eligibility and Deductible Application - IEMA:20170100 - Facility #: 3000721

Applicant Information

٠

Applicant Info		Contact Info	
Applicant Name	Evelyn Page Trust	Contact Name	Allan Green
C/0		Company	Midwest Environmental
Address	24 Rutledge Avenue	Phone Number	(309) 925-5551
	Bartonville, IL 61607	Email	mdwstenv@frontier.com
Email Address	vet6262@comcast.net		
	Current Property Owner Current Tank Owner		
Owner - U0038	682	Facility - 30007	21
Owner Name	Evelyn Page Trust	Facility Name	Evelyn Page Trust
Address	24 Rutledge Ave. Bartonville, IL 61607	Address	23907 W. Farmington Rd. Farmington, IL 61531
Contact Person	Wayne Page	County	Fulton
	(309) 573-2367	Contact Person	Wayne Page
Phone Number			

Incident Information

IEMA Number: 20170100 Type of release: Underground Storage Tank Leak How release was discovered: Subsurface Work/Repair Is the UST owner/operator the US government: No Is the UST owner/operator a rail carrier: No Is the UST owner/operator located at an airport: No

Tanks

1040104-0

Associated with Release

Tank No.	Current Product	Product at time of release	Size (gal)	Installed	First Notified	Last Used	Removed	Abandoned Date
2	Diesel Fuel	Diesel Fuel	2 2	, , ,	12/9/1992			


All tanks for Evelyn Page Trust on file


Tank No.	Current Product	Size (gal)	Installed	First Notified	Last Used	Removed	Abandoned Date
1	Gasoline	10000		1/31/1986	8/13/1992	8/14/1991	
2	Diesel Fuel	10000	8/14/1991		5/22/2012	3	

Attachments

Name	File Name(s)	Additional Information
Site Assessment Documents	<u>Evelyn Page Trust lab results 1 of 2.pdf</u> <u>Evelyn Page Trust lab results 2 of 2.pdf</u>	
IEMA Report	Evelyn Page Trust IEMA report.pdf	
Site Plan	Evelyn Page Trust site map.pdf	
Authorization to submit	Evelyn Page trust OSFM authorization.pdf	nd με το του τη ματηρογική του ματορογική του το του το πολογοριατική το ματορογιατική το του το του το το του Το πολογοριατική το

:





March 30, 2017

Allan Green Midwest Environmental Tremont Box 614 Tremont, IL 61568

Dear Allan Green:

Please find enclosed the analytical results for the sample(s) the laboratory received on 3/17/17 1:10 pm and logged in under work order 7032606. All testing is performed according to our current TNI certifications unless otherwise noted. This report cannot be reproduced, except in full, without the written permission of PDC Laboratories, Inc.

If you have any questions regarding your report, please contact your project manager. Quality and timely data is of the utmost importance to us.

PDC Laboratories, Inc. appreciates the opportunity to provide you with analytical expertise. We are always trying to improve our customer service and we welcome you to contact the Vice President, John LaPayne with any feedback you have about your experience with our laboratory.

Sincerely,

Kurt Stepping Senior Project Manager (309) 692-9688 x1719 kstepping@pdclab.com







PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

ï

٠

۲

×

Sample: 7032606-01 Name: NW1 Matrix: Soil - Grab				Sampled: 03/10/17 00:00 Received: 03/17/17 13:10			
arameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
eneral Chemistry - PIA							
olids - total solids (TS)	79	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
olynuclear Aromatic Hydrocarbons - PIA							
cenaphthene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
cenaphthylene	< 85	ug/kg dry		03/23/17 08;19	03/28/17 17:32	ELS	SW 8310
nthracene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
enzo(a)anthracene	12	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
enzo(a)pyrene	13	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
enzo(b)fluoranthene	17 in 17	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
enzo(g,h,i)perylene	11	ug/kg dry		03/23/17 08:19	03/28/17 17:32	EL\$	SW 8310
enzo(k)fluoranthene	6.9	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
hrysene	14	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
ibenzo(a,h)anthracene	< 8.5	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
luoranthene	20	ug/kg đry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
luorene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
deno(1,2,3-cd)pyrene	12	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
aphthalene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17;32	ELS	SW 8310
henanthrene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
yrene	22	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310
<u>olatile Organics - PIA</u>							
enzene	< 28	ug/kg dry		03/22/17 07:23	03/22/17 11:24	JJI	SW 8260B
thylbenzene	< 28	ug/kg dry		03/22/17 07:23	03/22/17 11:24	JJI	SW 8260B
bluene	< 28	ug/kg dry		03/22/17 07:23	03/22/17 11:24	الال	SW 8260B
ylenes- Total	< 83	ug/kg dry		03/22/17 07:23	03/22/17 11:24	JJI	SW 8260B



1

.

PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-02 Name: SW1 Matrix: Soil - Grab						03/10/17 0 03/17/17 1	
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
General Chemistry - PIA							
Solids - total solids (TS)	76	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
olynuclear Aromatic Hydrocarbons - PIA							
Acenaphthene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
Acenaphthylene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
nihracene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
Benzo(a)anthracene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
enzo(a)pyrene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
enzo(b)fluoranthene	< 8,8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
enzo(g,h,i)perylene	< 8.8	üg/kg dry		03/23/17 08:19	03/28/17 17:58	EL\$	SW 8310
enzo(k)fluoranthene	< 4.5	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
hrysene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
ibenzo(a,h)anthracene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
luoranthene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
luorene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
ndeno(1,2,3-cd)pyrene	< 8,8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
laphthalene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
Phenanthrene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
yrene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310
<u> Internet de la constante de </u>							
Benzene	< 31	ug/kg dry		03/22/17 07:23	03/22/17 11:51	JJI	SW 8260B
thylbenzene	< 31	ug/kg dry		03/22/17 07:23	03/22/17 11:51	ILL	SW 8260B
foluene	< 31	ug/kg dry		03/22/17 07:23	03/22/17 11:51	JJI	SW 8260B
ylenes- Total	< 94	ug/kg dry		03/22/17 07:23	03/22/17 11:51	ILL	SW 8260B



PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

٠

Sample: 7032606-03 Name: EW1 Matrix: Soil - Grab						03/10/17 (03/17/17 /	
arameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
eneral Chemistry - PIA							
olids - total solids (TS)	80	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
olynuclear Aromatic Hydrocarbons - PIA							
cenaphthene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
cenaphthylene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
nthracene	< 84	ug/kg đry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
enzo(a)anthracene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
enzo(a)pyrene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
enzo(b)fluoranthene	< 8,4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
enzo(g,h,i)perylene	< 8,4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
enzo(k)fluoranthene	< 4.2	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
hrysene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
ibenzo(a,h)anthracene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
luoranthene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
uorene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
deno(1,2,3-cd)pyrene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
aphthalene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
henanthrene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
vrene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310
platile Organics - PIA							
enzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 17:33	JJI	SW 8260B
hylbenzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 17:33	JJI	SW 8260B
luene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 17:33	JJI	SW 8260B
ylenes- Total	< 80	ug/kg dry		03/23/17 13:05	03/23/17 17:33	ILL	SW 8260B



.

.

.

PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-04 Name: WW1 Matrix: Soil - Grab				Sampled: 03/10/17 00:00 Received: 03/17/17 13:10			
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
General Chemistry - PIA							
Solids - total solids (TS)	80	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
Polynuclear Aromatic Hydrocarbons - PIA							
Acenaphthene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Acenaphthylene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Anthracene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Benzo(a)anthracene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Benzo(a)pyrene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Benzo(b)fluoranthene	< 8,3	ug/kg dry		03/23/17 08;19	03/28/17 18:49	ELS	SW 8310
Benzo(g,h,i)perylene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Benzo(k)fluoranthene	< 4.2	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Chrysene	< 8,3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Dibenzo(a,h)anthracene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ËLS	SW 8310
Fluoranthene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Fluorene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Indeno(1,2,3-cd)pyrene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Naphthalene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Phenanthrene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Pyrene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310
Volatile Organics - PIA							
Benzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 18;00	JJI	SW 8260B
Ethylbenzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 18:00	JJI	SW 8260B
Toluene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 18:00	ILL	SW 8260B
Xylenes- Total	< 82	ug/kg dry		03/23/17 13:05	03/23/17 18:00	ILL	SW 8260B



PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

۰,

.

•

٠

Sample: 7032606-05 Name: SF1 Matrix: Soil - Grab					Sampled: 03/10/17 0 Received: 03/17/17 1			
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method	
General Chemistry - PIA								
Solids - total solids (TS)	85	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*	
Polynuclear Aromatic Hydrocarbons - PIA								
Acenaphthene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Acenaphthylene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Anthracene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Benzo(a)anthracene	< 7,9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Benzo(a)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Benzo(b)fluoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Benzo(g,h,i)perylene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Benzo(k)fluoranthene	< 4.0	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Chrysene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Dibenzo(a,h)anthracene	< 7,9	úg/kg đry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Fluoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Fluorene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Indeno(1,2,3-cd)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Naphthalene	< 79	ug/kg dry		03/23/17 08;19	03/28/17 19:15	ELS	SW 8310	
Phenanthrene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310	
Volatile Organics - PIA								
Benzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 18:28	าม	SW 8260B	
Ethylbenzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 18:28	JJI	SW 8260B	
Toluene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 18:28	JJI	SW 8260B	
Xylenes- Total	< 97	ug/kg dry		03/23/17 13:05	03/23/17 18:28	ICL	SW 8260B	



,

.

ς.

PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-08 Name: NF1 Matrix: Soil - Grab						03/10/17 (03/17/17 1	
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
<u> General Chemistry - PIA</u>							
Solids - total solids (TS)	84	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
Polynuclear Aromatic Hydrocarbons - PIA							
Acenaphthene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Acenaphthylene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Inthracene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Benzo(a)anthracene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
enzo(a)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
enzo(b)fluoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
enzo(g,h,i)perylene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
enzo(k)fluoranthene	< 4.0	ug/kg đry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
hrysene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
ibenzo(a,h)anthracene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
luoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
uorene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
ideno(1,2,3-cd)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELŜ	SW 8310
aphthalene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
henanthrene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
yrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
olatile Organics - PIA							
Benzene	< 26	ug/kg dry		03/23/17 13:05	03/23/17 18:55	ILL	SW 8260B
thylbenzene	< 28	ug/kg dry		03/23/17 13:05	03/23/17 18:55	JJI	SW 8260B
oluene	< 26	ug/kg dry		03/23/17 13:05	03/23/17 18:55	JJI	SW 8260B
ylenes- Total	< 78	ug/kg dry		03/23/17 13:05	03/23/17 18:55	JJI	SW 8260B



PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

.

ø

Sample: 7032606-07 Name: BF1 Matrix: Soil - Grab					-	03/10/17 (03/17/17 ⁻	
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
General Chemistry - PIA							
Solids - total solids (TS)	77	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
Polynuclear Aromatic Hydrocarbons - PIA							
Acenaphthene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Acenaphthylene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Anthracene	< 87	ug/kg đry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Benzo(a)anthracene	< 8,7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Benzo(a)pyrene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Benzo(b)fluoranthene	< 8,7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Benzo(g,h,i)perylene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Benzo(k)fluoranthene	< 4.4	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Chrysene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Dibenzo(a,h)anthracene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Fluoranthene	< 8.7	ug/kg dry		03/23/17 08;19	03/28/17 20:07	ELS	SW 8310
Fluorene	< 87	ug/kg đry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Indeno(1,2,3-cd)pyrene	< 8,7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Naphthalene	1200	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Phenanthrene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Pyrene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310
Volatile Organics - PIA							
Benzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 19:22	JJI	SW 8260B
Ethylbenzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 19:22	JJI	SW 8260B
Toluene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 19:22	JJI	SW 8260B
Xylenes- Total	< 97	ug/kg dry		03/23/17 13:05	03/23/17 19:22	ILL	SW 8260B



PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

NOTES

Specific method revisions used for analysis are available upon request.

Certifications

PIA - Peoria, IL

TNI Accreditation for Drinking Water, Wastewater, Hazardous and Solid Wastes Fields of Testing through IL EPA Lab No. 100230 Illinois Department of Public Health Bacteriological Analysis in Drinking Water Approved Laboratory Registry No. 17553 Missouri Department of Natural Resources Certificate of Approval for Microbiological Laboratory Service No. 870 Drinking Water Certifications: Iowa (240); Kansas (E-10338); Missouri (870) Wastewater Certifications: Arkansas (88-0677); Iowa (240); Kansas (E-10338) Hazardous/Solid Waste Certifications: Arkansas (88-0677); Iowa (240); Kansas (E-10338)

SPMO - Springfield, MO USEPA DMR-QA Program

STL - St. Louis, MO

TNI Accreditation for Wastewater, Hazardous and Solid Wastes Fields of Testing through KS Lab No. E-10389 Illinois Department of Public Health Bacteriological Analysis in Drinking Water Approved Laboratory Registry No. 171050 Drinking Water Certifications: Missouri (1050) Missouri Department of Natural Resources

* Not a TNI accredited analyte

Qualifiers

H Test performed after the expiration of the appropriate regulatory/advisory maximum allowable hold time.



Certified by: Kurt Stepping, Senior Project Manager

Page 9 of 10

E	lectronic Fil	ing: Rece	ived, C	lerk's	Offic	ce î	11/	5/202	20			
PDC Laboratories, Inc.	C	HAIN OF C	USTO	Y REO	CORI	D					Phone: (800) 75:	2-6651
2231 W. Altorfer Dr	Sta	te where sam	ples were	e collect	ed						Fax: (309) 69:	
Peoria, IL 61615		IIGHLIGHTED AREAS <u>ML</u>	-			13.175					www.pdcla	p.con
CLIENT	P.O. NUMBER	PROJECT	NAME	DATE SH				LYSIS RE	QUESTE	Ď.	WORK ORDER	
Uniduest Gru.]	Firsts	hadent	3 r	רו ר	3) _			-	4 (FOR LAB USE ONLY	
ADDREŠS	PHONE	mowstma	5	MEANS S	HIPPED						LOGIN #:	0-1
CITY STATE ZIP	3099255551 SAMPLER (PLEASE PRIN	Frontier	· com	MATRIX TYP	DEC.						LOGGED BY:	Spi
Tremovit II 61505				WW-WASTE	WATER					1	PROJECT:	
CONTACT PERSON	SAMPLER'S SIGNATUR	ir een		GW - GROUN WWSL - SLUD NAS - SOLID	d water		H				PROJ MGR:	
Allon Greening	Dee	Huen	an an An an Alban an An An	UCHT - LEACH	ATE	1	2	l.			ł	
2 SAMPLE DESCRIPTION AS YOU WANT TO REPORT	Actor DATE TO T		LE TYPE COMP	MATRIX	BOTTLE COUNT	A	P				REMARKS	
NWI	3/10/17	K_			5	~	7		1			
SWI	3/10/17	~			5	1	~					
EW1	3/10/17	x			5		Ĭ					
<u>ww1</u>	3/10/17	<u> </u>			5		1				······································	
SFI	3/10/17	<u> </u>	1		5		-					
ANEL	3/10/17		ļ		5_	~	-					
<u> </u>	36/17	×			for	¥	1000	·	┼─┼			
					•;				+			······
۵۰۰۰۰۰ <u>المتعارض من المتعارض ا</u>									┼─┼			
5 TURNAROUND TIME REQUESTED (RUSH TAT IS SUBJECT TO APPROVAL AND SURCHARGE			LTS NEEDED	6 The sail you be this are	mple lempe fore proced ea, you allo	valure w ding will w the fai	All be mi h enelys b to prod	easured up is if the sar weed with a	on receipt nple temp nalylical te	al the lab, erature is sting rega	By initialing this area, you request that outside of the range of 0.1-5.0°C. By no roless of the semple temperature.	we notity (initiating
		IVED BY SIGNATURE	()	· 1-34				8		COMME	NTS (FOR LAB USE ONLY)	 /
all-minen		UNED BY SIGNATURE	(bit		TIME ノン・シ DATE	2		SAMPLE T	EMPERA	TURE UPO	IN RECEIPT	°c
	IME		· :		TIME			CHILL PRO			OR TO RECEIPT	OR N FOR N
	ATE -17-17 RECE JME: 10	IVED BY (SKONATURE				71/J.	2	PROPER B BOTTLES I SAMPLES	OTTLES F FILLED W RECEIVED	RECEIVED I ITH ADEQ S WITHIN	IN GOOD CONDITION UATE VOLUME HOLD TIME(S) (RAMETERS)	OR N OR N OR N OR N
Maz	3:19	- UMP	V	<u>, i</u> l.	13	D		DATE AND	TIME TA	KEN FROM	M SAMPLE BOTTLE	
		V										

Page 10 of 10



Hazardous Materials Incident EMAI Report 1438185006-Peorla Incident #: H-2017-0100 Pase, Evelyn M. trust Entered By: Kattner, Paul (IEMA) on 2017-02-07 14:49:04 Leaking UST Tech File

	•
Data Input Status: Op	en
Leaking Underground Storage Tank (LUST): Yes	5

Caller:	Allan Green	Illan Green					
Call Back #:	309/925-5551	09/925-5551					
Caller Represents:	Midwest Environmental	Aidwest Environmental					
Hazmat Incident Type:	Leak or spill	· · · · · · · · · · · · · · · · · · ·					
	INCIDENT	LOCATION					
Incident Location:	23907 West Farmington Rd	·· ··· ··· ····	• <u>.</u>				
County: Peoria	Fulton 6/569 City: Trivoli						
Primary IEMA Region:	6 Secondary IEMA Region: Not Applicable						
Full Address:	23907 West Farmington Rd, Tri	voli, IL					
Latitude:	40.698094	Longitude:	-89.929451	· · · · · · · · · · · · · · · · · · ·			
Milepost:	N/A	N/A Sec: N/A					
Twp.:	N/A Range: N/A						
Area Involved:	Fixed Facility						
Media or medium into which the release occurred:	Ground						

·	WEATHER IN	FORMATION	
Temp (deg F):	54 Degrees	Wind Dir/Speed m.p.h:	W 10 MPH

	MATERIALS IN	VOLVED				
Material Name:	Diesel Fuel	Material Type:	Liquid			
CHRIS Code:	Unknown CAS #: Unknown					
UN/NA #:	Unknown					
Is this a 302(a) Extremely Hazardous Substance?	Unknown					
Is this a RCRA Hazardous Waste?	Unknown		· · · · · · · · · · · · · · · · · · ·			
Is this a RCRA regulated facility?	Unknown					
Container Type:	Under ground storage tank	Container Size:	1 X 10,000 Gallons (Diesel)			
Amount Released:	Unknown	Rate of Release/min:	Unknown			
Duration of Release:	Unknown		<u>. </u>			
Cause of Release:	Piping Leak	***************************************				
Estimated Spill Extent:	Unknown	Spill Extent Units:	RELEASABLE			
			FEB 1 7 2017			

FEB 17 2017

ł

REVIEWER: JKS

Date/Time Occured:	(Date/Time Unknown)
Date/Time Discovered:	2017-02-06 10:00

Number Injured:	0	Where Taken:	N/A
Number Killed:	0	# Evacuated:	0
On Scene Contact:	Allan Green	On Scene Phone #:	309/925-5551
Proper safety precautions None	to take as a result of the release, inc	luding evacuation:	
Assistance needed from S None	itate Agencies:		νη η του παραγιατική ματοποιού το
Containment/Cleanup act Tank will be removed and		onmental (Contractor) will coordinate	cleanup and remediation.

Responsible Party:	Evelyn M./ Page Trust
Contact Person:	Wayne Page
Callback Phone Number:	
Facility Manager:	Wayne Page
Facility Manager Phone #:	
Street Address:	
City:	State: Zip Code:

Emergency Units Contacted	Contacted	On Scene	Agencies Contacted
ESDA			None
Fire		•	None
Police			None
Sheriff			None
Other	1		None

AGENCIES OR PERSONS NOTIFIED					
Agency	Date/Time	Name of Person	Notification Action		
IEPA, OSFM, NRTP, & IEMA Region #6	2017-02-07 14:50	E-mailed	Report.Sent		

-

.

Narrative:

ŧ٢

.

Follow-Up Information:

Attachments:

Bruce Rauner, Governor

Matt Perez, State Fire Marshal



Office of the State Fire Marshal

AUTHORIZATION TO SUBMIT ELIGIBILITY AND DEDUCTIBLE APPLICATION

The undersigned owner or operator for the underground storage tanks for facility number 3000721 23917 W. Farming ton Rd. ("this facility") certifies that: located at

(1) <u>MECK5</u>, located at <u>2230 IL R4.9 Tremant</u>, IL 6146 8 (name of representative or consultant) (address of representative/consultant)

is fully authorized by the undersigned to submit an Eligibility and Deductible Application to the Office of the State Fire Marshal for IEMA incident number 20170100; and

- (2) that the undersigned owner or operator of this facility has authority to direct remediation at this facility and has directed the above representative or consultant to take all actions necessary to perfect the Eligibility and Deductible Application for this facility, including the submittal of any necessary additional information; and
- (3) that the undersigned is a corporate officer, managing member, managing partner, individual owner, or other employee or other representative of the owner/operator with full authority to direct submittals concerning the remediation in this matter and make these representations on behalf of the owner/operator.

SIGNED:

Under penalties for perjury as provided by law pursuant to Section 1-109 of the Code of Civil Procedure, the undersigned certifies that the statements set forth in this instrument are true and correct.

16E AYNF

Estate Trustee Title (if not a sole proprietor)

3-1-2017

Vet62626 Comigstinet E-mail Address for Person Signing

1035 Stevenson Dr., Springfield, IL 62703, (217) 785-0969 JRTC, 100 W. Randolph St., Ste. 4-600, Chicago, IL 60601, (312) 814-2693 2309 W. Main St., Marion, IL 62959, (618) 993-7085 TDD: 217-785-0969 Web site: WWW.SFM.ILLINOIS.GOV



Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020 FOR OFFICE USE ONLY Facility # 3000721 Permit # 00203-2017REM Request Rec'd 02/22/2017 Amended Date Approval Date 2/23/2017 DS Permit Expires 8/23/2017

Permit for REMOVAL of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to remove underground storage tank(s) or piping is hereby granted. Such removal shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, at which time the UST activity shall be scheduled. THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Evelyn Page Trust 24 Rutledge Ave	Evelyn Page Trust 23907 W. Farmington Rd. Farmington, IL 61531
Contact: Wayne Page (309) 573-2367	Contact: Wayne Page (309) 573-2367

(3) <u>REMOVAL OF TANKS:</u>

- (a) Number and size of tanks being removed: (TK # 2) 10,000
- (b) Description/location of piping being removed:
- (c) Product to be stored in each tank: (TK # 2) Diesel Fuel
- (d) Reason of tanks being removed:
- (e) If tank(s) is leaking, indicate IEMA incident number: 2017-0100
- (f) Date each tank was last used: (TK # 2) 5/22/2012
- (4) The owner must notify this Office when completion of tank removal has occurred, on the Notification for Underground Storage Tank Form This form can be obtained at www.sfin illinois.gov or by calling (217)785-1020. After removal is completed, the owner/operator shall perform a site assessment by measuring for the presence of a release where contamination is most likely to be present at the UST site. This is in accordance with the Illinois Administrative Code 176.360 (a) regulations and 40 CFR Part 280.72 (a) Federal Register Requirement.

(5) SPECIAL CONTINGENCIES : Remove existing 10,000 gallon tank and piping.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Illinois Oil Marketing Equipment, Inc. 850 Brenkman Drive Pekin, IL 61554 Contact Person: Chris Epkins Phone: (309) 347-1819 Contractor Registration # IL1293 Exp. 2/4/2018

Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL

Removal Permit Application - 3000721 - Illinois Oil Marketing Equipment, Inc. - State ID: IL1293

Permit Application Summary

Permit Application Status: Approved

۴.

.

Received Date: 2/22/2017 ¡Owner - U0038682

 Owner Name
 Evelyn Page Trust

 Address
 24 Rutledge Ave.

 Bartonville, IL 61607

 Contact Person
 Wayne Page

 Phone Number

Facility - 3000721 Facility Name Evelyn Page Trust Address 23907 W. Farmington Rd. Farmington, IL 61531 County Fulton Contact Person Wayne Page Phone Number

Owner Information is different

Facility Information is different

Tanks on the Permit

Tank #	Capacity	Product	Tank Status	Pre-1974	Last Used Date	Comment
 2	10,000	Diesel Fuel	Out of service	No	5/22/2012	

Summary of Work

Remove existing 10,000 gallon tank and piping.

IEMA Number

2017-0100

Supplemental Documents Uploaded for the Application

Document Type	Document name	Last Uploaded	
There are no documents to display.			

Terms and Conditions

Name of the Authorized Representative: Chris Epkins Title or Position: Operations Assistant If agree to the Terms and Conditions

Payment

Permit Application Status: Approved

Bill To Name	Payment Received	Applied Amount	Received	Authorization Code	Transaction ID
Chris Epkins	\$200.00	(\$200.00)	2/23/2017	681258	1837659

Office of the Illinois State Fire Marshal

1035 Stevenson Dr. Springfield, IL 62704 | (217) 785-1020



1438185006 – Peoria County Page, Evelyn M Trust Incident # 20170100 Leaking UST Technical File 1

Midwest Environmental Consulting & Remed 22200 Illinois Route 9 • P.O. Box 61 Tremont, IL 61568-0614 Phone : (309) 925-5551 • Fax : (309) 925-5606 E-mail : mdwstenv@frontier.com

March 30, 2017

Illinois Environmental Protection Agency Bureau of Land - #24 LUST Section 1021 North Grand Avenue East Post Office Box 19276 Springfield, Illinois 62794-9276

> RE: LPC# 1438185006 – Peoria County Trivoli / Evelyn Page Trust 23907 West Farmington Road Incident # 20170100 LUST Technical File

Dear Sir or Madam:

Attached please find the 45-Day Report for the subject site. If you have any questions, please contact our office. Early action activities have been completed, including UST removal. Please find attached the results of early action activities and a request for issuance of a No Further Remediation (NFR) letter.

Sincerely,

Midwest Environmental Consulting & Remediation Services, Inc.

all-m then

Allan Green President

RECEIVED

APR 1 3 2017

IEPA-DIVISION OF RECORDS MANAGEMENT

AUG 17 2017

IEPA/BOL

REVIEWER: EMI

AJF/glg Job No. 17-18 cc: Mr. Wayne Page

1438185006 – Peoria County Page, Evelyn M Trust Incident # 20170100 Leaking UST Technical File

Leaking Underground Storage Tank

45 DAY REPORT

SUBJECT SITE:

EVELYN PAGE TRUST 23907 WEST FARMINGTON ROAD TRIVOLI, ILLINOIS 61569 INCIDENT #20170100

PREPARED FOR:

MR. WAYNE PAGE 24 RUTLEDGE AVENUE BARTONVILLE, ILLINOIS 61607 (309) 573-2367

PREPARED BY:

MIDWEST ENVIRONMENTAL CONSULTING AND REMEDIATION SERVICES, INC. 22200 Illinois Route 9 Post Office Box 614 TREMONT, Illinois 61568-0614 CONTACT: Allan Green, President



APR 1 3 2017

FOR REVIEW BY:

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY BUREAU OF LAND - #24 LEAKING UNDERGROUND STORAGE TANK SECTION 1021 NORTH GRAND AVENUE EAST POST OFFICE BOX 19276 SPRINGFIELD, ILLINOIS 62794-9276

IEPA-DIVISION OF RECORDS MANAGEMENT

AUG 17 2017 REVIEWER: EMI

45 Day Report

TABLE OF CONTENTS

IEPA 45 DAY REPORT FORM 45 DAY REPORT

FIGURES

Figure 1	Area Map
FIGURE 2	TOPOGRAPHIC MAP
FIGURE 3	SITE MAP
FIGURE 4	TANK PIT CROSS SECTION

TABLES

Table 1	SOIL ANALYTICAL DATA
Table 2	UST INFORMATION

APPENDICES

- APPENDIX A LABORATORY REPORTS
- APPENDIX B SOIL SAMPLING PROTOCOL
- APPENDIX C WELL SURVEY SWAP DATA
- APPENDIX D OSFM PERMIT
- APPENDIX E SITE PHOTOGRAPHS
- APPENDIX F PROPERTY OWNER SUMMARY FORM

IEPA 45 DAY REPORT FORM



Illinois Environmental Protection Agency

Bureau of Land • 1021 North Grand Avenue East • P.O. Box 19276 • Springfield • Illinois • 62794-9276

The Agency is authorized to require this information under Section 4 and Title XVI of the Environmental Protection Act (415 ILCS 5/4, 5/57 – 57.17). Failure to disclose this information may result in a civil penalty of not to exceed \$50,000.00 for the violation and an additional civil penalty of not to exceed \$10,000.00 for each day during which the violation continues (415 ILCS 5/42). Any person who knowingly makes a false material statement or representation, orally or in writing, in any label, manifest, record, report, permit, or license, or other document filed, maintained or used for the purpose of compliance with Title XVI commits a Class 4 felony. Any second or subsequent offense after conviction hereunder is a Class 3 felony (415 ILCS 5/44 and 57.17). This form has been approved by the Forms Management Center.

Leaking Underground Storage Tank Program 45-Day Report

A. Site Identification

IEMA Incident # (6- or 8-digit): 20170100	IEPA LPC# (10-	digit): 1438185006	
Site Name: Evelyn M Page Trust			
Site Address (Not a P.O. Box): 23907 West	Farmington Road		
City: Trivoli	County: Peoria	Zip Code: 61569	

B. Release Information

UST Volume (gallons)	Material Stored in UST	Release Yes / No	Type of Release Tank Leak / Overfill / Piping Leak	Product Removed? Yes / No	Tank Status Repaired / Removed / Abandoned / In Use
10000	diesel fuel	Yes	Tank Leak	Yes	Removed
					RECEIVE
					APP- 1- 8-2017
					IEPA/BOL

C. Early Action

1. Does this report demonstrate that the most stringent Tier 1 remediation objectives have been met? 7 Yes 7 No

🗌 Yes 🔽 No

🗌 Yes 🔽 No

2. Was free product encountered?

If yes , the owner or operator must submit a Free Product Removal Report (form LPC 504).
If free product removal will be conducted for more than 45 days, a Free Product Removal
Plan (and budget, if applicable) must be submitted (form LPC 504).

3. Have any fire or safety hazards posed by vapors or free product or contamination to a potable water supply been identified?

4.	What was the volume of	backfill material excavated?	Yards ³
۰.	Triac mad the Totallie of	odokim matorial executated:	10103

IL 532 2277 45-Day Report LPC 503 Rev. April 2014

5. What was the volume of native soil excavated?	Yards ³
6. Was groundwater encountered at the site?	🗌 Yes 🖌 No
7. Did the groundwater exhibit a sheen?	🗌 Yes 🖌 No

D. Site/Release Information

Provide the following:

- 1. Data on the nature and estimated quantity of release;
- 2. Data from available sources or site investigations concerning the following factors:
 - a. Surrounding populations;
 - b. Water quality;
 - c. Use and approximate locations of wells potentially affected by the release;
 - d. Subsurface soil conditions;
 - e. Location of subsurface sewers;
 - f. Climatological conditions; and
 - g. Land use;
- A discussion of what was done to measure for the presence of a release where contamination was most likely to be present at the UST site;
- 4. The results of the free product investigations;
- 5. A discussion of the action taken to prevent further release of the regulated substance into the environment;
- 6. A discussion of the action taken to monitor and mitigate fire and safety hazards posed by vapors or free product that has migrated from the UST excavation zone and entered subsurface structures; and
- 7. Any other information collected while performing initial abatement measures pursuant to 35 Ill. Adm. Code 731.162 or 734.210(b).

E. Other Information

Provide the following:

- 1. An area map showing the site in relation to surrounding properties;
- 2. A cross section, to scale, showing the UST(s) and the excavation;
- 3. Analytical/screening results in tabular format including the results of soil samples required pursuant to 35 III. Adm. Code 734.210(h) and the most stringent Tier 1 remediation objectives;
- 4. Site map meeting the requirements of 35 III. Adm. Code 734.440 and including sample locations;
- 5. Soil boring logs;
- 6. Chain of custody forms;
- 7. Laboratory analytical reports;
- 8. Laboratory certifications;
- 9. A copy of the Office of the State Fire Marshal Permit for Removal, Abandonment-in-Place, or other OSFM permits or notifications;

- 10. A narrative of tank removal and cleaning operations; describe how wastes generated during the tank removal were managed, treated, and disposed of;
- 11. Photographs of UST removal activities and the excavation; and
- 12. Copies of manifests for soil and groundwater transported off-site.

F. Early Action Tier 1 Remediation Objectives Compliance Report

If the most stringent Tier 1 remediation objectives of 35 III. Adm. Code 742 for the applicable indicator contaminants have been met and a groundwater investigation is not required, in addition to the information provided above, provide the following:

1. Site characterization;

- 2. If water was encountered in the excavation, provide a demonstration pursuant to 35 III. Adm. Code 734.210(h)(4)(C) that it is not representative of actual groundwater; and
- 3. Property Owner Summary (form LPC 568).

G. Signatures

UST Owner or Operator Signature:

All plans, budgets, and reports must be signed by the owner or operator and list the owner's or operator's full name, address, and telephone number.

UST Owner or Operator and Licensed Professional Engineer or Licensed Professional Geologist Certification of Stage 1 Site Investigation Plan and Budget (applies to Part 734 sites continuing beyond early action):

Pursuant to 35 III. Adm. Code 734.315(b) and 734.310(b), I certify that the Stage 1 site investigation will be conducted in accordance with 35 III. Adm. Code 734.315 and that the costs of the Stage 1 site investigation will not exceed the amounts set forth in 35 III. Adm. Code 734.Subpart H, Appendix D, and Appendix E. This certification is intended to meet the requirements for a plan and budget for the Stage 1 site investigation required to be submitted pursuant to 35 III. Adm. Code 734.310.

Continue onto next page.

Licensed Professional Engineer or Licensed Professional Geologist Certification:

I certify under penalty of law that all activities that are the subject of this plan, budget, or report were conducted under my supervision or were conducted under the supervision of another Licensed Professional Engineer or Licensed Professional Geologist and reviewed by me; that this plan, budget, or report and all attachments were prepared under my supervision; that, to the best of my knowledge and belief, the work described in this plan, budget, or report has been completed in accordance with the Environmental Protection Act [415 ILCS 5], 35 III. Adm. Code 731, 732, or 734, and generally accepted standards and practices of my profession; and that the information presented is accurate and complete. I am aware there are significant penalties for submitting false statements or representations to the Illinois EPA, including but not limited to fines, imprisonment, or both as provided in Sections 44 and 57.17 of the Environmental Protection Act [415 ILCS 5/44 and 57.17].

UST Owner or Operator

Consultant


Name Evelyn M Page Trust
Contact Mr. Wayne Page
Address 24 Rutledge Avenue
City Bartonville
State Illinois
Zip Code 61607
Phone (309) 573-2367
Signature Way Wary
Date 3-23-2017

Company M.E.C.R.S., Inc.
Contact Mr. Allan Green
Address 22200 Illinois Route 9, P.O. Box 614
City Tremont
State Illinois
Zip Code 61568
Phone (309) 925-5551
E-mail: mdwstenv@frontier.com
Signature Cler m Juin
Date 3/13/17
/ /

L.P.E. or L.P.G. Seal

Name Penny Silzer
Company M.E.C.R.S., Inc.
Address 22200 Illinois Rt. 9, P.O. Box 614
City Tremont
State Illinois
Zip Code 61568
Phone (309) 925-5551
III. Registration 196-000256
License Expiration Date 03/3 V17
Signature
Date 328N7

Licensed Professional Engineer or Geologist



45-Day Report Page 4 of 4

45 DAY REPORT

D. Site Information

1. Data on the nature and estimated quantity of the release;

A suspected release of diesel fuel was reported to the Illinois Emergency Management Agency on February 7, 2017 and assigned incident number 20170100. One 10,000 gallon diesel fuel tank was removed on March 10, 2017. Backfill impacted with petroleum hydrocarbons was observed in the tank pit. Soil analytical data collected confirms that a release of petroleum hydrocarbons from the UST has occurred. The quantity of the release is unknown.

2. Data from available sources or site investigations concerning the following factors:

a.) Surrounding populations;

The site of the release is located within a rural area in Trivoli, Illinois (approximate population: 1,000). Vicinity maps are attached.

b.) Water quality;

Water for the area is supplied by a municipal source. Water quality is reported as good. No reports of petroleum contamination of the local water supply have been identified.

c.) Use and approximate locations of wells potentially affected by the release;

No wells exist in the immediate proximity of the site. It does not appear that any wells are potentially affected by the release at the site. The well survey map generated from the SWAP database is provided in Appendix C.

d.) Subsurface soil conditions;

In general, the site is underlain by the Radnor Till Member of the Glasford Formation of the Wisconsinan glacial stage deposits. The Radnor Till is overlain by the Sangamon Soil, which is overlain by Wisconsinan loesses. The member occurs in central and east-central Illinois.

e.) Location of subsurface sewers;

A site sketch showing approximate utility locations is included.

f.) Climatological conditions;

Climatological conditions have been typical for the region. The climatological conditions are not expected to have a major impact on site activities or contaminant migration.

g.) Land use;

The subject site is located on West Farmington Road in Trivoli and is a former bus barn. The facility has been closed and will remain closed. The site is located in a rural area developed mainly for residential and agricultural use.

3. A discussion of what was done to measure for the presence of a release where contamination was most likely to be present at the UST site;

One soil samples was collected from the tank pit backfill (BF1) for verification of a release. Two samples were collected from native soil beneath the UST (NF1 and SF1). One sample for every 20 linear feet of tank pit wall was collected from native soil surrounding the tank pit (WW1, EW1, NW1, and SW1).

Soil samples were collected in accordance with the protocol detailed in Appendix B and submitted to PDC Laboratories in Peoria, Illinois for chemical analysis of BTEX and PNAs.

4. **Results of the free product investigations;**

Free product was not observed at the site.

5. A discussion of the action taken to prevent further release of the regulated substance into the environment;

The underground storage tank has been removed from the site.

6. A discussion of the action taken to mitigate fire and safety hazards posed by vapors or free product that has mitigated from the UST excavation zone and entered subsurface structures;

There have been no reports of free product or vapors in inhabited subsurface structures in the area as a result of the release.

7. Any other information collected while performing initial abatement measures pursuant to 35 Ill. Adm. Code Section 732.162 or 732.202 (b).

Not applicable.

Evelyn Page Trust-Trivoli 45 Day Report Page 4

E. Supporting Documentation Provide the following:

- 1. Site map to scale and oriented north showing:
 - a. UST(s) system(s) and excavation limits;
 - b. Product and dispenser lines;
 - c. Pumps and islands;
 - d. Underground utilities (sewer, gas, water, etc.);
 - e. Nearby structures (buildings, roads, etc.);
 - f. Soil boring(s) (if present);
 - g. Monitoring well(s) and/or sumps (if present);
 - h. Property boundaries;
 - i. Sample location points;

A site sketch showing the current layout is attached in Figure 3.

2. An area map showing the site in relation to surrounding properties. This map should identify the facilities on the surrounding properties;

An area map and topographical map are attached to this report. See Figures 1 and 2.

3. A cross section, to scale, with dimensions showing the UST(s) and the excavation;

A cross section to scale with dimensions showing the USTs and the excavation is provided in Figure 4.

4. Analytical/screening results in tabular format;

See Table 1.

5. UST(s) information in a tabular format and that at a minimum includes;

- a. The total number of UST(s) on site;
- b. The volume of the UST(s) (in gallons);
- c. The material stored in the UST(s);
- d. Identification of UST system(s) that had a release;
- e. Identification of UST system(s) that were repaired, removed, or abandonedin-place.

Underground storage tank information is attached to this report. See Table 1.

6. A copy of the Office of the State Fire Marshal Permit for Removal, Abandonment-in-Place or other OSFM permits or notifications;

A copy of the Tank Removal Permit is provided in Appendix B.

7. A narrative of tank removal and cleaning operations; describe how wastes generated during the tank removal were managed, treated and disposed;

There was one UST located at the site (OSFM Facility ID# 3-000721). The UST was registered with the OSFM. Incident number 20170100 was assigned to the subject site on February 7, 2017 in response to failure of tank inspections.

On March 10, 2017, personnel and equipment were mobilized to the site located at 23907 West Farmington Road in Trivoli, Illinois (site) for underground storage tank (UST) removal activities. Illinois Oil Marketing Equipment (IOME) of Pekin, Illinois provided UST excavation, cleaning and disposal services; Midwest Environmental Consulting and Remediation Services, Inc. (MECRS) of Tremont, Illinois provided project oversight, documentation and consultation. The USTs were decommissioned under the supervision of Office of the Illinois State Fire Marshal (OSFM) representative

The UST was exposed the day of tank removal. The tank was previously cleaned for inspection of the lining and was completely empty of debris and residue. Associated piping was excavated and removed. The top of the UST was exposed with a backhoe. The tank was then vented of vapors so that 5% of the lower explosive limit was detected. The tank was removed from its respective excavation and cut open. The decontaminated, open tank was then loaded onto a flatbed trailer for transport to be scrapped.

Upon removal of the tank, soil samples were collected from the excavation extents. The tank was in fair condition. Although it had been lined in the past, contamination in the UST pit was apparently due to piping leaks, corrosion, and spills or overfills. The removal procedures were conducted according to standard safety protocols, under the supervision of a representative of the OSFM.

The geologic strata encountered during removal consisted of silty, sandy, clays and till. Contaminated soils were observed in the UST excavation.

Soil samples were collected from native material at depths of about 3 feet below the invert elevation of the base of the tank and from the UST excavation sidewalls. Sidewall samples were retrieved from depths representative of two thirds the distance from the surface, in the lower one third of the excavation.

Soil samples were containerized in glass jars and sealed under lids with Teflon septums and placed into a cooler on ice. The samples were transported to PDC Laboratories of Peoria, Illinois for BTEX and PNAs under chain-of-custody, and accompanied by appropriate documentation.

No water bearing unit was identified in the depth of the UST excavation.

results and completed chains-of-custody are provided in Appendix A.

Confirmation of the presence of a release was indicated by soil analytical results which indicate the presence of PNAs in the backfill surrounding the tank pit.

8. Photographs of UST removal activities and the excavation;

Photos are presented in Appendix E.


9. Copies of manifests for soil and groundwater transported off-site.

Not applicable.

FIGURE 1

AREA MAP

Electronic Filing: Received, Clerk's Office 11/5/2020 Area Map



Copyright @ 1988-2004 Microsoft Corp. and/or its suppliers. All rights reserved. http://www.microsoft.com/streets/ @ Copyright 2003 by Geographic Data Technology, Inc. All rights reserved. @ 2004 NAVTEQ. All rights reserved. This data includes information taken with permission from Canadian authorities @ Her Majesty the Queen in Right of Canada. 0041

FIGURE 2

TOPOGRAPHIC MAP





FIGURE 3

I

SITE MAP



commercial properties

FIGURE 4

TANK PIT CROSS SECTION




TABLE 1

SOIL ANALYTICAL DATA

Table 1. Electronic Filing: Received, Clerk's Office 11/5/2020 Soil Analytical Data Evelyn Page Trust Trivoli, IL

				1				
Analytes/ Sample ID:	Tier I Soil CUOs for	NW1	SW1	EW1	WW1	SF1	NFI	BF1
SAMPLE DATE	Class I GW	03/10/17	03/10/17	03/10/17	03/10/17	03/10/17	03/10/17	03/10/17
Benzene	30	<28	<31	<27	<27	<32	<26	<32
Toluene	12,000	<28	<31	<27	<27	<32	<26	<32
Ethylbenzene	13,000	<28	<31	<27	<27	<32	<26	<32
Total Xylenes	5,600	<83	<94	<80	<82	<97	<78	<97
PNAs	\searrow	\times	\times	\ge	$\left \right\rangle$	\times	\times	\ge
Acenaphthene	570,000	<85	<88	<84	<83	<79	<79	<87
Acenaphthylene	xx	<85	<88	<84	<83	<79	<79	<87
Anthracene	12,000,000	<85	<88	<84	<83	<79	<79	<87
Benzo (a) Anthracene	900	12	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7
Benzo (a) Pyrene	90	13	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7
Benzo (b) Fluoranthene	900	17	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7
Benzo (g,h,i) Perylene	XX	11	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7
Benzo (k) Fluoranthene	9,000	6.9	<4.5	<4.2	<4.2	<4.0	<4.0	<4.4
Chrysene	88,000	14	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7
Dibenzo (a,h) Anthracene	90	<8.5	<8.8	<8.4	<8.3	<7,9	<7.9	<8.7
Fluoranthene	3,100,000	20	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7
Fluorene	560,000	<85	<88	<84	<83	<79	<79	<87
ldeno (1,2,3-cd) Pyrene	900	12	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7
Naphthalene	1,800	<85	<88	<84	<83	<79	<79	1,200
Phenanthrene	XX	<85	<88	<84	<83	<79	<79	<87
Pyrene	2,300,000	22	<8.8	<8.4	<8.3	<7.9	<7.9	<8.7

All results in ppb (parts per billion) except where noted.

.

TABLE 2

UST INFORMATION

Table 2. Underground Storage Tank InformationEvelyn Page Trust, Trivoli

<u>Tank No.</u>	Size (gal)	Contents	Release (Y or N)	Removed (Y or N)
1	10000	Gasoline	N	Y (in 1991)
2	10000	Diesel fuel	Y	Y

APPENDIX A

LABORATORY REPORTS



PDC Laboratories, Inc.

PROFESSIONAL • DEPENDABLE • COMMITTED

March 30, 2017

Allan Green Midwest Environmental Tremont Box 614 Tremont, IL 61568

Dear Allan Green:

Please find enclosed the analytical results for the sample(s) the laboratory received on 3/17/17 1:10 pm and logged in under work order 7032606. All testing is performed according to our current TNI certifications unless otherwise noted. This report cannot be reproduced, except in full, without the written permission of PDC Laboratories, Inc.

If you have any questions regarding your report, please contact your project manager. Quality and timely data is of the utmost importance to us.

PDC Laboratories, Inc. appreciates the opportunity to provide you with analytical expertise. We are always trying to improve our customer service and we welcome you to contact the Vice President, John LaPayne with any feedback you have about your experience with our laboratory.

Sincerely,

Kurt Stepping Senior Project Manager (309) 692-9688 x1719 kstepping@pdclab.com





PDC Laboratories, Inc.

2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-01 Name: NW1 Matrix: Soil - Grab	Sampled: 03/10/17 00:00 Received: 03/17/17 13:10								
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method		
General Chemistry - PIA									
Solids - total solids (TS)	79	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*		
<u> Polynuclear Aromatic Hydrocarbons - PIA</u>									
Acenaphthene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Acenaphthylene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Anthracene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Senzo(a)anthracene	12	ug/kg dry		03/23/17 08:19	03/28/17 17:32	EL\$	SW 8310		
Benzo(a)pyrene	13	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
3enzo(b)fluoranthene	17	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
3enzo(g,h,i)perylene	11	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Benzo(k)fluoranthene	6.9	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Chrysene	14	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Dibenzo(a,h)anthracene	< 8.5	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Fluoranthene	20	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Fluorene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
ndeno(1,2,3-cd)pyrene	12	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Naphthalene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Phenanthrene	< 85	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
Pyrene	22	ug/kg dry		03/23/17 08:19	03/28/17 17:32	ELS	SW 8310		
/olatile Organics - PIA									
Benzene	< 28	ug/kg dry		03/22/17 07:23	03/22/17 11:24	JJI	SW 8260B		
Ethylbenzene	< 28	ug/kg dry		03/22/17 07:23	03/22/17 11:24	JJI	SW 8260B		
foluene	< 28	ug/kg dry		03/22/17 07:23	03/22/17 11:24	JJI	SW 8260B		
Kylenes- Total	< 83	ug/kg dry		03/22/17 07:23	03/22/17 11:24	JJI	SW 8260B		



PDC Laboratories, Inc.

2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-02 Sampled: 03/10/17 00:00 Name: SW1 Received: 03/17/17 13:10 Matrix: Soil - Grab Soil - Grab Soil - Grab Soil - Grab									
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method		
General Chemistry - PIA									
Solids - total solids (TS)	76	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*		
Polynuclear Aromatic Hydrocarbons - PIA									
Acenaphthene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
Acenaphthylene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
Anthracene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
Benzo(a)anthracene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
Benzo(a)pyrene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
enzo(b)fluoranthene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
enzo(g,h,i)perylene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
enzo(k)fluoranthene	< 4.5	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
hrysene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
ibenzo(a,h)anthracene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
luoranthene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
luorene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
ndeno(1,2,3-cd)pyrene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
laphthalene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
Phenanthrene	< 88	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
Pyrene	< 8.8	ug/kg dry		03/23/17 08:19	03/28/17 17:58	ELS	SW 8310		
/olatile Organics - PIA									
Benzene	< 31	ug/kg dry		03/22/17 07:23	03/22/17 11:51	JJI	SW 8260B		
thylbenzene	< 31	ug/kg dry		03/22/17 07:23	03/22/17 11:51	ILL	SW 8260B		
Toluene	< 31	ug/kg dry		03/22/17 07:23	03/22/17 11:51	JJI	SW 82608		
ylenes- Total	< 94	ug/kg dry		03/22/17 07:23	03/22/17 11:51	JJI	SW 8260B		



PDC Laboratories, Inc.

2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-03 Sampled: 03/10/17 00:00 Name: EW1 Received: 03/17/17 13:10 Matrix: Soil - Grab Soil - Grab Soil - Grab Soil - Grab									
arameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method		
ieneral Chemistry - PIA									
olids - total solids (TS)	80	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*		
olynuclear Aromatic Hydrocarbons - PIA									
cenaphthene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
cenaphthylene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
nthracene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
enzo(a)anthracene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
enzo(a)pyrene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	EL\$	SW 8310		
enzo(b)fluoranthene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
enzo(g,h,i)peryléné	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
enzo(k)fluoranthene	< 4.2	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
hrysene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
ibenzo(a,h)anthracene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
luoranthene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
luorene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
ideno(1,2,3-cd)pyrene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
aphthalene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
henanthrene	< 84	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
yrene	< 8.4	ug/kg dry		03/23/17 08:19	03/28/17 18:24	ELS	SW 8310		
olatile Organics - PIA									
enzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 17:33	JJI	SW 8260B		
thylbenzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 17:33	JJI	SW 8260B		
bluene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 17:33	ILL	SW 8260B		
ylenes- Total	< 80	ug/kg dry		03/23/17 13:05	03/23/17 17:33	ILL	SW 8260B		



PDC Laboratories, Inc.

2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-04 Name: WW1 Matrix: Soil - Grab				Sampled: 03/10/17 00:00 Received: 03/17/17 13:10					
'arameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method		
eneral Chemistry - PIA									
olids - total solids (TS)	80	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*		
olynuclear Aromatic Hydrocarbons - PIA									
cenaphthene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
cenaphthylene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
nthracene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
enzo(a)anthracene	< 8,3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
enzo(a)pyrene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
enzo(b)fluoranthene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
enzo(g,h,i)perylene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
enzo(k)fluoranthene	< 4.2	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
hrysene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
ibenzo(a,h)anthracene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
luoranthene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
luorene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
ideno(1,2,3-cd)pyrene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
aphthalene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
henanthrene	< 83	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
yrene	< 8.3	ug/kg dry		03/23/17 08:19	03/28/17 18:49	ELS	SW 8310		
olatile Organics - PIA									
enzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 18:00	JJI	SW 8260B		
thylbenzene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 18:00	JJI	SW 8260B		
bluene	< 27	ug/kg dry		03/23/17 13:05	03/23/17 18:00	JJI	SW 8260B		
ylenes- Total	< 82	ug/kg dry		03/23/17 13:05	03/23/17 18:00	JJI	SW 8260B		



PDC Laboratories, Inc.

2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-05 Name: SF1 Matrix: Soil - Grab		00:00 13:10					
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
General Chemistry - PIA							
Solids - total solids (TS)	85	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
Polynuclear Aromatic Hydrocarbons - PIA							
Acenaphthene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Acenaphthytene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Anthracene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Benzo(a)anthracene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Benzo(a)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Benzo(b)fluoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Benzo(g,h,i)perylene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Benzo(k)fluoranthene	< 4.0	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Chrysene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Dibenzo(a,h)anthracene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Fluoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Fluorene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Indeno(1,2,3-cd)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Naphthalene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Phenanthrene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:15	ELS	SW 8310
Volatile Organics - PIA							
Benzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 18:28	ILL	SW 8260B
Ethylbenzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 18:28	JJI	SW 8260B
Toluene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 18:28	JJI	SW 8260B
Xylenes- Total	< 97	ug/kg dry		03/23/17 13:05	03/23/17 18:28	JJI	SW 8260B



PDC Laboratories, Inc.

2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-06 Name: NF1 Matrix: Soil - Grab					-	03/10/17 (03/17/17 ⁻	
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method
General Chemistry - PIA					_		
Solids - total solids (TS)	84	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*
Polynuclear Aromatic Hydrocarbons - PIA							
Acenaphthene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Acenaphthylene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Anthracene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Benzo(a)anthracene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Benzo(a)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Benzo(b)fluoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Benzo(g,h,i)perylene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Benzo(k)fluoranthene	< 4.0	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Chrysene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Dibenzo(a,h)anthracene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Fluoranthene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Fluorene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Indeno(1,2,3-cd)pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Naphthalene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Phenanthrene	< 79	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Pyrene	< 7.9	ug/kg dry		03/23/17 08:19	03/28/17 19:41	ELS	SW 8310
Volatile Organics - PIA							
Benzene	< 26	ug/kg dry		03/23/17 13:05	03/23/17 18:55	ILL	SW 8260B
Ethylbenzene	< 26	ug/kg dry		03/23/17 13:05	03/23/17 18:55	JJI	SW 8260B
Toluene	< 26	ug/kg dry		03/23/17 13:05	03/23/17 18:55	JJI	SW 8260B
Xylenes- Total	< 78	ug/kg dry		03/23/17 13:05	03/23/17 18:55	JJI	SW 8260B



PDC Laboratories, Inc. 2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

Sample: 7032606-07 Name: BF1 Matrix: Soil - Grab	Sampled: 03/10/17 00:00 Received: 03/17/17 13:10								
Parameter	Result	Unit	Qualifier	Prepared	Analyzed	Analyst	Method		
Seneral Chemistry - PIA									
Solids - total solids (TS)	77	%	н	03/20/17 09:12	03/20/17 09:43	KNS	SM 2540G*		
Polynuclear Aromatic Hydrocarbons - PIA									
Acenaphthene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
cenaphthylene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
Anthracene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
Benzo(a)anthracene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
Benzo(a)pyren o	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
Benzo(b)fluoranthene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
enzo(g,h,i)perylene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
enzo(k)fluoranthene	< 4.4	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
hrysene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
)ibenzo(a,h)anthracene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
luoranthene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
luorene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
ndeno(1,2,3-cd)pyrene	< 8.7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
laphthalene	1200	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
Phenanthrene	< 87	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
byrene	< 8,7	ug/kg dry		03/23/17 08:19	03/28/17 20:07	ELS	SW 8310		
<u>/olatile Organics - PIA</u>									
Benzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 19:22	JJI	SW 8260B		
thylbenzene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 19:22	JJI	SW 8260B		
oluene	< 32	ug/kg dry		03/23/17 13:05	03/23/17 19:22	ILL	SW 8260B		
(yienes- Total	< 97	ug/kg dry		03/23/17 13:05	03/23/17 19:22	JJI	SW 8260B		



2231 West Altorfer Drive Peoria, IL 61615 (800) 752-6651

NOTES

Specific method revisions used for analysis are available upon request.

Certifications

PIA - Peoria, IL

TNI Accreditation for Drinking Water, Wastewater, Hazardous and Solid Wastes Fields of Testing through IL EPA Lab No. 100230 Illinois Department of Public Health Bacteriological Analysis in Drinking Water Approved Laboratory Registry No. 17553 Missouri Department of Natural Resources Certificate of Approval for Microbiological Laboratory Service No. 870 Drinking Water Certifications: Iowa (240); Kansas (E-10338); Missouri (870) Wastewater Certifications: Arkansas (88-0677); Iowa (240); Kansas (E-10338) Hazardous/Solid Waste Certifications: Arkansas (88-0677); Iowa (240); Kansas (E-10338)

SPMO - Springfield, MO USEPA DMR-QA Program

STL - St. Louis, MO

TNI Accreditation for Wastewater, Hazardous and Solid Wastes Fields of Testing through KS Lab No. E-10389 Illinois Department of Public Health Bacteriological Analysis in Drinking Water Approved Laboratory Registry No. 171050 Drinking Water Certifications: Missouri (1050) Missouri Department of Natural Resources

* Not a TNI accredited analyte

Qualifiers

H Test performed after the expiration of the appropriate regulatory/advisory maximum allowable hold time.

Certified by:

by: Kurt Stepping, Senior Project Manager



DC Laboratories, Inc. 231 W. Altorfer Dr eoria, IL 61615		HAIN OF CU								Phone: (800) 75 Fax: (309) 69 www.pdcla	12-9 68
	ALL	IGHLIGHTED AREAS MUST 8			LINT)						
CLIENT	P.O. NUMBER	PROJECT NAM		SHIPPED	3		LYSIS REC	UESTED	• •	(FOR LAB USE ONL)	
Doress Gnu.		First Stu	Ident 3	רו רו	\square	7		·		-1,2210	×
	PHONE	mowstemal	MEAN	S SHIPPED						LOGIN #:	2
BOD GIY ITY STATE ZIP	SAMPLER (PLEASE PRIN	Grantier.	LOVI MATRIX	TYPES:	- 1					LOGGED BY:	
Tremont II 61				STE WATER IKING WATER			l			PROJECT:	
ONTACT PERSON	SAMPLER'S SIGNATUR	reen	GW-GRC WWSL-S NAS-SOL		X	π			ł	PROJ MGR:	
Alla Green	Dee	Maron	LCHT-LE LCHT-LE OTHER:_		IEX	<u>s</u>					
2 SAMPLE DESCRIPTION AS YOU WANT TO REPORT	DATE T	IM5 SAMPLE T		COUNT COUNT	Ā	2				REMARKS	
NWI	3/10/17	X		5	~	1					
SWI	3/10/17	×		5		~					
EW1	3/10/17	~		5	1	4					
<u></u>	3/10/17	~		5	1	1					
SFI	3/10/17	X	·	5	1	1					<u></u>
M NF1	3/10/17	~		5	~	-	•				
BF1	36010			4	v	<u>~</u>					
				<u> </u>							
TURNAROUND TIME REQUESTED		DATE RESULTS I	·····		aarGrov will	anoha	ie if the cor	nale iema	erzóure is	By initialing this area, you request th outside of the range of 0.1-8.0°C. By voliess of the sample temperature.	ist we no 'not initia
RELINQUISHED BY (SIGNATURE)		EIVED BY (SIGNATURE)	$\overline{}$	DATE -					COMME	NTS (FOR LAB USE ONLY)	
Ann Ann		~~~~~~ (dit de			{	₿			<u></u>	
ELINQUISHED BY (SIGNATURE)	DATE REC	EIVED BY SIGNATURE		DATE						DN RECEIPT	Y
,	ΤΙΜΕ		· · ·	TIME			SAMPLE(S) RECEIVI	D ON ICE		
ELINQUISHED BY (SIGNATURE)		EIVED BY (SKONATURE)	· · · ·	DATE	ולבו	2.	BOTTLES	FILLED WI	TH ADEQ	IN GOOD CONDITION	POR
Loi 1 Custa	3-17-17 TM5:10			TIME	<u>19 /.</u>	1	(EXCLUDE	S TYPICA	L FIELD P/	HOLD TIME(S) ARAMETERS) 4 IM SAMPLE BOTTLE	ØOR

Page 10 of 10

The Agency is authorized to require this information under Section 4 and Trile XVI of the Environmental Protection Act (415 ILCS 5/4, 5/57 - 67, 17). Faiture to disclose this information may result in a civil penalty of not to exceed \$50,000.00 for the violation and an additional civil penalty of not to exceed \$10,000 00 for each day during which the violation continues (415 ILCS 5/42). Any person who knowingly makes a false material stelement or representation in any label, manifest, record, report, pennit, or license, or other document filed, maintained or used for the purpose of compliance with Tille XVI commits a Class 4 falony. Any second or subsequent offense after conviction hereunder is a Class 3 felony (415 ILCS 5/67, 17). This form has been approved by the Forms Management Center.

> Illinois Environmental Protection Agency Leaking Underground Storage Tank Program Laboratory Certification for Chemical Analysis

A. Site Identification

IEMA Incident # (6- or 8-digit): 201701	00 IEPA LPC# (10-digit):	1438185006
Site Name: Evelyn M Page Trust		
Site Address (Not a P.O. Box): 23907	West Farmington Road	
City: Trivoli	County: <u>Peoria</u>	ZIP Code: 61569
Leaking UST Technical File		

B. Sample Collector

I certify that:


- 1. Appropriate sampling equipment/methods were utilized to obtain representative samples.
- 2. Chain-of-custody procedures were followed in the field.
- 3. Sample Integrity was maintained by proper preservation.
- 4. All samples were properly labeled.

C. Laboratory Representative

I certify that: FOR PDC # 703 2606

- 1. Proper chain-of-custody procedures were followed as documented on the chain-of-custody forms
- 2. Sample integrity was maintained by proper preservation.
- 3. All samples were properly labeled.
- 4. Quality assurance/quality control procedures were established and carried out.





initial

IL 532 2283 LPC 509 Rev. March 2006

0063

Laboratory Certification for Chemical Analysis

1 of 2

5. Sample holding times were not exceeded, SOLIDS ANALYSIS WAS DONE AT 10 DAYS

- SW-846 Analytical Laboratory Procedure (USEPA) methods were used for the analyses.
- An accredited lab performed quantitative analysis using test methods identified in 35 IAC 186.180 (for samples collected on or after January 1, 2003).

(initial)

D. Signatures

I hereby affirm that all information contained in this form is true and accurate to the best of my knowledge and belief. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sample Collector

Name: Allan Green
Title: Senior Project Manager
Company: M.E.C.R.S, Inc.
Address: 22200 IL Rte. 9, P.O. Box 614
City: Tremont
State: Illinois
ZIP Code: 61568
Phone: (309) 925-5551
Signature: <u>SIQ 9 m Muen</u>
Date: 3/10/17
1 1

Laboratory Representative

Name: Kurt Stepping
Title: Senior Project Manager
Company: PDC Laboratories
Address: 2231 W. Altorfer
City: Peoria
State: Illinois
ZIP Code: 61615
Phone:(309) 692,9688
Signature: AL St
Date: // 4-10-17

Laboratory Certification for Chemical Analysis 2 of 2

APPENDIX B

SOIL SAMPLING PROTOCOL

SOIL SAMPLING PROTOCOL

To be used when sampling L.U.S.T. site excavations for IEPA closure.

- 1. Sampling Methodology
 - A. All sampling equipment to be used will be cleaned and decontaminated using deionized water prior to and between samples.
 - B. Soil samples will be taken from excavation extents using a stainless steel trowel. The trowel will be inserted into the soil several inches so as to take a sample of undisturbed material. The sample will be immediately placed into a new, airtight, glass jar with a teflon lined lid.
 - C. The sample will be allowed to sit undisturbed for a period of time sufficient for vapor equilibrium to be reached. A headspace analysis of the sample will then be conducted using a portable photoionization detector.
 - D. Sampled extents showing contamination levels above 10 ppm on the PID will be continued. Sampled extents showing below 10 ppm.on the PID will be resampled for laboratory analysis.
- 2. Sample Storage and Transport
 - A. Soil samples will be collected in new, airtight, glass jars* with teflon lined lids. Samples for analysis will be immediately cooled using a thermally insulated cooler and ice. The samples will be transported, on ice, as soon as possible, to the laboratory or to the engineering office cooler to await transport to the laboratory.
 - B. No sample will be allowed to remain in the possession of the engineer or laboratory for more than two weeks prior to analysis.
 - C. A chain of custody record will be kept for all samples taken for laboratory analysis.
- 3. Samples will be taken from the excavation sidewalls and floor at the following intervals.
 - A. A minimum of one sample per twenty feet for sidewall extents. When lengths of sidewall exceed twenty feet, samples will be taken at equally spaced intervals, not to exceed twenty feet.
 - B. Samples will be taken at a height relating to the projection of the lower one third of the former under ground storage tanks onto the sidewall extents. Samples will be taken at a distance relating to one-third the total excavation height from the floor if tank elevations are unknown.

- C. A minimum of one sample per 400 square feet of excavation floor. Samples at minimum will be taken from the locations representing the bottoms of the former underground storage tanks.
- D. Composited samples of excavated materials may also be taken for background reference and landfill verification.

*Encore sampling system will be substituted for glass jars when required.

APPENDIX C

WELL SURVEY - SWAP DATA



Counties

Sources: Earl, HERE, DeLorme, Internap, Increment P. Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance: Survey, Esri Japan, METI, Esri China (Hong Kong), wwisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Web AppBuilder for ArcGIS

Appendix D

OSFM PERMIT



Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 3000721 Permit # 00203-2017REM Request Rec'd 02/22/2017 Amended Date Approval Date 2/23/2017 DS Permit Expires 8/23/2017

Permit for REMOVAL of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances,

Permission to remove underground storage tank(s) or piping is hereby granted. Such removal shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, at which time the UST activity shall be scheduled. THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Evelyn Page Trust 24 Rutledge Ave. Bartonville, IL 61607	Evelyn Page Trust 23907 W. Farmington Rd. Farmington, IL 61531
Contact: Wayne Page (309) 573-2367	Contact: Wayne Page (309) 573-2367

(3) <u>REMOVAL OF TANKS</u>;

- (a) Number and size of tanks being removed: (TK # 2) 10,000
- (b) Description/location of piping being removed:
- (c) Product to be stored in each tank: (TK # 2) Diesel Fuel
- (d) Reason of tanks being removed:
- (e) If tank(s) is leaking, indicate IEMA incident number: 2017-0100
- (f) Date each tank was last used: (TK # 2) 5/22/2012
- (4) The owner must notify this Office when completion of tank removal has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.sfm illinois.gov or by calling (217)785-1020. After removal is completed, the owner/operator shall perform a site assessment by measuring for the presence of a release where contamination is most likely to be present at the UST site. This is in accordance with the Illinois Administrative Code 176.360 (a) regulations and 40 CFR Part 280.72 (a) Federal Register Requirement.

(5) SPECIAL CONTINGENCIES : Remove existing 10,000 gallon tank and piping.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Illinois Oil Marketing Equipment, Inc. 850 Brenkman Drive Pekin, IL 61554 Contact Person: Chris Epkins Phone: (309) 347-1819 Contractor Registration # IL1293 Exp. 2/4/2018

Sincerely,


Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File APPENDIX E

SITE PHOTOS

DATE: <u>3/10/17</u> SITE NAME: Evelyn Page Trust property in Trivoli, Illinois – <u>EA Photos</u> PHOTOGRAPHS BY: <u>Allan Green</u>



COMMENTS: View looking west.



COMMENTS: South property line looking west along Route 116.

MIDWEST ENVIRONMENTAL CONSULTING AND REMEDIATION SERVICES, INC.

DATE: <u>3/10/17</u> SITE NAME: Evelyn Page Trust property in Trivoli, Illinois – <u>EA Photos</u> PHOTOGRAPHS BY: <u>Allan Green</u>




COMMENTS: View looking northwest.



COMMENTS: Utility markings along ROW of Route 116.

DATE: <u>3/10/17</u> SITE NAME: Evelyn Page Trust property in Trivoli, Illinois – <u>EA Photos</u> PHOTOGRAPHS BY: <u>Allan Green</u>




COMMENTS: West wall of UST excavation.



COMMENTS: Looking east along Route 116.

DATE: <u>3/10/17</u> SITE NAME: Evelyn Page Trust property in Trivoli, Illinois – <u>EA Photos</u> PHOTOGRAPHS BY: <u>Allan Green</u>



COMMENTS: Excavation of UST looking north.



COMMENTS: Commercial property to the west.

APPENDIX F

PROPERTY OWNER SUMMARY FORM



Illinois Environmental Protection Agency

Bureau of Land • 1021 N. Grand Avenue E. • P.O. Box 19276 • Springfield • Illinois • 62794-9276

The Agency is authorized to require this information under Section 4 and Title XVI of the Environmental Protection Act (415 ILCS 5/4, 5/57 – 57.17). Failure to disclose this information may result in a civil penalty of not to exceed \$50,000.00 for the violation and an additional civil penalty of not to exceed \$10,000.00 for each day during which the violation continues (415 ILCS 5/42). Any person who knowingly makes a false material statement or representation, orally or in writing, in any label, manifest, record, report, permit, or license, or other document filed, maintained or used for the purpose of compliance with Title XVI commits a Class 4 felony. Any second or subsequent offense after conviction hereunder is a Class 3 felony (415 ILCS 5/44 and 57.17). This form has been approved by the Forms Management Center.

Leaking Underground Storage Tank Program Property Owner Summary

A. Site Identification

IEMA Incident # (6- or 8-digit):	20170100	IEPA LPC# (10-dig	it): <u>1438185006</u>
Site Name: Evelyn M Page Tr	ust		
Site Address (not a P.O. Box):	23907 West Farmington Road		
City: <u>Trivoli</u>	County: Peoria	Zip Code: 6	1569

Leaking UST Technical File

Engineered barriers, institutional controls, and other use restrictions, if any, proposed for this site may not be implemented without approval by the title holder(s) of record for the above-named property or the agent(s) of such person(s). These controls and restrictions will be identified in the No Further Remediation (NFR) Letter, which must be recorded in the chain of title for the property. Failure to maintain these controls is grounds for voidance of the NFR Letter.

L1 3 2017

B.	Preventive, Engineering, and Institutional Controls and Land Use Limitations	R	ECI	ΞN	/EC	
	r reventive, Engineering, and metatorial controls and cana ose cinitations					

The following controls and restrictions are proposed for the above-named site:

- Industrial/commercial land use limitation;
- On-site groundwater restriction prohibiting the use of groundwater beneath the site as a potable water supply;

An engineered barrier: (description)	📋 Building, 📋	asphalt/concrete, or	Other
 Groundwater ordinance: Construction worker caut		☐ Without a MOU;	

- Other:
- None (There are no proposed institutional controls other than the NFR Letter.)

C. Property Ownership Declaration

I hereby affirm that I have reviewed the attached report entitled	45 Day Report/Corrective Action Completion
Report	and dated 3/30/17
Report and that I accept the terms and conditions set forth therein, inclu property I own. I further affirm that I have no objection to the rec containing the terms and conditions identified in the report upon	ording of a No Further Remediation Letter

Name of Property Owner: Ev	velyn M Page Trust
Name of Officer or Agent: M	r. Wayne Page
Mailing Address: 24 Rutledg	e Avenue
City Bartonville	
State Illinois	
Zip Code 61607 /	
Signature Wayn	Tan
Date 3-24-201	7
	State <u>Illinois</u> Zip Code 61607 Signature <u>Way</u> IW

D. Site Description

Real Estate Tax/Parcel Index Number: 1506400004


Legal Description of Site (must be provided on a separate sheet)

attached

Property Owner Summary Page 2 of 2

0079

	Peoria County, IL - Property Report	Convert to PDF	3/22/2017	
Parcel ID	Property Address	City	State	Zip
150640000	4 23907 W Farmington Rd	ELMWOO	D IL	61529



	Mobile Maps and Information	
--	-----------------------------------	--

Disclaimer: Peoria County makes every effort to produce and publish the most current and accurate information possible. This public information is furnished as a public service. The information must be accepted and used by the recipient with the understanding that the data was developed and collected for the purpose of administering a local property tax as required by the Illinois Property Tax Code. Peoria County assumes no liability whatsoever associated with the use or misuse of such data, and disclaims any representation or warranty as to the accuracy of the data.

Legal Description

SE 1/4 SEC 6-8-5E 1.181 AC BEG 1839.72' W & 30' N OF SE COR SEC 6: TH N 396' W 135.5' S 396' E 135.5' TO POB (EXC ROUTE 116 ROW AS DES C PER DOC #96-13383)

	Property Information - Section 1								
Property Type	Tax Code	Neighborhood	House Style	Stories	Exterior Construction	Year Built	Effective Year Built	Acres	
	954	150				0	0	1.18	

Property Information - Section 2							
Total Living Area	Main Living Area	Basement	Finished Basement	Recreation Area	Attached Garage	Detached Garage	
0	0	0	0	0	0	0	

Property Information - Section 3									
Air Conditioning	Bedrooms	Full Baths	Half Baths	Fire Places	Grade	Condition	Land AV	Building AV	Total AV
	0	0	0	0			\$7,340	\$23,330	\$30,670

Recent Sales					
Document Number	Sale Price	Sale Date			
1628099	\$40,000	12/1/2016			

http://gis.peoriacounty.org/Property_Report/Default.aspx?pin=1506400004&mapImage=_... 3/22/2017

LEAKING UST TECHNICAL REVIEW NOTES

Reviewed by: Carol Hawbaker Date Reviewed: 08/08/17

١

Re: LPC #1438185006 -- Peoria County Trivoli / Page, Evelyn M Trust 23907 West Farmington Road Leaking UST Incident No. 20170100 Leaking UST Technical File

Document(s) Reviewed:

45-Day /Early Action Tier 1 Compliance Report dated03/30/17, rcvd 04/13/17

General Site Information:

Site subject to: 734

IEMA date(s): 02/07/17	Payment from the Fund? (Y/N/unknown): Y
UST system removed? (Y/N): Y 03/10/17 -	OSFM Fac. ID #: 3000721 Facility Name =
UST was last used 05/22/12. no known UST's	Evelyn Page Trust
remain	
Encountered groundwater? (Y/N/unknown):	SWAP mapping and evaluation completion
Ν	date: 08/08/17
Free product? (Y/N/unknown): N	Site placement correct in SWAP? (Y/N): Y no
	private wells within 200ft, no CWS wells
•	within 2,500ft. No GW ordinance in effect
Current/past land use: Former First Student	Inspection Required? (Date/Plan): N
Transit bus facility. Presently Vacant	
Size & product of USTs: 1 – 10,000 gal diesel f	uel Indicator Contaminants = BETX and PNA's
Is site located in EJ area? N 08/08/17	Is investigation of indoor inhalation exposure
	route required? «Y_N»

*Note, the release was reported in Trivoli, an unincorporated area outside of Farmington to the east. OSFM lists the facility address as 23907 W. Farmington Road, Farmington - in Fulton County. The release is located in Peoria County.

A 10,000 gal gasoline UST was removed on 08/14/91. No release reported.

BOL File Information:(optional) (Arranged chronologically):

02/07/17: IEMA Incident Report H-2017-0100 Caller = Allan Green of Midwest Environmental Location = 23907 Farmington Road, Trivoli – Fulton County (later corrected to Peoria) Material = diesel from 10,000 gal UST Cause of release = piping IEPA-DIVISION OF RECORDS MANAGEMENT Discovered 02/06/17 Responsible Party = Evelyn M. Page Trust Contact: Wayne Page AUG 17 2017

RELEASADIE

REVIEWER: EMI

24 Rutledge Avenue, Bartonville, IL 61607

02/10/17: Illinois issued a Notice of Release letter

03/28/17: 20-Day Certification

Document Under Review

04/13/17:45-Day / Early Action Tier 1 Compliance ReportSection A:Site IdentificationIEMA Incident No. = 20170100LPC No. = 1438185006Site Name = Evelyn M. Page TrustSite Address = 23907 West Farmington Road, Trivoli – Peoria County

Section B: Release Information

UST Volume (gal)	Material Stored	Type of Release	Tank Status
10,000	Diesel Fuel	Tank Leak	Removed

Section C: Early Action

- 1. Does report demonstrate compliance with the most stringent Tier 1 RO's? Y
- 2. Was Free Product encountered? N
- 3. Were fire or safety hazards posed by vapors or contamination to a potable well supply identified? N
- 4. The volume of backfill material excavated = 0cy
- 5. The volume of native soil excavated = 0cy
- 6. Was GW encountered at the site? N

Section D: Site/Release Information

- Data on the nature and estimated quantity of release: A suspected release was reported on 02/07/17 due to tank failure inspections, and the UST was removed 03/10/17. The backfill was impacted with contamination. Analytical data confirms a release occurred.
- 2. Data from available source or site investigations concerning the following factors:
 - a. Surrounding Populations: Site is located in Trivoli, an unincorporated area, population app 1000. There is no mention of surrounding populations. To the south across Rte 116 is farmland, to the east is residential, to the west is industrial/commercial and to the north is farmland.
 - b. Water Quality: Water is provided by a municipal source

- c. Use and approximate locations of well potentially affected by the release: No wells are located within close proximity to the release.
- d. Subsurface soil conditions:
- e. Locations of subsurface sewers: The approximate locations are provided on a map
- f. Climatological conditions: Site is located in west central Illinois with typical west central Illinois climes.
- g. Land use: Site is a former bus barn. The facility is closed and will remain closed.
- 3. A discussion of what was done to measure for the presence of a release where contamination was most likely to be present: 1 soil sample was collected from UST backfill, 2 soil samples were collected from the native soil beneath the UST and 1 soil sample was collected from each sidewall.
- 4. Results of the free product investigation: FP not observed.
- 5. Discussion of the action taken to prevent further release into the environment: The UST was removed.
- 6. Discussion of the action taken to monitor and mitigate fire and safety hazards posed by vapors or free product: N/A no free product or vapors evident.
- Any other information collected while perform initial abatement measures pursuant to 35 Ill. Adm. Code 734.210(b): N/A

Section E: Other Information Provide the following:

- 1. Area map showing the site in relation to surrounding properties: A map showing the site in relation to surrounding properties is not provided in the report. See attached google map.
- 2. Cross section to scale showing the UST's and the excavation: The cross-section does not provide a scale. There is no information regarding the depth of the excavation.

- 3. Analytical screening results in tabular format including the results of soil samples required pursuant to 35 Ill. Adm. Code 734.210(h) and the most stringent Tier 1 RO's:
- 4. Site map meeting the requirements of 35 Ill. Adm. Code 734.440 and including sample locations: Provided. No soil samples exceeded most stringent Tier 1 RO's
- 5. Soil boring logs: N/A no borings drilled.
- 6. Chain of Custody forms: Provided.
- 7. Lab analytical reports: Provided.
- 8. Lab certifications: Provided.
- 9. A copy of the OSFM permit for removal or other OSFM permits or notifications: Provided.
- 10. A narrative of tank removal and cleaning operations; describe how wastes generated during tank removal were managed, treated and disposed of: Provided.
- 11. Photographs of UST removal activities and the excavation: Provided.
- 12. Copies of manifests for soil and groundwater transported off-site: No soil or GW transported off-site. Backfill placed back into tank basin.

Section F: Early Action Tier 1 Remediation Objectives Compliance Report Provide the following:

- 1. Site Characterization: Provided. No contamination exceeds Tier 1 RO's.
- If water was encountered in the excavation, provide a demonstration pursuant to 35 IAC 734.210(h)(4)(C) that it is not representative of actual groundwater: N/A GW not encountered.

<u>`</u>

3. Property Owner Summary Form Provided.

Section G: Signatures

UST Owner or Operator Signed by: Wayne Page, Evelyn Page Trust Consultant Signed by: Allan Green, Midwest Environmental Consulting & Remediation Certified by: Penny L. Silzer, LPG, Midwest Environmental Consulting & Remediation

, **`**

e.

Illinois EPA Decision:

-

No soil contamination exceeds most stringent Tier 1 RO's. Issue NFR with no restrictions.

Response Due: recorded NFR letter

Division of Petroleum & Chemical Safety

Facility Detai	Facility Details		
Facility Number:		Owner Name:	Evelyn Page Trust
Facility Name:	Evelyn Page Trust	· · · · · · · · · · · · · · · · · · ·	
Address:	23907 W. Farmington Rd. Farmington, IL	Owner Address:	24 Rutledge Ave. Bartonville, IL 61607
	<u>61531</u>	Owner Status:	Current Owner
County:	Fulton	Purchase Date:	12/12/2016
Status:	Closed	Type of Financial Responsibility:	
Facility Type:	Commercial / Retail	Financial Responsibility Reporting	
Motor Fuel Type:	Fleet	Due Date:	
Owner Type:	Private		
Green Tag Decal:	N002325		
Green Tag Issue Date:	3/20/2012		
Green Tag Expiration Date:	12/31/2014		
Motor Fuel Dispensing Permit Inspection Date:			
Motor Fuel Dispensing Permit Expiration Date:	12/31/2014		

Owner Summary

Owner Number	Owner Name	Owner Status	Purchase Date
U0038682	Evelyn Page Trust	Current Owner	12/12/2016
U0011481	Laidlaw Transit, Inc.	Former Owner	12/5/1991
U0030276	First Student, Inc.	Former Owner	

Permits (Unexpired)

Click for permit history						
Permit Number	Туре	Status	OSFM Receive Date	Issue Date	Expiration Date	Documents
00203-2017REM	Removal	Approved / Issued	2/22/2017	2/23/2017	8/23/2017	Documents

•

Deficiencies (Current)

No Deficiencies Found

IEMA Numbers Associated with the Facility

IEMA Number	Inspection Date	Inspection Type	Permit Number	
<u>17-0100</u>	3/10/2017	Removal Log	00203-2017REM	

LUST Fund Eligibility and Deductibility Determinations

IEMA Number	Status	OSFM Received Date	OSFM Response Date	Deductible	Letter
<u>20170100</u>	Eligible	4/6/2017	4/7/2 017	\$5,000	<u>Letter</u>

Tank Information

Tank Number 1

· · · · · · · · · · · · · · · · · · ·			
Capacity:	10000	Petroleum Use:	

0086

http://webapps.sfm.illinois.gov/ustsearch/Facility.aspx?ID=3000721&PrintDetail=true

Office of the Illinoie State Fire Marshal UST Search Facility Details for Fypy 2020 Trust Page 2 of 2

Product:	Gasoline	CE	CERCLA Substance:	
Status:	Removed	CA	CAS Code:	
OSFM First Notify Date:	1/31/1986	Re	Removed Date: 8/14/1	
Current Age:	25	· Ab	Abandoned Material:	
Install Date:		Ab	andoned Date:	
Last Used Date:	8/13/1992	Re	d Tag Issue Date:	
Product Date:		Fe	e Due:	\$0.00
Equipment Type Equip	ment Last Pas	sing Date Test	Expire Date	

Tank Number 2

-		· · · · · · · · · · · · · · · · · · ·	~r			
Capacity:	10000	Petroleum Use:	<u> </u>			
Product:	Diesel Fuel	CERCLA Substance				
Status:	Removed	CAS Code:				
OSFM First Notify Da	te: 12/9/1992	Removed Date:	3/10/2	017		
Current Age:	25	Abandoned Material:				
Install Date:	8/14/1991	Abandoned Date:				
Last Used Date:	5/22/2012	Red Tag Issue Date:				
Product Date:	8/14/1991	Fee Due:	\$0.00			
Equipment Type	Equipment			Las Dat	t Passing e	Test Expire Date
Corrosion Prot - Piping	Fiberglass No	iberglass Non-Corrosive				N/A
Corrosion Prot - Piping	Isolation Boots	solation Boots Flex Connector				N/A
Corrosion Prot - Tank	Fiberglass Non-Corrosive					N/A
Leak Detect - Piping	Mechanical Pr FX1DV	Mechanical Pressurized Line Leak Detection Red Jacket FX1DV				6/14/2013
Leak Detect - Piping	Piping Sump S TLS 300c	Piping Sump Sensors Interstitial Monitoring Veeder Root				6/14/2013
Leak Detect - Tank	Interstitial Mor	itoring Veeder Root TLS 300c		6/14	/2012	6/14/2013
Leak Detect - Tank	Automatic Tan	Automatic Tank Gauging Veeder Root TLS 300c				N/A
Overfill Prev Device	Ball Float Ven	Ball Float Vent Valve				N/A
Piping	Fiberglass Do	Fiberglass Double Wall Ameron				N/A
Spill Contain Device	Manhole Pre-r	Manhole Pre-manufactured OPW 1				N/A
Tank	Fiberglass Double Wall Owens Corning Brine Filled					

0087



LPC 1438185006 - Peoria County Trivoli / Page, Evelyn M. Trust 23907 W. Farmington Rd. Leaking UST Incident No. 20170100 Leaking UST Technical File

Right-to-Know Evaluation

The Bureau of Land site identified above has been reviewed. A check mark next to any one of the following criteria indicates further evaluation of the site is necessary.

CRITERIA:

- П Groundwater contamination is measured or modeled to exceed, within the setback zone or regulated recharge area of a potable Community Water Supply (CWS) well, or setback zone of a private well or non-CWS well, either TACO Tier 1 groundwater remediation objectives under Part 742, Appendix B, Table E or Class I groundwater standards under Part 620; or \Box Five or fewer properties \Box More than five properties
- Measured off-site groundwater contamination from volatile chemicals from the site where a release occurred poses a threat of indoor inhalation exposure above appropriate Tier 1 remediation objectives for the current use of the site; or □ Five or fewer properties □ More than five properties
- Π Soil contamination exceeding applicable remediation objectives for the soil component of the groundwater ingestion route is modeled to exceed, within the setback zone or regulated recharge area of a potable Community Water Supply (CWS) well, or setback zone of a private well or non-CWS well, either TACO Tier 1 groundwater remediation objectives under Part 742, Appendix B, Table E or Class I groundwater standards under Part 620; or \Box Five or fewer properties \Box More than five properties
- Γ Contaminated soil is measured off-site to exceed the appropriate Tier 1 remediation objectives based on the current use of the off-site property; or \Box Five or fewer properties \Box More than five properties
- Γ Measured off-site soil gas contamination from the site where the release occurred poses a threat of exposure above the appropriate Tier 1 remediation objectives for the current use of the site: or □ Five or fewer properties □ More than five properties
- Γ BOL refers a matter to the Division of Legal Counsel for enforcement under Section 43(a) of the Act; or
 - BOL refers a site to the Division of Legal Counsel for issuance of a seal order under Section 34(a) of the Act.

Comments:

 \square

E

- At least one of the above criteria is met and the above-identified site must be further evaluated.
- Insufficient information submitted to make an adequate RTK decision.

REVIEWER: EMI None of the above criteria are met and the above-identified site does not warrant any further evaluation

Project Manager Signature <u>2009 Hawbaku</u>

Date: 8/8/17

IEPA-DIVISION OF RECORDS MANAGEMENT

RELEASARIE

Electronics Engv Received ICTEAK's BRIGET ET 5/2020 AGENCY



1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397
BRUCE RAUNER, GOVERNOR
ALEC MESSINA, DIRECTOR

217/524-3300

CERTIFIED MAIL

7014 2120 0002 3286 1102

AUG 09 2017

Evelyn M. Page Trust Attention: Wayne Page 24 Rutledge Avenue Bartonville, Illinois 61607

Re: LPC #1438185006 -- Peoria County Trivoli / Page, Evelyn M. Trust 23907 West Farmington Road. Leaking UST Incident No. 20170100 -- NFR Letter Leaking UST Technical File

Dear Mr. Page:

The Illinois Environmental Protection Agency (Illinois EPA) has reviewed the Early Action Tier 1 Remediation Objectives Compliance Report submitted for the above-referenced incident. This information was dated March 30, 2017 and was received by the Illinois EPA on April 13, 2017. Citations in this letter are from the Environmental Protection Act (415 ILCS 5) (Act) and Title 35 of the Illinois Administrative Code (35 Ill. Adm. Code).

The Early Action Tier 1 Remediation Objectives Compliance Report and the Licensed Professional Engineer Certification submitted pursuant to Section 57.6 of the Act and 35 Ill. Adm. Code 734.135(d) indicate the remediation objectives have been met.

Based upon the certification by Penny L. Silzer, a Licensed Professional Geologist, and pursuant to Section 57.10 of the Act (415 ILCS 5/57.10), your request for a no further remediation determination is granted under the conditions and terms specified in this letter.

Issuance of this No Further Remediation Letter (Letter), based on the certification of the Licensed Professional Engineer, signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with; (2) all corrective action concerning the remediation of the occurrence has been completed; and (3) no further corrective action concerning the occurrence is necessary for the protection of human health, safety, and the environment. Pursuant to Section 57.10(d) of the Act, this Letter shall apply in favor of the following parties:

- 1. Evelyn M. Page Trust, the owner or operator of the underground storage tank system(s).
- 2. Any parent corporation or subsidiary of such owner or operator.
- 3. Any co-owner or co-operator, either by joint tenancy, right-of-survivorship, or any other party sharing a legal relationship with the owner or operator to whom the Letter is issued.

0090

- 4. Any holder of a beneficial interest of a land trust or inter vivos trust whether revocable or irrevocable.
- 5. Any mortgagee or trustee of a deed of trust of such owner or operator.
- 6. Any successor-in-interest of such owner or operator.
- 7. Any transferee of such owner or operator whether the transfer was by sale, bankruptcy proceeding, partition, dissolution of marriage, settlement or adjudication of any civil action, charitable gift, or bequest.
- 8. Any heir or devisee of such owner or operator.
- 9. An owner of a parcel of real property to the extent that this Letter applies to the occurrence on that parcel.

This Letter and all attachments, including but not limited to the Leaking Underground Storage Tank Environmental Notice, must be filed within 45 days of receipt as a single instrument with the Office of the Recorder or Registrar of Titles in the county in which the above-referenced site is located. This Letter shall not be effective until officially recorded by the Office of the Recorder or Registrar of Titles of the applicable county in accordance with Illinois law so it forms a permanent part of the chain of title for the above-referenced property. <u>Within 30 days of this Letter being recorded, an accurate and official copy of this Letter, as recorded, shall be obtained and submitted to the Illinois EPA.</u> For recording purposes, it is recommended that the Leaking Underground Storage Tank Environmental Notice of this Letter be the first page of the instrument filed.

CONDITIONS AND TERMS OF APPROVAL

LEVEL OF REMEDIATION AND LAND USE LIMITATIONS

- The remediation objectives for the above-referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, were established in accordance with the requirements of the Tiered Approach to Corrective Action Objectives (35 III. Adm. Code 742) rules.
- 2. As a result of the release from the underground storage tank system(s) associated with the abovereferenced incident, the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter, shall not be used in a manner inconsistent with the following land use limitation: There are no land use limitations.
- 3. The land use limitation specified in this Letter may be revised if:
 - a. Further investigation or remedial action has been conducted that documents the attainment of objectives appropriate for the new land use; and
 - b. A new No Further Remediation Letter is obtained and recorded in accordance with Title XVII of the Act and regulations adopted thereunder.

PREVENTIVE, ENGINEERING, AND INSTITUTIONAL CONTROLS

4. Preventive: None.

Engineering: None.

- Institutional: This Letter shall be recorded as a permanent part of the chain of title for the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter.
- 5. Failure to establish, operate, and maintain controls in full compliance with the Act, applicable regulations, and the approved corrective action plan, if applicable, may result in voidance of this Letter.

OTHER TERMS

- 6. Any contaminated soil or groundwater removed or excavated from, or disturbed at, the abovereferenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, must be handled in accordance with all applicable laws and regulations under 35 III. Adm. Code Subtitle G.
- 7. Further information regarding the above-referenced site can be obtained through a written request under the Freedom of Information Act (5 ILCS 140) to:

Illinois Environmental Protection Agency Attention: Freedom of Information Act Officer Division of Records Management - #16 1021 North Grand Avenue East Post Office Box 19276 Springfield, IL 62794-9276

- 8. Pursuant to 35 III. Adm. Code 734.720, should the Illinois EPA seek to void this Letter, the Illinois EPA shall provide notice to the owner or operator of the leaking underground storage tank system(s) associated with the above-referenced incident and the current title holder of the real estate on which the tanks were located, at their last known addresses. The notice shall specify the cause for the voidance, explain the provisions for appeal, and describe the facts in support of the voidance. Specific acts or omissions that may result in the voidance of this Letter include, but shall not be limited to:
 - a. Any violation of institutional controls or industrial/commercial land use restrictions;
 - b. The failure to operate and maintain preventive or engineering controls or to comply with any applicable groundwater monitoring plan;
 - c. The disturbance or removal of contamination that has been left in-place in accordance with the Corrective Action Plan or Completion Report;

Page 4

- d. The failure to comply with the recording requirements for the Letter;
- e. Obtaining the Letter by fraud or misrepresentation; or
- f. Subsequent discovery of contaminants, not identified as part of the investigative or remedial activities upon which the issuance of the Letter was based, that pose a threat to human health or the environment.

Submit an accurate and official copy of this Letter, as recorded, to:

Illinois Environmental Protection Agency Bureau of Land - #24 Leaking Underground Storage Tank Section 1021 North Grand Avenue East Post Office Box 19276 Springfield, IL 62794-9276

If you have any questions or need further assistance, please contact the Illinois EPA project manager, Carol Hawbaker, at 217/782-5713.

Sincerely,

A. Colantine

Stephen A. Colantino Acting Unit Manager Leaking Underground Storage Tank Section Division of Remediation Management Bureau of Land

SAC:CLH

Attachments: Leaking Underground Storage Tank Environmental Notice

 c: Allen Green, Midwest Environmental Consulting & Remediation Services, Inc. (electronic copy), <u>mdwstenv@frontier.com</u> BOL File

PREPARED BY:

Name: Wayne Page Evelyn M. Page Trust

Address: 23907 West Farmington Road Trivoli, Illinois 61569

RETURN TO:

- Name: Wayne Page Evelyn M. Page Trust
- Address: 24 Rutledge Avenue Bartonville, Illinois 61607

(THE ABOVE SPACE FOR RECORDER'S OFFICE)

LEAKING UNDERGROUND STORAGE TANK ENVIRONMENTAL NOTICE

THE OWNER AND/OR OPERATOR OF THE LEAKING UNDERGROUND STORAGE TANK SYSTEM(S) ASSOCIATED WITH THE RELEASE REFERENCED BELOW, WITHIN 45 DAYS OF RECEIVING THE NO FURTHER REMEDIATION LETTER CONTAINING THIS NOTICE, MUST SUBMIT THIS NOTICE AND THE REMAINDER OF THE NO FURTHER REMEDIATION LETTER TO THE OFFICE OF THE RECORDER OR REGISTRAR OF TITLES OF PEORIA COUNTY IN WHICH THE SITE DESCRIBED BELOW IS LOCATED.

Illinois EPA No.: 1438185006

Leaking UST Incident No.: 20170100

Evelyn M. Page Trust, the owner and/or operator of the leaking underground storage tank system(s) associated with the above-referenced incident, whose address is 24 Rutledge Avenue, Bartonville, Illinois 61607, has performed investigative and/or remedial activities for the site identified as follows:

- Legal Description or Reference to a Plat Showing the Boundaries: SE ¼ SEC 6-8-5E
 1.181 AC BEG 1839.72' W & 30' N of SE COR SEC 6: TH N 396' W 135.5' S 396' E
 135.5' TO POB (EXC ROUTE 116 ROW AS DES C PER DOC #96-13383)
- 2. Common Address: 23907 West Farmington Road, Trivoli, Illinois 61569
- 3. Real Estate Tax Index/Parcel Index Number: 1506400004
- 4. Site Owner: Evelyn M. Page Trust
- 5. Land Use Limitation: There are no land use limitations.
- 6. See the attached No Further Remediation Letter for other terms.

ELECTIONALS FEINER REGENSE NOTAK'S BRIGT E (75/2020 AGENCY



 1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397

 BRUCE RAUNER, GOVERNOR

 ALEC MESSINA, DIRECTOR

RECORDING REQUIREMENTS FOR NO FURTHER REMEDIATION LETTERS

Introduction

The Illinois Environmental Protection Agency's (Illinois EPA) Bureau of Land/Leaking Underground Storage Tank Section issues a No Further Remediation (NFR) Letter after a demonstration of compliance with Title XVI of the Environmental Protection Act and applicable regulations is made. The NFR Letter signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with, (2) all corrective action concerning the remediation of the occurrence has been completed, and (3) no further corrective action concerning the occurrence is necessary so long as the site is used in accordance with the terms and conditions of the NFR Letter.

Significance

When properly recorded, the NFR Letter holds legal significance for all applicable parties outlined at Section 57.10(d) of the Environmental Protection Act. (See 415 ILCS 5/57.10(d).) If not properly recorded, the Illinois EPA *will* take steps to void the NFR Letter in accordance with the regulations.

Duty to Record

The duty to record the NFR Letter is *mandatory*. You *must* submit the NFR Letter, with a copy of any applicable institutional controls proposed as part of a corrective action completion report, to the Office of the Recorder or the Registrar of Titles of the county in which the site is located *within 45 days after receipt of the NFR Letter*. You must record the NFR Letter and any attachments. The NFR Letter shall be filed in accordance with Illinois law so that it forms a permanent part of the conditions and terms of approval including level of remediation; land use limitations; and preventive, engineering, and institutional controls. A certified or otherwise accurate and official copy of the NFR Letter and any attachments, as recorded, must be submitted to the Illinois EPA. Failure to record the NFR Letter in accordance with the regulations will make the NFR Letter voidable.

For More Information

Please refer to the Tiered Approach to Corrective Action Objectives (TACO) fact sheet entitled *No Further Remediation Letters*, which is available from the Illinois EPA by calling (217) 524-3300 or by accessing it on the Illinois EPA Web site at

http://www.epa.illinois.gov/topics/cleanup-programs/taco/fact-sheets/no-further-remediationletters/index.

4302 N. Main St., Rockford, IL 61103 (815)987-7760 595 S. State, Elgin, IL 60123 (847)608-3131 2125 S. First St., Champoign, IL 61820 (217)278-5800 2009 Mall St., Collinsville, IL 62234 (618)346-5120

0095

ELECTIVOIDSFEINDU PRODENDAEINCTANL'S PRODEECUTIONAGENCY



1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397BRUCE RAUNER, GOVERNORALEC MESSINA, DIRECTOR

217/524-3300

CERTIFIED MAIL

2014 5750 0005 359P 7705

AUG 09 2017

Evelyn M. Page Trust Attention: Wayne Page 24 Rutledge Avenue Bartonville, Illinois 61607


Re: LPC #1438185006 -- Peoria County Trivoli / Page, Evelyn M. Trust 23907 West Farmington Road. Leaking UST Incident No. 20170100 -- NFR Letter Leaking UST Technical File




Dear Mr. Page:

The Illinois Environmental Protection Agency (Illinois EPA) has reviewed the Early Action Tier 1 Remediation Objectives Compliance Report submitted for the above-referenced incident. This information was dated March 30, 2017 and was received by the Illinois EPA on April 13, 2017. Citations

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Contracte items 1, 2, and 3. Also complete item 4 f Restricted Delivery in a lifed. Print your name and soft of s on the reverse so that we can nour the d to you. Attach to can it it it is an off the mailpiece, or on the soft of the units. Article Addressed to: 	A. Signature
Evelyn M. Page Trust	20170100 SelCH
24 Butledge Avenue Barton ville, SC 61607	Serice Type Certified Mail Express Mail Registered Return Receipt for Merchandise Insured Mail C.O.D.
	4. Restricted Delivery? (Extra Fee)
2. Article Number (Transfer from service label) 7014 20096	0 0002 3286 1102
PS Form 3811, February 2004 Domestic Ret	urn Receipt 102595-02-M-1540







ELECTIVOIDSFEIND/ PREOPINAGENCTAAL'S PRIOTECT \$12080 AGENCY

 1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397

 BRUCE RAUNER, GOVERNOR

 ALEC MESSINA, DIRECTOR

217/524-3300

CERTIFIED MAIL

2014 5150 0005 358P 1105

AUG 09 2017

Evelyn M. Page Trust Attention: Wayne Page 24 Rutledge Avenue Bartonville, Illinois 61607

Re: LPC #1438185006 -- Peoria County Trivoli / Page, Evelyn M. Trust 23907 West Farmington Road. Leaking UST Incident No. 20170100 -- NFR Letter Leaking UST Technical File

EPA-DANSION OF RECORDS MANAGELENT

AUG 28 2017

REVIEWER JRM

Dear Mr. Page:

The Illinois Environmental Protection Agency (Illinois EPA) has reviewed the Early Action Tier 1 Remediation Objectives Compliance Report submitted for the above-referenced incident. This information was dated March 30, 2017 and was received by the Illinois EPA on April 13, 2017. Citations in this letter are from the Environmental Protection Act (415 ILCS 5) (Act) and Title 35 of the Illinois Administrative Code (35 Ill. Adm. Code).

The Early Action Tier 1 Remediation Objectives Compliance Report and the Licensed Professional Engineer Certification submitted pursuant to Section 57.6 of the Act and 35 Ill. Adm. Code 734.135(d) indicate the remediation objectives have been met.

Based upon the certification by Penny L. Silzer, a Licensed Professional Geologist, and pursuant to Section 57.10 of the Act (415 ILCS 5/57.10), your request for a no further remediation determination is granted under the conditions and terms specified in this letter.

Issuance of this No Further Remediation Letter (Letter), based on the certification of the Licensed Professional Engineer, signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been completed; and (2) all corrective action concerning the remediation of the occurrence has been completed; and (3) no further corrective action concerning the occurrence is necessary for the protection of human health, safety, and the environment. Pursuant to Section 57.10(d) of the Act, this Letter shall apply in favor of the following parties:

- 1. Evelyn M. Page Trust, the owner or operator of the underground storage tank system(s).
- 2. Any parent corporation or subsidiary of such owner or operator.
- 3. Any co-owner or co-operator, either by joint tenancy, right-of-survivorship, or any other party sharing a legal relationship with the owner or operator to whom the Letter is issued.

- 4. Any holder of a beneficial interest of a land trust or inter vivos trust whether revocable or irrevocable.
- 5. Any mortgagee or trustee of a deed of trust of such owner or operator.
- 6. Any successor-in-interest of such owner or operator.
- 7. Any transferee of such owner or operator whether the transfer was by sale, bankruptcy proceeding, partition, dissolution of marriage, settlement or adjudication of any civil action, charitable gift, or bequest.
- 8. Any heir or devisee of such owner or operator.
- 9. An owner of a parcel of real property to the extent that this Letter applies to the occurrence on that parcel.

This Letter and all attachments, including but not limited to the Leaking Underground Storage Tank Environmental Notice, must be filed within 45 days of receipt as a single instrument with the Office of the Recorder or Registrar of Titles in the county in which the above-referenced site is located. This Letter shall not be effective until officially recorded by the Office of the Recorder or Registrar of Titles of the applicable county in accordance with Illinois law so it forms a permanent part of the chain of title for the above-referenced property. Within 30 days of this Letter being recorded, an accurate and official copy of this Letter, as recorded, shall be obtained and submitted to the Illinois EPA. For recording purposes, it is recommended that the Leaking Underground Storage Tank Environmental Notice of this Letter be the first page of the instrument filed.

CONDITIONS AND TERMS OF APPROVAL

LEVEL OF REMEDIATION AND LAND USE LIMITATIONS

- The remediation objectives for the above-referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, were established in accordance with the requirements of the Tiered Approach to Corrective Action Objectives (35 III. Adm. Code 742) rules.
- 2. As a result of the release from the underground storage tank system(s) associated with the abovereferenced incident, the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter, shall not be used in a manner inconsistent with the following land use limitation: There are no land use limitations.
- 3. The land use limitation specified in this Letter may be revised if:
 - a. Further investigation or remedial action has been conducted that documents the attainment of objectives appropriate for the new land use; and
 - b. A new No Further Remediation Letter is obtained and recorded in accordance with Title XVII of the Act and regulations adopted thereunder.

PREVENTIVE, ENGINEERING, AND INSTITUTIONAL CONTROLS

4. Preventive: None.

Engineering: None.

Institutional: This Letter shall be recorded as a permanent part of the chain of title for the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter.

5. Failure to establish, operate, and maintain controls in full compliance with the Act, applicable regulations, and the approved corrective action plan, if applicable, may result in voidance of this Letter.

OTHER TERMS

- 6. Any contaminated soil or groundwater removed or excavated from, or disturbed at, the abovereferenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, must be handled in accordance with all applicable laws and regulations under 35 Ill. Adm. Code Subtitle G.
- 7. Further information regarding the above-referenced site can be obtained through a written request under the Freedom of Information Act (5 ILCS 140) to:

Illinois Environmental Protection Agency Attention: Freedom of Information Act Officer Division of Records Management - #16 1021 North Grand Avenue East Post Office Box 19276 Springfield, IL 62794-9276

- 8. Pursuant to 35 III. Adm. Code 734.720, should the Illinois EPA seek to void this Letter, the Illinois EPA shall provide notice to the owner or operator of the leaking underground storage tank system(s) associated with the above-referenced incident and the current title holder of the real estate on which the tanks were located, at their last known addresses. The notice shall specify the cause for the voidance, explain the provisions for appeal, and describe the facts in support of the voidance. Specific acts or omissions that may result in the voidance of this Letter include, but shall not be limited to:
 - a. Any violation of institutional controls or industrial/commercial land use restrictions;
 - b. The failure to operate and maintain preventive or engineering controls or to comply with any applicable groundwater monitoring plan;
 - c. The disturbance or removal of contamination that has been left in-place in accordance with the Corrective Action Plan or Completion Report;

¥

Page 4

- d. The failure to comply with the recording requirements for the Letter;
- e. Obtaining the Letter by fraud or misrepresentation; or
- f. Subsequent discovery of contaminants, not identified as part of the investigative or remedial activities upon which the issuance of the Letter was based, that pose a threat to human health or the environment.

Submit an accurate and official copy of this Letter, as recorded, to:

Illinois Environmental Protection Agency Bureau of Land - #24 Leaking Underground Storage Tank Section 1021 North Grand Avenue East Post Office Box 19276 Springfield, IL 62794-9276

If you have any questions or need further assistance, please contact the Illinois EPA project manager, Carol Hawbaker, at 217/782-5713.

Sincerely,

tephen A. Colantine

Stephen A. Colantino Acting Unit Manager Leaking Underground Storage Tank Section Division of Remediation Management Bureau of Land

SAC:CLH

Attachments: Leaking Underground Storage Tank Environmental Notice

c: Allen Green, Midwest Environmental Consulting & Remediation Services, Inc. (electronic copy), <u>mdwstenv@frontier.com</u> BOL File

PREPARED BY:

Name: Wayne Page Evelyn M. Page Trust

Address: 23907 West Farmington Road Trivoli, Illinois 61569

RETURN TO:

- Name: Wayne Page Evelyn M. Page Trust
- Address: 24 Rutledge Avenue Bartonville, Illinois 61607

(THE ABOVE SPACE FOR RECORDER'S OFFICE)

LEAKING UNDERGROUND STORAGE TANK ENVIRONMENTAL NOTICE

THE OWNER AND/OR OPERATOR OF THE LEAKING UNDERGROUND STORAGE TANK SYSTEM(S) ASSOCIATED WITH THE RELEASE REFERENCED BELOW, WITHIN 45 DAYS OF RECEIVING THE NO-FURTHER REMEDIATION LETTER CONTAINING THIS NOTICE, MUST SUBMIT THIS NOTICE AND THE REMAINDER OF THE NO FURTHER REMEDIATION LETTER TO THE OFFICE OF THE RECORDER OR REGISTRAR OF TITLES OF PEORIA COUNTY IN WHICH THE SITE DESCRIBED BELOW IS LOCATED.

Illinois EPA No.: 1438185006

Leaking UST Incident No.: 20170100

Evelyn M. Page Trust, the owner and/or operator of the leaking underground storage tank system(s) associated with the above-referenced incident, whose address is 24 Rutledge Avenue, Bartonville, Illinois 61607, has performed investigative and/or remedial activities for the site identified as follows:

- Legal Description or Reference to a Plat Showing the Boundaries: SE ¼ SEC 6-8-5E
 1.181 AC BEG 1839.72' W & 30' N of SE COR SEC 6: TH N 396' W 135.5' S 396' E
 135.5' TO POB (EXC ROUTE 116 ROW AS DES C PER DOC #96-13383)
- 2. Common Address: 23907 West Farmington Road, Trivoli, Illinois 61569
- 3. Real Estate Tax Index/Parcel Index Number: 1506400004
- 4. Site Owner: Evelyn M. Page Trust
- 5. Land Use Limitation: There are no land use limitations.
- 6. See the attached No Further Remediation Letter for other terms.

ELECTION OF STEIN VIRCOUVAGE DIEAKS BRIGETEICS/ROBDAGENCY



 1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397

 BRUCE RAUNER, GOVERNOR

 ALEC MESSINA, DIRECTOR

RECORDING REQUIREMENTS FOR NO FURTHER REMEDIATION LETTERS

Introduction

The Illinois Environmental Protection Agency's (Illinois EPA) Bureau of Land/Leaking Underground Storage Tank Section issues a No Further Remediation (NFR) Letter after a demonstration of compliance with Title XVI of the Environmental Protection Act and applicable regulations is made. The NFR Letter signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with, (2) all corrective action concerning the remediation of the occurrence has been completed, and (3) no further corrective action concerning the occurrence is necessary so long as the site is used in accordance with the terms and conditions of the NFR Letter.

Significance

When properly recorded, the NFR Letter holds legal significance for all applicable parties outlined at Section 57.10(d) of the Environmental Protection Act. (See 415 ILCS 5/57.10(d).) If not properly recorded, the Illinois EPA *will* take steps to void the NFR Letter in accordance with the regulations.

Duty to Record

The duty to record the NFR Letter is *mandatory*. You *must* submit the NFR Letter, with a copy of any applicable institutional controls proposed as part of a corrective action completion report, to the Office of the Recorder or the Registrar of Titles of the county in which the site is located *within 45 days after receipt of the NFR Letter*. You must record the NFR Letter and any attachments. The NFR Letter shall be filed in accordance with Illinois law so that it forms a permanent part of the conditions and terms of approval including level of remediation; land use limitations; and preventive, engineering, and institutional controls. A certified or otherwise accurate and official copy of the NFR Letter and any attachments, as recorded, must be submitted to the Illinois EPA. Failure to record the NFR Letter in accordance with the regulations will make the NFR Letter voidable.

For More Information

Please refer to the Tiered Approach to Corrective Action Objectives (TACO) fact sheet entitled *No Further Remediation Letters*, which is available from the Illinois EPA by calling (217) 524-3300 or by accessing it on the Illinois EPA Web site at

http://www.epa.illinois.gov/topics/cleanup-programs/taco/fact-sheets/no-further-remediationletters/index.

4302 N. Main St., Rodcford, IL 61103 (815)987-7760 595 S. State, Bgin, IL 60123 (847)608-3131 2125 S. First St., Champaign, IL 61820 (217)278-5800 2009 Mall St., Collinsville, IL 62234 (618)346-5120 9511 Harrison St., Des Plaines, IL 60016 (847)294-4000 412 SW Washington St., Suite D, Peoria, IL 61602 (309)671-3022 2309 W. Main St., Suite 116, Marion, IL 62959 (618)993-7200 100 W. Randolph, Suite 10-300, Chicago, IL 60601

Myers, Dave

From: Sent: To: Subject: Attachments: mecrs <mdwstenv@frontier.com> Thursday, November 16, 2017 11:53 AM Myers, Dave [External] Re: Lust # 20170100 Evelyn Page Trust nfr recording Untitled_11162017_115304.pdf


Dave, Here is the recorded NFR.

From: Myers, Dave
Sent: Wednesday, November 15, 2017 3:48 PM
To: Midwest Environmental (mdwstenv@frontier.com)
Subject: Lust # 20170100 Evelyn Page Trust nfr recording

Al, the Agency has yet to receive a copy of the recorded nfr letter for this site. I was able to talk to Wayne Page, who is now in Florida for the winter and stated he did record the letter. He referred me to you, so could you please forward a copy of the recorded nfr letter so we can update our database to show the letter as properly recorded. Thanks.

Dave Myers, IEPA

State of Illinois - CONFIDENTIALITY NOTICE: The information contained in this communication is confidential, may be attorney-client privileged or attorney work product, may constitute inside information or internal deliberative staff communication, and is intended only for the use of the addressee. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify the sender immediately by return e-mail and destroy this communication and all copies thereof, including all attachments. Receipt by an unintended recipient does not waive attorney-client privilege, attorney work product privilege, or any other exemption from disclosure.



ECH

The appearance of some of the images

following this page is due to

Poor Quality Original Documents

and not the scanning or filming processes.

Com Microfilm Company (217) 525-5860

distantibacipeorDecador



PREPARED BY:

•

- Name: Wayne Page Evelyn M. Page Trust
- Address: 23907 West Farmington Road Trivoli, Illinois 61569

RETURN TO:

Name: Wayne Page Evelyn M. Page Liust

Address: 24 Rutledge Avenue Battonville, Illinois 61607 Recording Fee: \$54.00 Rental Housing Fee: \$9.00

Total Fee: \$53.00 Steve Sonnensker County Clerk, Pearia, I

RUE

(THE ABOVE SPACE FOR RECORDER'S OFFICE)

LEAKING UNDERGROUND STORAGE TANK ENVIRONMENTAL NOTICE.

THE OWNER AND/OR OPTRATOR OF THE LEAKING ENDERGROUND STORAGE TANK SYSTEM(S) ASSOCIATED WHILL HE RELEAST REFERENCED BELOW, WITHIN 45 DAYS OF RECEIVING THE NO FURTHER REMEDIATION LETTER CONTAINING THIS NOTICE, MUST SUBMIT THIS NOTICE AND THE REMAINDER OF THE NO FURTHER REMEDIATION LETTER TO THE OFFICE OF THE RECORDER OR REGISTRAR OF TITLES OF PEORIA COUNTY IN WHICH THE SITE DESCRIBED BELOW IS LOCATED.

lilmoix EPA/Not: 1438185005

Leaking UST Incident No.: 20170100

Evelyn M. Page Trust, the owner and/or operator of the leaking underground storage tank system(s) associated with the above referenced incident, whose address is 24 Ruiledge Avenue, Bartonville, Illinois 61607, has performed incistentive and 19 remedial activities for the site identified as follows:

- Legal Description or Reference to a Plat Showing the Boundaries: SE 14 SFC b 8-5F L181 AC BEG 1839 72° W & 30° N of SF COR SEC 6; TH N 396° W 135 5° S 396° E L35.5° TO POB (FAC ROUTE 116 ROW AS DES C PER DOC #96 13383)
- 2 Common Address: 23907 West Fainington Road, Trivoli, Illinois 64569
- 3. Real Estate Tax Indes/Parcel Index Number, 1506400004
- 4. Site Owner Evelyn M. Page Trust
- 5 Land Use Einstation: There are no find use initiations.
- 6 See the attached No Further Repudiation Letter for other terms

Leaking Underground Storage Tank Environmental Nonce-



•

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

2173212464

216 09 2017

Evelon M. Page Trust Arcorologi Wayne Pag 24 Kurle for Avenu Biological University (27

C. 1418288 (1997) C. C. C.
 Frisch, P. Barris, M. Barris, M. Barris, 20097 West Faramogra Road
 Barris, F. S. Barris, R. 2007 (1979) (1979) St. B. F. Strig, E. Strig, S. B. F. Strig, 2017) (1979).

CERTIFIED MML

1914 - 1 137 B B 1107

CORDED

-

.1

AN END OF

(Fighther Account of Real control of Onjects (see complete to Report 1997) in the control of second seco

Busilian intercentication of PCL ST, SM more spectral Profession PCC to the extinct term Subject TREPP ACCURATE BUSINESS DO THE CONTRACT THE CONTRACT DEPOSITION transferra Contract Profession of the State PCC sector.

(a) A second frequencies of the transmission of the transmissio

How Mangel And Construction and the state of the state of

A construction provides the second second

(2) A second se second sec

• • •

· · · ·

Page 2

1

- 4 Any holder of a beneficial interest of a land trust or intervivos trust whether revocable or irrevocable
- 5. Any mortgagee or trustee of a deed of trust of such owner or operator.
- 6. Any successor-in-interest of such owner or operator.
- Any transferee of such owner or perator whether the transfer was by sale, bankruptcy proceeding, partition, dissolution of matriage, sentement or adjudication of any civil action charitable gift, or bequest
- 8. Any here or devisee of such owner or operator
- An owner of a parcel of real property to the extent that this Letter applies to the occurr mee on that parcel.

This Letter and all attachments, including but not limited to the Leaking Underground Storage Tank. Environmental Notice, must be filed within 45 days of receipt as a ongle instrument with the Office of the Recorder or Registrar of Tules in the county in which the above-referenced site is located. This Leiter shall not be effective until officially recorded by the Office of the Recorder or Registrar of Titles of the applicable county in accordance with Illinois laws, a forms a permanent part of the chain of files of the above referenced property. Within Mideys of U site the angle coulded an accurate, and officially option this letter, as recorded, shall by the active source to the Illinois EPA. For recording purposes, it is recommended that the Leaking Underground Storage Tank Environmental Notice of this Letter by the first page of the instrument filed.

CONDITIONS AND TERMS OF APPROVAL

UND OF REMEDIATION AND LAND USE LIMITATIONS.

- The reincidiation objectives for the above referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, were established in necordance with the requirements of the Tack Expression Corrective Action Objectives 35 III Ador. Code 742 (rules).
- 2 As a result of the release from the underground storage tank system(s) associated with the above-referenced incident, the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank havinomental Notice of this fetter, shall not be used in a manner inconsistent with the following land use himitation. There are no land use limitations.
- 3 The land use functation specified in this Letter may be revised if
 - a. Further investigation or remodul action has been conducted that dreaments the attainment of objectives appropriate for the new land use, and
 - b. A new No-E-rither Renned atom Feith is obtained and recorded make induces with Title XNR of the Act and regulations adopted there under

_____ -----

.

4

.

Pere 3

~

PLEVENDE ENGELENG CORNEL FORM CONFIGS

1 Proventise $N_{\rm eff}$

English rolg - Nord

Insurnoval - This Leave that be recorded as a procession matching channel to be run of the nervolabove referenced with the problem. Index in reference and call casion U.L. States I. Hereit K. K. S. S. States and S. S. S.

1 . • . Net a prime a compared concerned proved a contract of a plan temperation may use the effective of 1

company and

- (v) v contratenation of the providence of the statement of the statement of the Region of the statement of solution of the statement of the statement of the Region of An experimentation of the second t.
- 1.... $\tau_{\rm eff}$ is the first second second parameter μ is set induction to identific a strain of Reason
 - The east transmitted Herediser Agency Auction of collocal later cance Accore-Divise in these lists Marcoling all marcol 1921 North Grand Assault ist. 书写中的公书云 电子 Span, faile Borth (1977)
 - B) wound (15.6) which is a first product of the second state of
 - A CAMPAN AND A
 - $= \Lambda^{\alpha_1} \sqrt{2\pi} e^{-i\omega_1 \omega_2} e^{-i\omega_2 \omega_2} e^{-i\omega_2 \omega_2} \sqrt{2\pi} e^{-i\omega_2 \omega_2} e^{-i\omega$
 - $\frac{1}{2} = \frac{1}{2} \left(\frac{1}{2} \frac{1}{2} + \frac{1}{2} \frac{1}{2} \frac{1}{2} + \frac{1}{2} \frac{1}{2} \frac{1}{2} \frac{1}{2} \frac{1}{2} + \frac{1}{2} \frac$ · · · · · · · 16
 - (2) Standard and the first of the standard standard standard standard standard standards and the standard standard standard standards.

Page 4

- d. The failure to comply with the recording requirements for the Letter.
- e Obtaining the Letter by fraud or misrepresentation; or
- f Subsequent discovery of contaminants instidentified as part of the investigative or remedial activities upon which the oscionce of the Leiter was based, that pose a threat to hungin health or the environment.

Subout an accurate and official or py of this Leuce, as recorded to

Illnois Environmental Protection Agency Bureau of Land - #24 Feaking Underground Storage Tank Section 1021 North Grand Avenue Last Post Office Box 19276 Springfield, IL 62794-9276

If you have any questions or need further assistance please contact the IIIm as EPA product manager. Carol Hawbaker, at 217/782-5713

Sec. 128

Agrica H. Constance Stephen A. Columbino

Acting Unit Manager Leaking Unit Manager Distsion of Remediation Management Bureau of Land

SACICLH

Attachments - Reasong Endersteand Storage Tark Er vironna nur Notice.

 Allen Green, Midwest Environmental Consulting & Remediation Services. Inc. (Cleatronic copy) <u>indwsteny@frognacicom</u> BOL File

Electronic Filing Reader Charles Charles Street 11/5/2020

Reviewer: LPC # & County:	Melissa Owens 1438185006 / Peoria	Queue Date: Subject to Program:	<u>4/2/18</u> 734		eview Dat awbaker	te: <u>6/29/18</u>		
Site Name:	Trivoli / Evelyn M. Page Trus	.t						
LUST IncidentClaim #	2017010069179	Bi	ling Period:	2/7/17	to	5/17/17		
	xxxxxxxxxx Site Class.:							
Free Product:	Site Invest.:	Correc	tive Action:					
Amount requested for	Early Action:		•	23,488.	45	······		
SUB TOTAL:				\$23,488.	45			
Less: STANDARD DEI	DUCTIBLE:		:	(5,000.0		_		
Less: DEDUCTIONS:				(,			
cons mat-adj 66 miles fr	rom .58/mile to 0.535/mile			(2.97))			
cons mat-cut postage; la	acks doc			(7.20)	(7.20)			
cons pers-adj 2.75 hrs F	Fetterolf from proj man 112.34	per hr to 68.83 per hr		(144.8)	2)			
cons pers-adj personne	l per Brian's sheet			(774.3	9)			
rem and disp-drum disp	after 59 days			(915.0	0)			
UST removal-lacks doc	and not bid correctly			(8,951.8	31)			
handling-no proof of pay	yment			(0.86)			
SUMMARY D. NFR DATE OPT-IN DAT	8/9/17	- Total Amount	Due:	\$7,691.	40			

Payee:	Evelyn Page Trust	Facility: Page, Evelyn M. Trust
Attention:	c/o Midwest Environmental Consulting and	Address: 23907 West Farmington Road
	Remediation Services, Inc.	City/State: Trivoli, IL 61569
Address:	22200 Illinois Route 9, P.O. Box 614	County: Peoria
City/St./Zip:	Tremont, IL 61568	
	0111	

TO:	Greg Dunn
FROM:	Melissa Owens

Initial Review Date: 6/29/18 Project Manager: Hawbaker Subject to Program: 734

LPC # & County:	1438185006 / Peor	pria
Site City & Name:	Trivoli / Evelyn M. F	Page Trust
Site Address:	23907 West Farmir	ington Road
LUST Incident-Claim #	2017010069179	
Queue Date:	4/2/2018	
LUST / FISCAL FILE		_

The above referenced facility's consultants/contractors submission regarding invoices and billings has been reviewed.

The consultant/contractor	or in this billing pack	age is:	Midwest Enviror	nmental Consult	ting & Remediati	ion Services, Inc.
Queue Date:	4/2/18			Revised	120 Day Date: 1 120 Day Date:	······································
IEMA:	2/7/17				ays After IEMA:	<u> </u>
OSFM: _					45 Day Report:	
F.P. Discovered:			45 Days After	Free Product v	vas Discovered:	
E.A. Ext Date:			Da	te of Site Class	. Comp. Report:	
NFR Date:	8/9/17		Dai	te of Site Invest	. Comp. Report:	
Opt-In Date:			Or Stage of	of Site Invest. w	ork being billed:	
Opt-In as New Owner:						
# of Eligible Tanks:	11		10,000 gallon di	iesel		
Tank Pull:		Planned:			Not Planned:	
The <u>Billing Period</u> for t	his claim covers:		2/7/17	to	5/17/17	
The Amount Requeste	<u>d</u> in this billing pack	age is:	-	\$23,488.45	_	
The Budget Amount A	pproved for this site	e is:	-		-	
The Deductible Applie	<u>d</u> to this billing pack	age is:	-	(\$5,000.00)	-	
Early Action:	xxxxxxxxxx	Site Class .:		Low Priority:	-	High Priority:
Free Product:		Site Invest .:		Ce	orrective Action:	

MANDATORY DOCUMENTS:

x	1. Payment Certification Form.
x	2. Owner/Operator & Professional Engineer/Geologist Billing Certification Form.
x	3. Private Insurance Coverage Questionnaire & Affidavit Forms.
x	Federal Taxpayer Identification Number &/or W-9 Form(s):
x	5. Copy of OSFM Eligibility / Deductibility Letter.
x	6. Women / Minority Business Enterprise Form.

Owens, Melissa

From: Sent:	mecrs <mdwstenv@frontier.com> Friday, July 20, 2018 10:22 AM</mdwstenv@frontier.com>
To:	Owens, Melissa
Subject:	[External] Re: Evelyn Page Trust 20170100 early action claim
Attachments:	Untitled_07202018_101754.pdf
Follow Up Flag:	Follow up
Flag Status:	Flagged

Melissa,

I have previously sent you paperwork regarding points #1 and #5. I asked the tank removal contractor for every invoice they had regarding point #2 (removal, backfill, drums, etc.) and those are included in the attachment. Also included in the attachment are updated MECRS invoices for point #3 with names. In regards to point #4, I have been told by more than one IFPA project manager that the postage receipts are not needed because the fact that you received the mail from the USPS is proof of payment and what we paid is on the postage sticker of the envelope. If you need anything else or have any questions please let us know. Thanks,

MECRS From: Owens, Melissa Sent: Tuesday, July 10, 2018 7:53 AM To: mecrs Subject: Evelyn Page Trust 20170100 early action claim

Good morning,

I'm working on the above referenced claim, and I discussed it with Brian on Friday afternoon.

For Remediation and Disposal, can you please provide the invoice for the \$915 for drum disposal? Brian also said
 I need to request a legible copy of the manifest.

 $\frac{\alpha S k}{\beta V \sqrt{2}}$ For the UST Removal, Brian said the work was not bid properly. He said we can pay the H rate plus the backfill and drums, we will need invoices.

- \checkmark 3. Can you please provide the name of those doing the work on the invoices?
 - (4) I don't see a receipt for postage. We will need the receipt in order to reimburse the cost and pay handling.
- \sim 5. I don't see proof of payment for PDC Laboratories. We can't pay handling without it.

Please provide the requested documentation by July 23rd.

Thanks,

Melissa Owens

State of Illinois - CONFIDENTIALITY NOTICE: The information contained in this communication is confidential, may be attorney-client privileged or attorney work product, may constitute inside information or internal deliberative staff communication, and is intended only for the use of the addressee. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify the sender immediately by return e-mail and destroy this communication and all copies thereof, including all attachments. Receipt by an unintended recipient does not waive attorney-client privilege, attorney work product privilege, or any other exemption from disclosure.

AN EMPLOYEE OWNED COMPANY

OIL MARKETING EQUIPMENT, Inc. 1-800-447-2611 850 Brenkman Drive, Pekin, IL 61554 Sold To: Wayne Page Evelyn Page Trust 24 Rutledge Ave. Peoria, IL 61607

Confirm To: Customer PO:

Tank Romoval Breekdown:

DOT Drums, oil dry, removal material (tax Incl.)	= \$1,558.44
Labor 67.976 x 82.00	= \$ 5,574.06
Excevation (Incl mob/demob)	= \$ 3,997.50
Trucking and backfill 74 yds	= \$ 1,850.00
OSFM Permit	=\$ 205.00
Dumpster and tank disposal	=\$ 755.00
Mileoge 100 x .90	= <u>\$ 90.00</u>
Remove Tank as per Bid	= \$14,030.00

Involce

Involce Date: 3/31/2017 Involce Number: 0113973-INbrk Job Number: 0050413 Customer Number: 0005326 Salesperson: PB

Ship To: First Student 23907 West Farmington Rd. Farmington, IL 61531

Terms: Net 10

HITATE \$ 3942.33 UST

UST BACKFILC 68.07 TON-1.5 = 45.38 M HRATE \$5.03 = 1135.86

Joint & 5078.19

Thank you for your Business, Please remit to: 850 Brenkman Drive - Pekin, IL 61554

We accept VISA and Mastercard. Processing fees apply to installation invoices. 1 1/2% (18% Annual) Finance Charge will be added after 45 days.

All products and components carry the manufacturer's warranty which is passed on to purchaser according to manufacturer's policy. No other warranties are either expressed or implied.

Net Invoice: 14,030.00 Sales Tax: 0.00 Shipping & Handling: 0.60

Involce Totel:

14,030.00

0114

Page: 1

	WINSTEAD EXCAVATING Box 256 McLean, Illinois 61754 Phone (309) 825-487	4	
	4	<u>uuh 13</u> ,	17
Name	Consis and alter		
Address			na Arandinatan Inama Ar
City			
-	Fishandore	ten wet	2
DATE	DESCRIPTION OF WORK	HOURS	AMOUNT
Marsh 4.	17 Marin 225 Latter 100,54	4	40000
	- and the second		70 00
7	225 colde 1407 th	8	1420 201
18	1. 1. 11	9	1460 00
11	1. 421. 7 0 7 5 2 24	4	40000
		·	25000
·····			
	Dete Recti 3-17		
	Acet	506(74	Intern
	LET 70/02	1	ST DU
		IVE	
	titunelane	- ' ''	
	FISTStuden	-	
	1-2050413-002]	
		1	
	FINE OK E. T	<u> </u>	
		···	
Ţ			

MONTHLY SERVICE CHARGE WILL BE ADDED TO UNPAID ACCOUNTS AFTER 30 DAYS. THIS IS AN ANNUAL PERCENTAGE RATE OF 18%

.

÷

Rask Transportation

1880 State Rt 167

Invoice

	WEEK END	ÍNVOICE #
İ	3/10/2017	91120

BILL TO

Illinois Oil Marketing 850 Brenkman Dr. Pekin, IL 61564

BOL	DATE	QUANTITY	RATE	DESC	RIPTION	CLASS	AMOU
11793978	3 10 2017	21.16	8.95	1" down	494 - 4 4 a - 4 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a - 4 a -	***	189.38
Trucking 11794000	3/10/2017	21.16 21.8		Milcs - Valley to Farmington 1" down		Niles ***	137.54 195.11
Trucking 55202 Trucking 55203 Trucking 55204 Trucking	3/10/2017 3/10/2017 3/10/2017	21.8 23.54 22.17 22.17 22.36 22.36	4.80 4.25 4.80 4.25 4.80	Miles - Valley to Farmington Weast fill sand Miles - Weast to Farmington Weast fill sand Miles - Weast to Farmington Miles - Weast to Farmington	Date Front M-19-17 had 17 Prove AUDITATION AUDITATI	Niles	141.70 112.99 100.05 106.42 94.22 107.33 95.03
	JE UPON ECEIPT			an manana kata kata kata kata kata kata kata	Total		\$1,279.77
โดงการของสามาร์และสามารถสามารถสามารถ	*****	R BUSINESS!!		A 2012 - FARL HUIL HUIL HUIL ANN ANN ANN ANN ANN ANN ANN ANN ANN AN	Balance Due	9440 XIII X. III AN	\$1,279.77

	Phone #	Fax #
*	309-879-2221	309-879-3206

WASTE MANAGEMENT			Ci Se Inv	ustomer II Istomer Nam Prvice Period: Voice Date: Voice Number	e:	ILLIN	Page 1 o - 12956-7300 NOIS OIL MARKETI 13/01/17-03/15/ 03/16/20 3313731-2070
n Maritani di	н						
Visit wm.c	om	04	1/14/2	017		\$197.	93
statements, marege your accour schedules, pay your invoice or sch	r, vew norcay ractula a pictup	within your cont monthly late ch	of the invoiced err bactual terms, yo arge of 2.5% of	u may be charge the unceid error	da st.		
Customer Service (866) 570-470		with a minimum	a monthiy charge i under applicable	of \$5, or such l		Reverse for Impor	rtant Messages
		with a minimum charge allowed	n monthiv cherce	of \$5, or sich l i law, regulation		harges	rtant Messages Total Due 197.93
(866) 570-470 Previous Balance 0.00	2 Payments	with a minimum charge allowed contract.	n monthy drarge I under applicable Adjustments	of \$5, or such I law, regulation	cr See Current C 197.3	harges }3	Total Due 197.93
(866) 570-470 Previous Balance 0.00 Description Delivery 30 yd open top Ticket Total Fuel/environmental charge	2 Payments	with a minimum charge allowed contract.	n monthy drarge I under applicable Adjustments	of \$5, or sich l i law, regulation	or See Current C	harges	Total Due 197.93 Amount 150.00 150.00
(866) 570-470 Previous Balance 0,00 Description Delivery 30 yd open top Ticket Total	2 Payments	with a minimum charge allowed contract.	n monthy drarge I under applicable Adjustments	of \$5, or such I law, regulation S Date	cr See Current C 197.3 Sectors Ticket	harges }3 Quantity	Total Due 197.93

Midwest Environmental Consulting & Remediation Services Inc 22200 Illinois Route 9 P.O. Box 614 Tremont, IL 61568-0614

Invoice

DATE	INVOICE NO.
4/14/17	6700B

BILL TO WAYNE PAGE 24 RUTLEDGE AVE.

BARTONVILLE, IL 61607

				TERMS	PROJECT	SITE	LOCATION
				UPON RECEIPT		T	RIVOLI
ITEM	DATE	QTY.	RATE	······			AMOUNT
PROJECT MANAG/AJF	3/1/17	3			DAY:REPORTS:PERMITS	;	337.02
PROJECT MANAG/AJF	3/2/17	2.5	112.34	E.ACTION;REPORTS			280.85
PROJECT MANAG/AJF	3/3/17	1.5	112,34	E.ACTION:REPORTS			168.51
SR. PROJ. MGR/AJF	3/7/17	1.25	121.49	E.ACTION			151.86
PROJECT MANAG/AJF	3/7/17	2.5		E.ACTION;REPORTS			280.85
SR. PROJ. MGR/AJF	3/8/17	1	121.49	E.ACTION			121.49
PROJECT MANAG/AJF	3/8/17	I	112.34	E.ACTION;REPORTS			112.34
SR. PROJ. MGR/AJF	3/10/17	4.75	121.49	E.ACTION;SITE;UST P	ULL; SAMPLING:MAPS:I	REPORTS	577.08
MILEAGE	3/10/17	6.6	5.80				38.28
PID	3/10/17	1	75.00				75.00
ENCORE SAMPLE	3/10/17	6	12.52				75.12
PROJECT MANAG/AJF	3/13/17	2	112.34	E.A.;REPORTS			224.68
SR. PROJ. MGR/AJF	3/14/17		121,49	E.ACTION;SITE;UST P	ULL; SAMPLING:MAPS;I	REPORTS	242.98
PROJECT MANAG/AJF	3/14/17	2 2 2	112.34	E.A.;REPORTS			224.68
PROJECT MANAG/AJF	3/21/17	2	112.34	E.ACTION;REPORTS			224.68
SR. PROJ. MGR/AJF	3/21/17	1	121.49	E.ACTION			121.49
PROJECT MANAG/AJF	3/22/17	3.5		E.ACTION;REPORTS			393.19
SR. PROJ. MGR/AJF	3/22/17	1		E.ACTION			121.49
PROJECT MANAG/AJF	3/23/17	1.5	112.34	REPORTS			168.51
PROJECT MANAG/AJF	3/24/17	1.5	112.34	REPORTS			168.51
SR. PROJ. MGR/AJF	3/29/17	1		E.ACTION			121.49
SR. PROJ. MGR/AJF	3/30/17	1.5	121.49	E.ACTION			182.24
SR. PROJ. MGR/AJF	4/5/17	2.5	121,49	E.ACTION			303.73
SR. PROJ. MGR/AJF	4/6/17	1.5	121.49	E.ACTION:REPORTS:M	AAPS:CACR		182.24
SR. PROJ. MGR/AJF	4/7/17	2		E.ACTION:REPORTS:N			242,98
SR. PROJ. MGR/AJF	4/10/17	1.5		E.ACTION; REPORTS; M			182.24
SR. PROJ. MGR/AJF	4/12/17			E.ACTION:REPORTS:M			121.49
Reimb Group							
•	4/14/17		2.076.34	LAB ANALYSIS SOIL			2.076.34
				Total Reimbursable Expe	enses		2,076.34
			-12.00%-				249.16
				Total Reimbursable Expo	enses		2,325.50
				<u> </u>			
THANK YOU! PLEASE CALL WITH A! (309) 925-5551	NY QUESTI	IONS.			Total		\$7,770.52

....

Teaching long viz REPRINT St Auguston dama france Part (309) 462-3003	TICKET NO: 1179 Date: 3/10/2017	3978	
St Augustation State Part (309) 462-3003 2201 State State 3030 (303) 757-8250	Jane: 3/10/2017		
RAS	Material: 1D	·········	······
ATEFT TOTAL LOWE	Desc: 1" DOWN COMM		}
ATE TE THE THE THE ATE THE	Billed Units: 21.16 Ton	- (1)6)	
	Directonics. 21.10 Ton	Pounds	Tons (US)
A COL 20 CONTRACT CONTRACTOR CONTRAC	Gross	72400	36.20
	Tare	30080	15.04
A P.O.Mes LANDE DL SARETRE	Net	42320 *	<u>21.16</u> °
Today's Tupez SLOA Tare LE 3 Loads	* Manual Weight		
/ Rete Derrer		Rate	Amount
Vence Per-541 Dher RASKTRANSFORTATIONS			
	Tax: 114	7.250	
╞────── ੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑੑ	Fees:		
Driver's signeilire	Rec'd by:	*******	
custome	-		av 1.27 0/16/2014
Vallay QuarryRiverSlone Group, Inc.REPRINTP.O. Box 110St. Augustine, Illinois 61474Plant: (309) 462-3003ILDOT# 5187201Main Office: (309) 757-8250	71CKET NO: 1179 Date: 3/10/2017 Time Out: 11:02	3978	
Customer RASTRA RASK TRANSPORTATION CO INC (RG)	Material: 10	*******	
1880 STATE RTE 167 VICTORIA, IL 61485	Desc: 1" DOWN COM	,	
(309) 879-2221	Billed Units: 21.16 Tar	s (US)	Tons (US)
Order, RASTRA006 VARIOUS	Gross	` <u>Pounds</u> 72400	36.20
	Tare	30080	15.04
		*	21.16 .
P O./Job ILLINOIS OIL MARKETING	Net * Manuel Weight	42320 *	2110*
Today's Totals: 50.84 Tons (US) 3 Loads			<u></u>
Rale Carrier:		Rate	Amount
Vehicle: P831943 Driver: RASK TRANSPORTATION 3			
Delivery DeVPickup: PickUp			
	Tax: 114	7.250	
	Fees:		
	1		
	L.,]
Daver's signature	Rec'd by:		
Driver's signature	-		
	ercopy 2	I	ev. 1.27 9/16/2014
custome	ercopy 2	1	an an anna anna an an an an

CONTRACTOR AND A CONTRACTOR

Waterial Company STO Knox Rd. 1800 East • Maquon, IL 61458 • (309) 358-1420 Total * Maguon, IL 61458 • (309) 358-1420 Material Total * Maguon, IL 61458 • (309) 358-1420 Material Material Material * Maguon, IL 61458 • (309) 358-1420 <th colspa="</th"><th>4</th></th>	<th>4</th>	4
ALARY TRAVE CORPUTENCY Titler # Job ACCOUNT ACCOUNT ON THE TAXES Material Tool Charge Material		
JOB Material Total Charge Material Total Charge Material Total Charge Driver Ant. pdc Overvedsht loads are the driver's responsibility. Received by Wearst Status Expression Status Received by STO Knox Rd. 1800 East • Maquion, IL 61458 • (309) 358-1420 Total Charge Customer Example to add are the driver's responsibility. Received by Wearst Status Example to add are the driver's responsibility. Total Charge Material Total Charge Hauler Example to add are the driver's responsibility. Very status and to add are the driver's responsibility. Total Charge Material Total Charge Hauler Example to add are the driver's responsibility. Wearst Status Example to add are the driver's responsibility. Total Charge Job Total Charge Material Ant. pdc Hauler Example to add are the driver's responsibility. STO Knox Rd. 1800 East • Maquion, IL 61458 • (309) 358-1420 Customer Example to add are the driver's responsibility. Wearst Example to a driver's responsibility. Total charge Material Ant. pdc Hauler Example to add are the driver's responsibility. Wearst Example to add are th	203	
Material Total Charge Hauler EARST TRANSPORTATION 22,17 Ant. pd: Driver Ant. pd: Received by Ant. pd: Orerweight loads are the driver's responsibility. Received by Received by STO Knox Rd. 1800 East • Maquon, IL 61458 • (309) 358-1420 Total Charge Customer DATE: 3/ 10/ 1792 Excel • 44:05 Fast State • 7440 State read East • Control • 100 - 1		
Hauler Ann. pd: Driver Ann. pd: Overregent todak the the driver's responsibility. Received by Weenst Sand & Gravel Countenary S70 Knox Rd. 1800 East • Maquon, IL 61458 • (309) 358-1420 Customer Date: 3/ 10/ 178 12893 44:06 5.84 Sand Tester the driver's responsibility. Total Charge Material Total Charge Material Ann. pd: Weenst Send & Counter of the driver's responsibility. Total Charge Material Total Charge Material Ann. pd: Weenst Send & Counter of the driver's responsibility. State the driver's responsibility. Weenst Send & Counter of the driver's responsibility. Received by Orevelated related to the driver's responsibility. Received by State of the driver's responsibility. State of the driver's responsibility. Weenst Send & Counter of the driver's responsibility. Received by Customer State of the driver's responsibility. Weenst Send & Counter of the driver's responsibility. State of the driver's responsibility. State of the driver's responsibility. Received by Customer State of the driver's responsibility. Bableo Ber		
Driver Overweight loads are the driver's responsibility. Received by Weast Sand & Gravel Company 570 Knox Rd. 1800 East • Maquén, IL 61458 • (309) 358-1420 Customer Davis: 3/10/1781H88+44:06 Rd Réceived by Totat # Customer Davis: 3/10/1781H88+44:06 Rd Réceived by Totat # State * State * Material Total Charge Material Total Charge Model State * Company STO Knox Rd. 1800 East * Maquén, IL 61458 * Company Job Total Charge Amt. pd: Material Total Charge Amt. pd: Basis * State * Maquén, IL 61458 * Company STO Knox Rd. 1800 East * Maquén, IL 61458 * Company STO Knox Rd. 1800 East * Maquén, IL 61458 * Company STO Knox Rd. 1800 East * Maquén, IL 61458 * Company State * State * State * State * Material Ital 61458 Company State * Material Material Ital 61458 Company State * Material Material To		
Wreast Stand & Gravel Company 570 Knox Rd. 1800 East • Maquon, IL 61458 • (309) 358-1420 Customer DATE: 3/10/17721488:44:05 #4 Pape, ypans restrances 12880 w: re 144 Received by Job Topi Charge Material Amt. pd: Hauler EAST TRANSPORTATION Oriver Oriver's responsibility. Wreast Seal Received by Oriver State: seal Job Topi Charge Material Amt. pd: Base TRANSPORTATION Amt. pd: Oriver EAST TRANSPORTATION Job Topi Charge Material Amt. pd: Base Transport Constant of the driver's responsibility. Wreast Seal Material Material Amt. pd: Base Transport State of the driver's responsibility. State: State: Material Totat # Base to the driver's responsibility. Totat # State: State: Driver State: Driver State: Driver State: Driver State:	1 may .	
570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Ticket #		
STO KHOK KU, 1000 EAST * Plaquidit, 12 Girsts * (307) 330-1420 Ticket # Tic		
Customer DATE: 3/10/17719188:44:06 PM PARE: 3/10/1771888:44:06 PM PARE: 75460 TARE: 75460 TARE: 75460 TARE: 75460 TARE: 75460 TARE: 75460 Total Charge Ant. pd: Ant. pd: Ant. pd: Total Charge Ant. pd: Customer DATE: 7/10/17718812: 17:36 FM Received by 570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358.1420 Customer DATE: 7/10/17718812: 17:36 FM RASE: 7/120 Total charge Ant. pd: Total charge Total charge Total charge Ant. pd: Total charge Ant. pd: Total charge Ant. pd: Total charge Ant. pd: Ant. pd: An	· -	
10b Total Charge Job Total Charge Material Material Hauler EASR STANDORTATION Driver EASR STANDORTATION Overweight/loads are the driver's responsibility. Received by Weelst Send & Grewel Company 570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Customer EASE: 3/10/17TTHEIR: 17/136 FM BASE STERESCORTATION Greats: 74120 Material Total Charge Material Total Charge	3	
Material FILE SAMP (BASK FIRM FILM FILE) Hauler EASE TRANSPORTATION Driver Ant. pd: Overweight/loads are the driver's responsibility. Received by Weesse Send & Crewel Company 570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Customer EASE TEAMSEORTATION 18860 pr HT 167 18860 pr HT 167 Job VICTORIA, IL 63465 Material Material FILE SAMP (BASK FUE) Truck		
Material Ant. pd: Hauler RASK STRAMBOORTASION Ant. pd: Driver Overweight/loads are the driver's responsibility. Received by WOEDST SEARCH & COMPLEX Received by		
Hauler RASE TRANSPORTATION Received by Driver Overweight?loads are the driver's responsibility. Received by Weelst Sand & Chavel Company 570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Customer EASE TEANSPORTATION 18285 gr BP 187 Job Material Fills (AND (Deach Fun) Truck		
Overweight loads are the driver's responsibility. Weest Send & GRAVEL Company 570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Customer EASE: 3/19/17FINEL2: 17: 36 PM EASE TEANSEOSTATION 16880 az ep 167 NET: 39490 NET: 39490 NET: 39490 NET: 39490 NET: 39490 NET: 394920 Total Charge: Material Haulor FILL GAND (Deach Fun) Truct # Amt. pd:		
Weess Send & Crevel Company 570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Ticker # Source Customer EASE TEANSPORTATION 16880 ar er 167 Source F Job VICTORIA, IL 63405 Material FILL GASE (Dark run) Truct		
570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Customer Ticket # EASE TEAMSEQREATION 16880 sr mp 167 Job VICTORIA, IL 61455 Material Total charge: Haulor FILL SAND (Dank run) Truct#		
570 Knox Rd. 1800 East • Maquón, IL 61458 • (309) 358-1420 Customer Ticket # EASE TEAMSEQREATION 16880 sr mp 167 Job VICTORIA, IL 61455 Material Total charge: Haulor FILL SAND (Dank run) Truct#		
Customer Ticket # EASE TEANSPORTATION GROSS: 74120 16850 st EP 167 Total Charge: Job VICTORIA, IL 63405 ; Material Total Charge: Haulor FILL SAND (Dank run) Truck #		
EATE: 3/10/17FINEL2:17:36 FM S5294 RASE TEAMSEOREATION GROSS: 74120 16880 ST RP 167 GROSS: 74120 Job VICTORIA, TE G1465 Material Total charge: Haulor FILL SAND (Dank run) Truck#		
16880 st RP 167 RARD: 20400 Job VICTORIA, IL 61405 Material Total Charge: Haulor FILL SAND (Dank run) Truck#		
Material Total charges Haulor FILL SAND (Dank run) Truck# Amt. pd.:		
Driver Received by		
0120		

Electronic Filing: Received, C	Clerk's Office 11/5/2020)
Valley Quarry RiverStone Group, Inc. P.O. Box 110 St. Augustine, Illinois 61474 Plant: (309) 462-3003 ILDOT# 5187201 Main Office: (309) 757-8250	TICKET NO: 11794090 Date: 3/10/2017 Time Out: 01:24	ORIGINAL
Customer: RASTRA RASK TRANSPORTATION CO INC (RG) 1880 STATE RTE 167 VICTORIA, IL 61485 (309) 879-2221 Order: RASTRA006 VARIOUS P.O./Job: ILLINOIS OIL MARKETING Today's Totals: 72.64 Tons (US) 4 Loads	Material: 1D Desc: 1" DOWN COMM Billed Units: 21.80 Tons (US) Gross 73680 Tare 30080 Net 43600 *	<u>Tons (US)</u> 36.84 15.04 1.80 *
Rate: Carrier: Vehicle: P831943 Driver: RASK TRANSPORTATION 3 Del/Pickup: PickUp	Tax: 114 7.250	Amount
Driver's signature:	Rec'd by:	ev. 1.27 9/16/2014
Valley Quarry RiverStone Group, Inc.	TICKET NO: 11794000	
P.O. Box 110 St. Augustine, Illinois 61474 Plant: (309) 462-3003 ILDOT# 5187201 Main Office: (309) 757-8250	Date: 3/10/2017 Time Out: 01:24	ORIGINAL
- · · · · · · · · · · · · · · · · · · ·	Date: 3/10/2017	Tons (US) 36.84 15.04 21.80 *
ILDOT# 5187201 Main Office: (309) 757-8250 Customer: RASTRA RASK TRANSPORTATION CO INC (RG) 1880 STATE RTE 167 VICTORIA, IL 61485 (309) 879-2221 Order: RASTRA006 VARIOUS	Date: 3/10/2017 Time Out: 01:24 Material: 1D Desc: 1° DOWN COMM Billed Units: 21.80 Tons (US) <u>Pounds</u> Gross 73680 Tare 30080 Net 43600 *	<u>Tons (US)</u> 36.84 15.04

customarcopy 2

rev. 1.27 9/16/2014

Midwest Environmental Consulting & Remediation Services Inc 22200 Illinois Route 9 P.O. Box 614 Tremont, IL 61568-0614

> BILL TO WAYNE PAGE 24 RUTLEDGE AVE. BARTONVILLE, IL 61607

Invoice

DATE	INVOICE NO.
5/18/17	6704B

				TERMS	PR	OJECT	SITE	LOCATION
				UPON RECEIPT			FAR	MINGTON
ITEM	DATE	QTY.	RATE		<u></u>			AMOUNT
SR. PROFESSIONAL PROJECT MANAG/AJF SR. PROJ. MGR/AJF PROJECT MANAG/AJF SR. PROJ. MGR/AJF SR. PROJ. MGR/AJF SR. PROJ. MGR/AJF Reimb Group	4/10/17 4/13/17 4/13/17 4/14/17 4/14/17 4/19/17 5/2/17 5/11/17 5/10/17 5/10/17	1 2 0.5 0.75 1 1.25 1 0.5	112.34 121.49 112.34 121.49 112.34 121.49 121.49 121.49	45 DAY;PG CERT EA:REPORTS REPORTS;REIMB EA;REPORTS REPORTS;REIMB EA;REPORTS REIMB:REPORTS REIMB POSTAGE Total Reimbursable Expe Markup Total Reimbursable Expe				133.64 224.68 60.75 56.17 91.12 112.34 151.86 121.49 60.75 7.20 7.20 0.86 8.06
THANK YOU! PLEASE CALL WITH AN (309) 925-5551	VY QUESTI	ONS.				Total		\$1,020.86

Owens, Melissa

From:	mecrs <mdwstenv@frontier.com></mdwstenv@frontier.com>
Sent:	Tuesday, July 10, 2018 9:36 AM
To:	Owens, Melissa
Subject:	[External] Re: Evelyn Page Trust 20170100 early action claim
Attachments:	Untitled_07102018_092838.pdf
Follow Up Flag:	Follow up
Flag Status:	Flagged

Melissa,

Please find attached the proof of payment for PDC Laboratories. It was part of a larger payment to PDC and PDC invoice #860599 is included as part of the payment. We are working on everything else and will get it to you prior to July 23rd. The only thing that might be difficult is a legible copy of the manifest. The copy of the manifest given to the client is a flimsy piece of paper because the manifest is filled out in triplicate. We copied it as dark as we could get it and sent that to you. Also, the tank removal was offered to the only two reputable tank removal companies in our area and we chose the lowest bid.

Sincerely,

MECRS

From: Owens, Melissa Sent: Tuesday, July 10, 2018 7:53 AM To: mecrs Subject: Evelyn Page Trust 20170100 early action claim

Good morning,

I'm working on the above referenced claim, and I discussed it with Brian on Friday afternoon.

- ✓ 1. For Remediation and Disposal, can you please provide the invoice for the \$915 for drum disposal? Brian also said I need to request a legible copy of the manifest.
 - 2. For the UST Removal, Brian said the work was not bid properly. He said we can pay the H rate plus the backfill and drums. To pay for backfill and drums, we will need invoices.
 - 3. Can you please provide the name of those doing the work on the invoices?
 - 4. I don't see a receipt for postage. We will need the receipt in order to reimburse the cost and pay handling.
- ✓ 5. I don't see proof of payment for PDC Laboratories. We can't pay handling without it.

Please provide the requested documentation by July 23rd.

Thanks,

Melissa Owens

State of Illinois - CONFIDENTIALITY NOTICE: The information contained in this communication is confidential, may be attorney-client privileged or attorney work product, may constitute inside information or internal deliberative staff communication, and is intended only for the use of the addressee. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify the sender immediately by return e-mail and destroy this communication and all copies thereof, including all attachments. Receipt by an unintended recipient does not waive attorney-client privilege, attorney work product privilege, or any other exemption from disclosure.

Midwest Environmental Consulting & Remediation Services Inc 22200 Illinois Route 9 P.O. Box 614 Tremont, IL 61568-0614

,	Bill
Date	Ref. No.
04/14/17	860599

PDC LABORATORIES, INC PO BOX 9071 PEORIA IL 61612-9071



Bill Due	05/15/17
Terms	
Memo	SOIL ANALYSIS

Expenses

Account	Memo	Amount	Customer:Job
Job Cost Subcontract	LAB ANALYSIS SOIL	1,855.00	EVELYN PAGE TRUST

Expense Total : 1,855.00

Bill Total : \$1,855.00

2/9/18

**9,297.92

PDC LABORATORIES, INC

PDC LABORATORIES, INC PO BOX 9071 PEORIA IL 61612-9071

852186;857986;860598;860599;860597

PDC	LABOR	ATORIES, INC			2/9/18	
Date	Туре	Reference	Original Amt.	Balance Due	Discount	Payment
1/2/17	Bill	852186	1,217.02	1,217.02		1,217.02
3/23/17	Bill	857986	128.50	128.50		128,50
4/14/17	Bill	860598	5,311.40	5,311.40		5,311.40
4/14/17	Bill	860599	1,855.00	1,855.00		1,855.00
4/26/17	Bill	860597	786.00	786.00		786.00
					Check Amount	9,297.92

Cash-Operating Acco 852186;857986;860598;860599;860597

ť

.

9,297.92

PDC	LABOR	ATORIES, INC			2/9/18	
Date	Туре	Reference	Original Amt.	Balance Due	Discount	Payment
1/2/17	Bill	852186	1,217.02	1,217.02		1,217.02
3/23/17	Bill	857986	128.50	128.50		128,50
4/14/17	Bill	860598	5,311.40	5,311.40		5,311.40
4/14/17	Bill	860599	1,855.00	1,855.00		1,855.00
4/26/17	Bill	860597	786.00	786.00		786.00
					Check Amount	9,297,92

Cash-Operating Acco 852186;857986;860598;860599;860597


Electronic Filing: Received, Clerk's Office 11/5/2020 history - The First National Bank in Tremont

Page 1 of 1

MI	DWEST ENVIRONMENTAL CONSULTING & REMEDIATION SERVICES, INC. PHONE: (309) 925-5551 22200 ILLINOIS ROUTE 9 P.O, BOX 614 TREMONT, IL 61568	TREMONT COMMUNITY BANK TREMONT, IL 61669 70-943/711 	86
PAY TO TH ORDER OF	PDC LABORATORIES, INC	\$ **9,297.92	
Nine Ti	PDC LABORATORIES, INC PO BOX 9071 PEORIA IL 61612-9071	DOLLARS	<u>`</u> .

history - The First National Bank Filing: Received, Clerk's Office 11/5/2020

Page 1 of 1



0127

Owens, Melissa

From:	mecrs <mdwstenv@frontier.com></mdwstenv@frontier.com>
Sent:	Thursday, July 12, 2018 12:12 PM
То:	Owens, Melissa
Subject:	[External] Re: Evelyn Page Trust 20170100 early action claim
Attachments:	Interstate Chemical invoice and manifest.pdf
Follow Up Flag:	Follow up
Flag Status:	Flagged

Melissa,

Please find attached the invoice for the drum disposal and as legible a copy of the manifest as is possible. We are continuing to work on everything else and will get it to you soon.

Thanks,

MECRS

From: Owens, Melissa Sent: Tuesday, July 10, 2018 7:53 AM To: mecrs Subject: Evelyn Page Trust 20170100 early action claim

Good morning,

I'm working on the above referenced claim, and I discussed it with Brian on Friday afternoon.

- 1. For Remediation and Disposal, can you please provide the invoice for the \$915 for drum disposal? Brian also said I need to request a legible copy of the manifest.
- 2. For the UST Removal, Brian said the work was not bid properly. He said we can pay the H rate plus the backfill and drums. To pay for backfill and drums, we will need invoices.
- 3. Can you please provide the name of those doing the work on the invoices?
- 4. I don't see a receipt for postage. We will need the receipt in order to reimburse the cost and pay handling.
- 5. I don't see proof of payment for PDC Laboratories. We can't pay handling without it.

Please provide the requested documentation by July 23rd.

Thanks,

Melissa Owens

State of Illinois - CONFIDENTIALITY NOTICE: The information contained in this communication is confidential, may be attorney-client privileged or attorney work product, may constitute inside information or internal deliberative staff communication, and is intended only for the use of the addressee. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify the sender immediately by return e-mail and destroy this communication and all copies thereof, including all attachments. Receipt by an unintended recipient does not waive attorney-client privilege, attorney work product privilege, or any other exemption from disclosure.

Customer Number	INTERSTATE (INV℃	PICE
· ·	PHONE (724) 981-37	71 FAX (724) 981-8	383	Date	Invoice #
	~			06/21/2017	287535
				Date Shipped	Order #
	R INTERSTATE CHEMICAL CO., I	NC.		05/21/2017	253698
	E PO BOX 931412				
	M CLEVELAND , OH 44193-1573			Dafe	Due:
	T			07/21	/2017
	TO	7			
S ESTATE OF EVELYN PAGE O 23907 W FARMINGTON ROAD	S H	ESTATE OF EVELYN 23907 W. FARMING			
L FARMINGTON, IL 61531-	11 1	FARMINGTON, IL 6			
D	P	17 a data for one field	1001		
т	τ.				
0	ļ o				
Customer PO #	FOB Remark	The left of		······································	~ · · · · ·
(E)	DESTINATION	Freight Cl PREP/		Vend	or Code
		·			
Requisition #	Payment Terms	Ship		Si	ales ID
the the Decement	NET 30	ALPON			602
Units Package 1.00 1 E UNIT	Description ENVIRONMENTAL SERVICES		Total Quantity	Unit Price	Amount
	33330-EA		1.0000	//E	
	Loi: DEFAULT				
	ENVIRONMENTAL SERVICES			,	915.00
Manilest# 016662830 ***Paid by check# 773 Thank Youl					
· · ··· ······························	SALES	TAX EXEMPT	······································		0.00
		en 14 2017			
		7739			
Seter represents that with respect to the production of the articles at provisions of the Fair Labor Standards Act of 1938, as amended.	d'or the services covered by this invoice, it has fully complied with the		Total:	Ş	915.00
PRICE EFFECTIVE ON DATE OF SHIPMENT AN	D PRODUCT SUBJECT TO AVAILABILITY AT TIM	2		EASE PAY THIS A	
OF SHIPMENT UNLESS OTHERWISE AGREED	ÎO IN ADVANCE IN WRITING.				
A LATE FEE OF 1 1/2	2 % PER MONTH (18% PER ANNUM) W	ILL BE APPLIED TO AI	LLATE PAYME	NTS	
	Page 1 of 1				

			\$7		1.51	4 9	· Æ	r ek	7				r	
Plea		prifficer type. (Form desig	ned for úse ón ellia Li Generato: O Numi	(12-pilch) typewriter	1.07		•	gency Response	Phone	4. Manifest		n Ap(ກຍົນອີດ. (DMB'No. 1	2050-0939
Ť		NASTE MANIFEST -	0.5501					66.0268		01	RRR	283() J.	IK
	1	Senerator's Hame and Hallis	nç Address		ALC MENT		Generald	S'S Sile Address	(il different V	ian maling addre	<u>55</u>]			
		Estate of Evelyn F 23007 W. Ferminia	tun ikd		L.						<u>e</u> rt i	3 • ¹ • ·		
	Gui	Farry Pronet IL Sil	534 			- 11 m2 - 11 m2 - 11 m2	•,		· · ·	U.S. EPAIDI	Mumbus			
	ł	Alpont Trensport		a de la construcción de la construcción de la construcción de la construcción de la constru- ciona de la construcción de la const	·····			n an eta		FAR	0 G	054.	194	4
		ransporter 2 Company Nam		·····						U.S. EPA ID I	Number		<u> </u>	
	8. D	Designated Facility Name an	d Sile Address				·			U.S. EPAID	Number			
		TRADEDE TREAT 4943 KENNEDY A		YCLING, LLC										
		EAST CHICACIO		· -	. .	••••.	• • • •		· · · •	LI N IS	n'n :	0.81416	194	3
	1 80. Ba.	9b, U.S. DOT Description	on finduling Proper St	vipping Name, Hazard C	lass, ID Number, .			10, Coniai	ners , ,	j 1. Total	- \$2,.Unit	T	laste Code	
	нм	1					·; ·	No.	Тура	Quantity	WLVol.			
TOR	X	UN1202. VAS 3. POIII	TE Diesel fuel					AAI	ÐF-	and and and		0001		·····
GENERATOR	Ľ	2	e esta com A desta diferencia	· · · · · · · · · · · · · · · · · · ·	<u> </u>	· · · · ·	<u> </u>	001		055	G	·		
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	X	UN1202. WAS	TE Diesel fuel						0角			0001		
		3,						<u>90 L</u>	75959	μq	<u>⊢</u> ⊆_	 		
												<u>├</u> ───-		
	<u> </u>	<u> </u>	· · · · · · · · · · · · · · · · · · ·		~			· · · · · · · · · · · · · · · · · · ·	ļ			$\frac{1}{1}$		
													;;	
	14.	Special Handling Instruction	moni lanoù bha a	nation	•					1	J			
				•M) S	TREAM# 17	050008	ERG	128-2KI) S	IREAM	#17080097	' ERG#	28		
		،	۰.			¥. 4					•			
	15.	GENERATOR'S/OFFERO marked and tabeled place	R'S CERTIFICATION	: Thereby declare that t	he contants of this In far transport acco	consignment which to and	Lane fully a	and accurately de mational and nat	iscribed abov	re bý lite propar s mental reculation	hipping nan	ie, and are clas bloment and t	stied, paci m the Poin	බයුරේ, මාදුරේ,
		Exporter, I certify that the of I certify that the waste min	contents of this consign	nmani conform to the to	ms of the attached	EPA Acknow	អូចជុទ្ធជានរា	t of Consent,					r	2015 °
	Gen	erabris/Offeror's Prinled/Ty	ped Name	**************************************		and the second se	gnature	. f.	.}	X 2.4 K		Mon	th Day	Year
+	7	International Shipmasita		the second s	(Afent		<u>*</u>	<u></u>					<u>= []</u>	17
INT	Tra.	nsporter signature (for expo			ئـــــا 	Export from	U.S.	Port of er Daie leav			·····			
TRANSPORTER	17 Tran	Transporter Acknowledgmen Isopoter 1 Printed/Typed Nat		s •		Si	mature .	2				Món	lh Day	Year
SPOF		Or Moins	ALIC	Sam			1	12				D		17
RAN	Trai	sponel 2 Printed Typesky a	mo			Si I	gnalore	~~	••.			Mor I	eh Day I	i Year
<u>►</u> ↑		Discrepancy		· · · · · · · · · · · · · · · · · · ·		I					·			<u></u>
	16a	Discrepancy Indication Sp	ecs 🗌 Quantit	ý	Тура	•	[Residua		Pavlial R	ejection	[Fut Re	្រុំដល់ព
							ħ	Innifest Referenc	æ Number:					
Ł	165	Alismets Facility (or Gener	raior)		í		<u></u>			U.S. EPA ID	Numbar			
FACI	Fac	ility's Phone:												
(JED	180	Signature of Atternate Fac	lity (or Ganeralor)	<u></u>		<u></u>	,				<u> </u>	M	onth D	ay Year
DESIGNATED FACILITY	19	Hazardous Wasia Report M	lanecement Method C	odes (Lo., codes for ha	antous wasis iree	mant, oisoo	sal, end co	lambiaya prelovo						
DES	1.			2.		3.	and the second se			4.				
1	30	Designated Facility Owner (or Operator: Certification	on of receipt of hazardo	us materials cover	ed by the ma	i i nifêşt ekc	çpi as neisé in in	em 18a				ŧ	-
		Hear proved Nember	S/7	FXIV	7K		Signatur	11.	<u>A</u> 1/1	r FKI	11 1	11/11	kih con	iy Year
EP.	<u>Ι</u> A For	m 8700-22 (Rev. 205)	h Y F Previous éditions a	re obsoleta,	<u> (K.)</u>	1	<u>U.</u>	11:13	<u></u>	<u>(. 1 . 6</u>	11 12	<u>I II</u> THANSPO		<u>)/ /</u> 's cop
												· · · · · · · · · · · · · · · · · · ·		

ł

2¹⁰ 10 10 10 10 10

Page 1 Transactions for LB CLE-931412 DT 20170719 TID G-9094037

Transaction Information G-9094037 CLE-931412 2017/07/19

Transaction Level Details

Env Num	34	Envelope	G-9094037
Transaction	G-9094037	Lockbox	CLE-931412
Date	2017/07/19	Time	09:00
Batch	1	Batch Item	39
Check	39	Amount	\$915.00
ABA/RT	271183701	Account Num	0101993251
Check Num	7739		

Envelope and Check Image

EVELYN M. PAGE REV LIVING TRUST	:
W. PAGE K. PAGE L. MARSH CO. TTEES	
24 RUTLEDGE AVE. 6-16-2017	i.
Date	•
Pay to the INTYRSIATE CHEMICON \$915	-~
Underflundred Fifteen, and 100 Dollars Dollars	
CEFCU	
P.O. BOX1715, Peorla, IL 61656-1715	
	•
fierend Circles	
INTERSTATE CHEMICAL COMPANY, INC. 2797 Freedland Road, P.O. Box 1600 Harmitage, PA 16148-0600 13 JUN 2017 FM 3 L	
beviece A ecioval oN	
materiate Chemical Co.	
P.D. Box 931412	
Cleucland, 0H 44193-1573	
44193~1573 միկինիթյիսիդիովիինիդինիդինիդին	

Electronic Filing: Received, Clerk's Office 11/5/2020 774.39 4/10 182.29 1.5 hr PAST 1 121:49 4/12 121.49 PASI 121.49 V 133.64 TASI 133.63 4/10 4/13 PASÍ 112.34 224.68 2 121.49 ReimB 4/13 60.75 5 112.34 56.17 KEIMB 4/14 5 3/4 121.49 9/.12 4/10 REIMB 112,34 112.34 4/19 PASI 1.25 151.86 5/2 49 REMB 21. FEIMB 5/11 121.49 21.49 KAMB 1/2 60.75 5/17 Loduce adjust 2.75 to 68.83 Cut summary cut 2,5@ 121,49 = 313.73 1 @ 133.64 = 133.64 334.10 189.28 30 112.34 = 337.02 144.82 774.39 0132

	Electro nois Environme IST Claims Unit TS Queue Date dnesday, April 04, 20:	e Tracking			LPC Number	1438185006 20170100 <u>69179</u>
Queue Date	4/2/2018				120-Day Date	
	PAGE EVELYN M	TRUST				.,
	EVELYN M PAGE					
Operator Name	Evernmenne				IEMA	
Class Code	E۸	Program	73/		2/1/1-> 4/1	and the second sec
		Flogram	194			\$\$ \$ X
Amount Requested		T 5/4	7/0047			
Billing Period From	2/7/2017		7/2017			
Consultant Name	MIDWEST ENVIR			_		
Opt-In Date		V -	\$5,000 di	eductible		
NFR Date	8/9/2017	-	Consultina	g Personne!	- 04Z -	
NFR Recorded Date	8/14/2017		need	names on m	to sen acci to	och
Division File			HOW EQ.	day writeff?	volce to son acci te	
Comments			- and se	e billing st	mmany to	other genestions egible manifest c plus Unckfill plus backfill + droms

FIRST CLAIM NO BREAKDOWNS

.

Midwest Environmental Consulting & Remediation Services Inc. 22200 Illinois Route 9 • P.O. Box 614 Tremont, IL 61568-0614 Phone : (309) 925-5551 • Fax : (309) 925-5606 E-mail : mdwstenv@frontier.com

March 1, 2018

Illinois Environmental Protection Agency Division of Remediation Management Remedial Projects Accounting and Procurement Unit 1021 North Grand Avenue East Post Office Box 19276 Springfield, Illinois 62794-9276

RE: LPC #1438185006 -- Peoria County Trivoli/Evelyn Page Trust 23907 West Farmington Road Trivoli, Illinois Incident #20170100 LUST Fiscal File

Dear Sirs:

Please find enclosed the early action reimbursement request for the subject site. Attached are the following listed invoices and corresponding documentation:

- Invoice #6700B dated 4/14/17 for \$7,770.52 from Midwest Environmental Consulting and Remediation Services, Inc. (MECRS), \$7,522.62 of which is eligible for reimbursement, along with the corresponding subcontractor invoices.
- 2) Invoice #6704B dated 5/18/17 for \$1,020.86 from MECRS.
- 3) Manifest, Certificate of Recycle, and cancelled check dated 6/16/17 to Interstate Chemical in the amount of \$915.00 for drum removal.
- 4) Invoice #0113973-INbrk dated 3/31/17 for \$14,030.00 from Illinois Oil Marketing Equipment, Inc. Also included are the quotes for tank removal from Illinois Oil Marketing Equipment and Total Petroleum. The quote from Illinois Oil Marketing Equipment, Inc. was the lowest bid that we received for the type of tank that was removed.

The total amount being requested for this reimbursement submittal is \$23,488.48.

Please feel free to contact our office with any comments or questions.

Sincerely,

Midwest Environmental Consulting & Remediation Services, Inc.

Gaye Lynn Green Reimbursement Manager

Job #17-20



General Information for the Budget and Billing Forms

i

i

LPC#: <u>1438185006</u>		County: <u>Peoria</u>	
City: <u>Trivoli</u>		Site Name: Evelyn	Page Trust
Site Address: 23907 West Fa	armington Road		
IEMA Incident No:	20170100		
IEMA Notification Date:	2/7/2017	······	······································
Date this form was prepared:			
This form is being submitte	d as a (check one if appli	cable):	
Budget Propos	al		
Budget Amendr	ment (Budget Amendments	must include only the	costs over the previous budget.)
X Billing Package	e		
Please provide	the name(s) and date(s) o	f report(s) document	ing the costs as requested:
Name(s):	Early Action		
Date (s):			
This package is being subm	nitted for the site activitie	s indicated below:	
35 III. Adm. Code 734:			
X Early Action			
Free Product F	Removal After Early Action		
Site Investigati	ionStage 1:	Stage 2:	Stage 3:
Corrective Act	ion		
35 III. Adm. Code 732:			
Early Action			
Free Produce	Removal After Early Action	I	
Site Classificat	tion		
Low Priority Co	orrective Action		
High Priority C	orrective Action		
35 lil. Adm. Code 731			RECEIVED
Site Investigat	ion		
Corrective Act	ion		APR 02 2018
IL 532-2825 LPC 630 Rev. 1/2007			IEPA/BOL

General Information for the Budget and Billing Forms

•

ι

≁.

The following address will be used as the mailing address for checks and any final determination letters regarding payment from the Fund.

Pay to the order of: Evelyr	n Page Trust					
Send in care of: Midwe	est Environmenta	I Consulting and I	Remediation Serv	ices, Inc.		
Address: 22200 Illinois	s Route 9, PO Bo	ox 614				
City: <u>Tremont</u>		State: IL	Zip:	61568		
The payee is the:	Owner: X) Operator		(Check one or both)		
[Nay - H	Lest.			W-9 must be submitted.		
Signature of the owner	of operator of i	ine UST(s) (requ	ired)	Click here to print off a W-9 Form.		
	pany of the owne	r or operator; and		er or operator; any subsidiary, ned by any parent, subsidiary		
Few	er than 101 🗙	101 or more:				
Number of USTs at the site: have been removed).	1(Nur	mber of USTs incl	udes USTs prese	ently at the site and USTs that		
Number of incidents repo	orted to the IEMA	for this site:		1		
Incidents Numbers assig	ned to the site d	ue to releases fro	m USTs:	20170100		
Please list all tanks that	have ever been l	ocated at the site	and tanks that ar	e presently located at the site.		
Product Stored in UST	Size (gallons)	Did UST have a release?	Incident No.	Type of Release Tank Leak / Overfill / Piping Leak		
diesel fuel	10,000	YesX No	20170100	tank leak		
		Yes No				
		Yes No				

No

No

No

No

Yes

Yes

Yes

Yes

Billing Summary

•

۰.

	\$ Amount Approved in the Budget	\$ Amount Requested for Payment from the Fund	
1. Drilling and Monitoring Well Costs Form			\$0.00
2. Analytical Costs Form			\$1,930.12
3. Remediation and Disposal Costs From		Ø	\$915.00
 UST Removal and Abandonment Costs Form 		5,078,19	\$14,030.00
 Paving, Demolition, and Well Abandonment Costs Form 		1	\$0.00
6. Consulting Personnel Costs Form		5,350.18	\$6,269.39
7. Consultant's Materials Costs Form		110.31	\$120.48
Total Amount Approved in the Budget*		NOT APPLI	CABLE
Subtotal of lines 1-7:	NOT APPLICABLE	12.468.80	\$23,264.99
8. Handling Charges Form	NOT APPLICABLE	222.60	\$223.46
TOTAL AMOUNT REQUESTED FOR PAYMENT	NOT APPLICABLE	12,691.40	\$23,488.45

< 5,000.007 deductible

*Date(s) this Budget(s) was approved:

NA; Early Action

7,691.40

Analytical Costs Form

`

٠

Laboratory Analysis	Number of Samples		Cost (\$) per Analysis		Total per Parameter
Chemical Analysis	Joumpioo		Analyoio		
BTEX Soil with MTBE EPA 8260	7		\$90.00	=	\$630.00
BTEX Soli with MTBE EPA 8260		X	\$90.00		\$0.00
COD (Chemical Oxygen Demand)		X	\$92.02		\$0.00
Corrosivity		x	\$16.36		\$0.00
Flash Point or Ignitability Analysis EPA 1010		X	\$35.99	=	\$0.00
Fraction Organic Carbon Content (f _{oc}) ASTM-D 2974-00		x	\$41.44		\$0.00
The proverties of the second		201335-20203092	Product of Public Action Action System Action	KCACONTY SCARA NO	\$0.00
Fat, Oil, & Grease (FOG)		X	\$65.43		•
LUST Pollutants Soil - analysis must include volatile, base/ neutral, polynuclear aromatics and metals list in Section 732.		X	\$836.20		\$0.00
Appendix B and 734. Appendix B.	10.2 (2 (3 (3 (3 (3)				
Dissolved Oxygen (DO)		N.	\$26.17	03170988 5897-1358	\$0.00
Paint Filter (Free Liquids)		X	\$20.17		\$0.00
PCB / Pesticides (combination)		X X	\$37.08	0=0	\$0.00
PCBs		X	\$165.76	995-304 -	\$0.00
Pesticides		×	\$165.76		\$0.00
pH		X	\$15.27		\$0.00
Phenol		×	\$13.27		\$0.00
Polynuclear Aromatics PNAs or PAH SOIL EPA 8270	7	X	\$175.00	=	\$1,225.00
Polynuclear Aromatics PNA, PAH WATER EPA 8270		x	\$176.80		
Reactivity	5 09900099 (92000 9900900	X	\$74.15		\$0.00
SVOC - Soil (Semi-Volatile Organic Compounds)		X	\$341.33		\$0.00
SVOC - Water (Semi-Volatile Organic Compounds)			\$341.33	=	\$0.00
TKN (Total Kjeldahl) "nitrogen"		x	\$47.98		\$0.00
TPH (Total Petroleum Hydrocarbons)		X	\$133.04		\$0.00
VOC (Volatile Organic Compound) - Soil (Non-Aqueous)		X	\$190.84		\$0.00
VOC (Volatile Organic Compound) - Water		x	\$184.29		\$0.00
Voo (vodilic organio compound) vvadi		X	ψ104.23	=	\$0.00
	5	x		=	\$0.00
	- <u>2000 (200) (</u>	x		/ \$10,25/mc.19249 =	\$0.00
		x			\$0.00
in an		X		=	\$0.00
Geo-Technical	1		1		φ0.00
Bulk Density (p _b) ASTM D4292 / D2937		x	\$23.99	=	\$0.00
Ex-Situ Hydraulic Conductivity / Permeability		x	\$278.08		\$0.00
Moisture Content (w) ASTM D2216-90 / D4643-87		X	\$13.09	=	\$0.00
Porosity		$\frac{1}{x}$	\$32.71		
Rock Hydraulic Conductivity Ex-Situ	2 SENAAN 2018 (1928) 	X	\$381.67		\$0.00
Sieve / Particle Size Analysis ASTM D422-63 / D1140-54		X	\$158.12	-	\$0.00
Soll Classification ASTM D2488-90 / D2487-90			\$74.15	=	\$0.00
Soil Particle Density (p _s) ASTM D854-92		X	φ/ӊ.١ῦ	00000000000000	****
Son Fande Density (Ps) AS HVI DO04-92		X		=	\$0.00
	a a second and a second subsection	X			\$0.00
		<u> </u>			
		X		=	\$0.00

/

Analytical Costs Form

Metals Analysis			··· ·		· · · ·
Soil preparation fee for Metals Soil TCLP (one fee per soil sample)		X	\$86.15	=	\$0.00
Soil preparation fee for Metals Total Soil (one fee per soil sample)		X	\$17.45		\$0.00
Water Preparation fee for Metals in Water (one fee per water sample)		x	\$12.00		\$0.00
Arsenic TCLP Soil		x	\$17.45	=	\$0.00
Arsenic Total Soil		x	\$17.45		\$0.00
Arsenic Water		X	\$19.63		\$0.00
Barium TCLP Soil		x	\$10.90		\$0.00
Barium Total Soil	1999-000 A.A. (20.000 A.A. 699, 409, 409, 409, 409, 409, 409, 409, 4	X	\$10.90		\$0.00
Barium Water		x	\$13.09	197 - 29	\$0.00
Cadmium TCLP Soil		X	\$17.45	=	\$0.00
Cadmium Total Soil	nk (3 5 8 94	x	\$17.45	()=()	\$0.00
Cadmium Water		x	\$19.63	=	\$0.00
Chromium TCLP Soil	fel av for skall ander av far skallender Men skallen skallender Men skallender	X	\$10.90		\$0.00
Chromium Total Soil		X	\$10.90	=	\$0.00
Chromium Water		X	\$13.09	=	\$0.00
Cyanide TCLP Soil		X	\$30.53	=	\$0.00
Cyanide Total Soil		X	\$37.08		\$0.00
Cyanide Water		x	\$37.08	=	\$0.00
Iron TCLP Soil		X	\$10.90		\$0.00
Iron Total Soil		X	\$10.90	=	\$0.00
Iron Water		x	\$13.09		\$0.00
Lead TCLP Soil		X	\$17.45	=	\$0.00
Lead Total Soil	and the standard and	X	\$17.45	I	\$0.00
Lead Water		X	\$19.63	=	\$0.00
Mercury TCLP Soil		X	\$20.72		\$0.00
Mercury Total Soil		X	\$10.90	Ξ	\$0.00
Mercury Water	0.4.2.2.2	X	\$28.35		\$0.00
Selenium TCLP Soil		X	\$17.45	=	\$0.00
Selenium Total Soil		X	\$17.45		\$0.00
Selenium Water	ļ	X	\$16.36	=	\$0.00
Silver TCLP Soil		X	\$10.90	E	\$0.00
Silver Total Soil		X	\$10.90	=	\$0.00
Silver Water	1. The Contract of the Contrac	X	\$13.09	=	\$0.00
Metals TCLP Soil (a combination of all RCRA metals)		X	\$112.32	=	\$0.00
Metals Total Soil (a combination of all RCRA metals)		X	\$102.51		\$0.00
Metals Water (a combination of all RCRA metals)		X	\$129.77	=	\$0.00
		Setta			
Other					
EnCore Sampler, purge-and-trap sampler or equivalent					
sampling device	6	x	\$12.52	=	\$75.12
Sample Shipping per sampling event ¹	n al anna an ta Matana a Salaha		\$17.20	- 200500	\$0.00

¹A sampling event, at a minimum, is all samples (soil and groundwater) collected in a calendar day.

Total Analytical Costs:

\$1,930.12

Remediation and Disposal Costs Form

A. Conventional Technology

、

•

Excavation, Transportation, and Disposal of contaminated soil and/or the 4-foot backfill material removal during early action activities:

Number of Cubic Yards	Cost per Cubic Yard (\$)	Total Cost

Backfilling the Excavation:

Number of Cubic Yards	Cost per Cubic Yard (\$)	Total Cost
		\$0.00

Overburden Removal and Return:

Number of Cubic Yards	Cost per Cubic Yard (\$)	Total Cost
		\$0.00

B. Alternative Technology

Alternative Technology Selected:				
Number of Cubic Yards of S	oil to Be Remediated			
Total Non-Consulting Personnel Costs Summary Sheet (\$				
Total Remediation Materials Costs Summary Sheet (\$)				
Total Cost of the System				

Remediation and Disposal Costs Form

C. Groundwater Remediation and/or Free Product Removal System

Total Non-Consulting Personnel Costs Summary Sheet (\$)	
Total Remediation Materials Costs Summary Sheet (\$)	
Total Cost of the System	

D. Groundwater and/or Free Product Removal and Disposal

Subpart H minimum payment amount applies.

Number of Gallons	Cost per Gallon (\$)	Total Cost (\$)

E. Drum Disposal

Subpart H minimum payment amount applies.

Number of Drums of Solid Waste	Cost Per Drum (\$)	Total Cost (\$)
3	305	\$915.00
Number of Drums of Liquid Waste	Cost Per Drum (\$)	Total Cost (\$)
Total Drum Dispo	osal Costs	\$915.00

Total Remediation and Disposal Costs:	\$915:00

after 59 days

UST Removal and Abandonment Costs Form

Product Stored in UST	Size (gallons)	Abandoned or Removed	Cost (\$)	Did UST have a release?
diesel fuel	10,000	removed	\$14,030.00	Yes X No
				Yes No
				Yes No
				Yes No
				Yes No
			동안 (영국) · 영국의 실험적인	Yes No
				Yes No
	e de ser a d			Yes No
		 A second sec second second sec		Yes No
				Yes No
			n – Marina Indonesia (h. 1996) 1999 - Angelan Santa Indonesia (h. 1997) 1997 - Angelan Indones	Yes No
	<u>en a contre a la posta da contre da po</u> sta en la posta de la posta			Yes No

VVIII pay H rate = 3,942.33 (3) backfill 68.07+1.5= 45.38 x 25.03 - 1,135.86 (3) drums no doc provided 5078.19 Not Bits Not Bits Not Bits - 254.09 DEMMS

NEED DOC.

Consulting Personnel Costs Form

•

Employee Name	Personnel Title*	Hours	Rate *	Total \$
Remediation Category		Task		
		(0.00	0 101 10	AA 400 00
	Senior Project Manager	18.00	\$121.49	\$2,186.82
UST-OT/20-Day/45-Day	EA project oversigh	t, planning, pern	nits, subcontract	
Allan Green	Senior Project Manager	8.00	\$121.49	\$971.92
UST-OS	EA; tank remo	val/EA sampling	/sample prep	
Andrew Fetterolf	Project Manager	26.50	\$112.34	\$2,977.01
UST-OT/20-Day/45-Day	20 Day/45 Day/EA re	port and reimbu	rsement prepara	ation
Penny Silzer	Sr. Professional Geologist	1.00	\$133.64	\$133.64
UST-OT/20-Day/45-Day	report	review and certif	ication	
			I	I,
			• • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •
<u>- 대한 가는 인간에 가</u> 는 같을]	

*Refer to the applicable Maximum Payment Amounts document.

Total of Consulting Personnel Costs	\$6,269.39
adjust 2.75 hours Fetter olf to 68.83/hour	<144.82>
auts per Brianis sheet	(774.39)
	5,350.18

Consultant's Materials Costs Form

Consulting Materials Costs:

•

•

Materials, Equipment, or Field F	/urchgege%%%	ne or unt Use Rate (\$)	Units	Total Cost	
Remediation Category	Descrip	tion/Justification		· · · · · · · · · · · · · · · · · · ·	
Company Vehicle Mileag	e 6	6.00 \$0.58	, /mile	\$38.28	35.31
EA-SB-Field	site visits and m	obilization to and from	site		
Photoionization Detecto	r.	.00 \$75.00	/day	\$75.00	_
EA-SB-Field	field scree	ning of soil samples			
Postage		\$7.20		\$7.20	Ø
EA		reports	N	\$7.20 O veceipt	
				\$0.00	_
				\$0.00	_
		· · · · · · · · · · · · · · · · · · ·		\$0.00	
				\$0.00	

Total Consultant's Material's Costs: \$120.48 [[0.3]

Handling Charges Form

•

Subcontractor or Field Purchase Cost:

Eligible Handling Charges as a Percentage of Cost:

\$1 - \$5,000 \$5,001 - \$15,000 \$15,001 - \$50,000 \$50,001 - \$100,000 \$100,001 - \$1,000,000 12% \$600 + 10% of amt. over \$5,000 \$1,600 + 8% of amt. over \$15,000 \$4,400 + 5% of amt. over \$50,000 \$6,900 + 2% of amt. over \$100,000

Subcontractor Name of Field Purchase	Type of Work Performed by Subcontractor soil analytical		Subcontractor or Field Purchase Amount \$
PDC Laboratories, Inc.			\$1,855.00
USPS	poslage	no prove	\$7.20
Т	otal Subcontractor and	l Field Purchase Costs	\$1,862.20

1,855,00

,


			I A
Total Landling Charges:	6005 AC	ddd.	60
Total Handling Charges.	\$440 \$ 423.40	ano.	

Payment Certification Form Electronic Filing: Received, Clerk's Office 11/5/2020

This certification form must be included with every request for payment.

I, Mr. Wayne Pa				
application for payment is b	eing submitted, certify that $#23, 488, 48$ is the amount being sought in this			
application for payment,	\$0.00 has already been paid from the FUND for this occurrence, and			
\$0.00	has been sent to the Illinois EPA for payment for this occurrence but has not yet been paid.			
I further certify that the number of petroleum USTs in Illinois presently owned or operated by the owner or				
operator, any subsidiary, parent or joint stock company of the owner or operator, and any company owned by				
any parent, subsidiary or joint stock company of the owner or operator is (check one):				

Fewer than 101 X



Except for applications for payment associated with Early Action, I certify that a plan for the work included in this application for payment was approved by the Illinois EPA on N/A (EA); except for applications for payment associated with to 35 Ill. Adm. Code 731, certify that a budget for the work included in this application for payment was approved by the Illinois EPA on N/A (EA); and certify that the amount sought for payment was expended in conformance with the approved budget and approved plan. I further certify that, if the costs included in this application for payment are approved for payment, the following limitations will not be exceeded:

- Payment will not result in the owner or operator receiving payment of corrective action costs or indemnification costs from the Fund for more than \$1,000,000 per occurrence for sites subject to 35 III. Admin. Code 731 or732. (OR) Payment will not result in the owner or operator receiving payment of corrective action costs or indemnification costs from the Fund for more than \$1,500,000 per occurrence for sites subject to 35 III. Admin. Code 734.
- 2. Payment of this claim will not result in the owner or operator receiving payment of corrective action costs or indemnification costs from the Fund incurred during a calendar year in excess of the following amounts:

For costs incurred in calendar years prior to 2002:

\$1,000,000, if fewer than 101 tanks were owned or operated in Illin \$2,000,000, if 101 or more tanks are owned or operated in Illinois.

For costs incurred in calendar years 2002 and later:

\$2,000,000, fi fewer than 101 tanks were owned or operated in Illin \$3,000,000, if 101 or more tanks are owned or operated in Illinois.

Owner/Operator Name:	Evelyn Page Trust		AK
Authorized Representative*	Mr. Wayne Page		Title: Trustee
Signature: Daw	- Aller		Date: 2/5/18
Subscribed and swo	χ n to before me the <u>54</u> da	y of February	2017
(this certification must be notarize	I when the certification is signed.)	OFFICIAL SEAL	www.
Wotar	y Public)	GAYE LYNN GREEN NOTARY PUBLIC - STATE OF ILL MY COMMISSION EXPIRES:05/	18/21 🏅

*For a corporation, a principal executive officer of at least the level of vice president, or a person authorized by a resolution of the board of directors to sign the applicable document if a copy of the resolution, certified as a true copy by the secretary of the corporation, is submitted with the document.

Owner/Operator and Licensed Professional Engineer/Geologist Billing Electronic Filing: Received, Clerk's Office 11/5/2020

Under penalty of perjury as defined in Section 32-2 of the Criminal Code of 1961 [720 ILCS 5/32-2], I certify to the following:

- * The bills in the attached application for reimbursement are for performing corrective action activities associated with Incident # 20170100 reported for the Leaking Underground Storage Tank site located at address:

 City :
 Trivoli

 State:
 Illinois

 Zip:
 61569
- * The bills are for the billing period: $\frac{2/1/17}{110}$ through $\frac{5/17/17}{110}$ and were incurred in conformance with the Environmental Protection Act and 35 III. Adm... Code 731, 732 or 734.
- * The attached application for reimbursement and all documents submitted with it were prepared under the supervision of the licensed professional engineer or licensed professional geologist and the owner and/or operator whose signatures are set forth below and in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information provided. The information in the attached application for reimbursement is, to the best of my knowledge and belief, true, accurate, and complete.
- * The costs for remediating the above-listed incident are correct, are reasonable, and if applicable, were determined in accordance with Subpart H: Maximum Payment Amounts, Appendix D Sample Handling and Analysis amounts, and Appendix E Personnel Titles and Rates of 35 III. Adm. Code 732 or 734.
- * I am aware there are significant penalties for submitting false statements or representations to the Illinois EPA, including but not limited to fines, imprisonment, or both as provided in Section 44 of the Environmental Protection Act [415 ILCS 5/44] and Section 32-2 of the Criminal Code of 1961 [720 ILCS 5/32-2].

Owner/Operator Name: Evelyn Page Trust

Authorized R	epresentative**: Mr. Wayne Page			
Address:	24 Rutledge Avenue		Phone: (309) 573-23	67
City: Barton	ville	State: Illinois	Zip: <u>61607</u>	
Signature:	Waymand toz		Date: 2/5/1	CENF
Subșcribed a	nd sworn to before me the 54 day of	February	2 Adrammas	
$\underline{\nabla}$	an Kin Sun	Seal: GAY	F I YNN GREEN	APR 02 2018
	Notan Public) 3. Name: Penny Silzer	S MY COMMI	BLIC - STATE OF ILL MOIS	PABO
L.P.E./L.P.G	. Illinois Registration No: <u>196-000256</u>	· · · · · · · · · · · · · · · · · · ·	PENNY L.	DK
L.P.E./L.P.G. F	Registration Expiration Date: 3/31/2019		NO. 196-000256	
Company N	ame: Midwest Environmental Consulting & Rem	ediation Service, Inc.		*
Address:	22200 IL Rte. 9; P.O. Box 614	<u> </u>	Phone: 369) 625	5551
City:		State: Illinois	Zip:6150	38
L.P.E./L.P.G.	Signature:	Date: _	2/5/18	
Subscribed a	and sworn to before me the 5% day of	February	2018 man	
<u>V</u>		Seal: Seal:	ICHAL SEAL	
	(Notary ⊉ublic) (& NOTARY PUR	LIC-STATE OF ILLINUIS	
**For a corpora	ition, a principal executive officer of at least the level of vice	president. ar a person auto	orized by a resolution of	

**For a corporation, a principal executive officer of at least the level of vice president, or a person authorized by a resolution the board of directors to sign the applicable document if a copy of the resolution, certified as a true copy by the secretary of the corporation, is submitted with the document.

Private Insurance Coverage Questionnaire Electronic Filing: Received, Clerk's Office 11/5/2020

This form must be completed in full by all owners or operators, or their authorized representatives, that have a claim for payment from the State of Illinois Underground Storage Tank Fund for the labor, materials, overhead, and profit costs related to the investigation and/or remediation of a Leaking UST site.

1.	Site Name:	Evelyn Page Trust			
	Address:	23907 West Farmington Road			
	City:	Trivoli	State: Illinois	Zip:	61569
2.	Name of in	surance company providing coverage for this Lea	king UST site:		
	N/A				
3.	Amount of	coverage provided: <u>N/A</u>			
4.	Have you c	or your firm filed a claim against your insurance co	mpany for this Leaking UST site?		
		Yes No X			
	a.	If yes, how much is the claim? <u>N/A</u>			
	b.	If no, explain why. <u>No Insurance</u>			
5.	Have you c	or your firm received payment for a claim against y	your insurance company for this L		
	site?	Yes No X			
	a.	If yes, how much and when? <u>N/A</u> Date:	1.1.1.1.1.2. 0.1. 1.1.1.1.0.		
	b.	If no, explain why. <u>No Insurance</u>			
	Are you go	ing to file a claim against your insurance policy? Yes No X			
	a.	If yes, how much and when? <u>N/A</u> Date:			
	b.	If no, explain why. <u>No Insurance</u>			

This Illinois EPA is authorized to request this information under the Environmental Protection Act, 415 ILCS 5/1 et seq. (formerly Ill. Rev. Stat. Ch 11-1/2, 1001 et seq.). Disclosure of this information is required. Failure to properly complete this form in its entirety may result in the delay or denial of any payment requested hereunder. This form has been approved by the Forms Management Center.

PRIVATE INSURANCE AFFIDAVIT

ι,

l,	, a duly authorized r	epresentative of			
		Evelyn Page			1
	(own	er/operator or t	firm's name)		
hereby certify that	Evelyn Page Trus (owner/operator or firm's	t name)	_ (does, does not)	does not (choose one)	have private
insurance coverage for a	ll or part of the costs related	to claim for pa	yment of	Evelyn Pag (owner/operator o	
investigation or remediat	ion costs for work performed	i at		Page Trust name)	located at
	23907 West	Farmington Ro	ad, Trivoli, IL 6156	9	
		(addres	ss)		
l, Mr. Wayne	Page		of	Evelyn F	Page Trust or or firm's name)
(name)		(title)		(owner/operato	or or firm's name)
	e, the above information is a A for any overpayment made ich site.				
Owner/Operator:	Evelyn Page Trust	∄Mr. Wayne Pa	age	Title: \underline{Tr}	ustee
Signature:	Day may Alog			0	5/18
Subscribed and sworn to	before me the 5^{4}	day of	February	2018	·
Cley	(Notary Public)	ery	Seal:	GAYE LYNN GAYE LYNN NOTARY PUBLIC - STA MY COMMISSION EX	GREEN §

The Illinois EPA is authorized to require this information under 415 ILCS 5/1. Disclosure of this information is required. Failure to do so may result in the delay or denial of any budget or payment requested hereunder. This form has been approved by the Forms Management Center.

	Electronic Filing: Received, Clerk's (Jffice 11/5/	2020
Depart	November 2017) ment of the Treasury I Revenue Service Go to www.irs.gov/FormW9 for instructions and the la	test information.	Give Form to the requester. Do not send to the IRS.
	1 Name (as shown on your income tax return). Name is required on this line; do not leave this line blan Evelyn M. Page Revocable Living Trust 2 Business name/Bisregarded entity name, if different from above Waune Page. Trustee	k.	
r. Is on page 3.	2 Check apprendiate how forfactoral tax classification of the person whose name is entered on line 1 (Check only one of the	4 Exemptions (codes apply only to certain entities, not individuals; see instructions on page 3): Exempt payee code (if any)
Print or type. Specific Instructions on page	Limited liability company. Enter the tax classification (C=C corporation, S=S corporation, P=Partr Note: Check the appropriate box in the line above for the tax classification of the single-member LLC if the LLC is classified as a single-member LLC that is disregarded from the owner unless the another LLC that is not disregarded from the owner for U.S. federal tax purposes. Otherwise, a si is disregarded from the owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of its owner should check the appropriate box for the tax classification of the should check the appropriate box for the tax classification of the should check the appropriate box for the tax classification of the should check the appropriate box for the tax classification of the should check the appropriate box for the	owner. Do not check owner of the LLC is ngle-member LLC that	Exemption from FATCA reporting code (if any)
ecif	□ Other (see instructions) ►		(Applies to accounts maintained outside the U.S.)
See Sp	24 Rutledge Avenue 6 City, state, and ZIP code Bartonville Illinois 6/607	Requester's name a	ınd address (optional)
Par	7 List account number(s) here (optional) Taxpayer Identification Number (TIN)		
Enter backu reside	your TIN in the appropriate box. The TIN provided must match the name given on line 1 to a p withholding. For individuals, this is generally your social security number (SSN). However, ant alien, sole proprietor, or disregarded entity, see the instructions for Part I, later. For other is, it is your employer identification number (EIN). If you do not have a number, see <i>How to g</i>	for a	urity number
Note: Numb	If the account is in more than one name, see the instructions for line 1. Also see What Name er To Give the Requester for guidelines on whose number to enter.		identification number - 6528418
Par	III Certification		

Under penalties of perjury, I certify that:

- 1. The number shown on this form is my correct taxpayer identification number (or I am waiting for a number to be issued to me); and
- 2. I am not subject to backup withholding because: (a) I am exempt from backup withholding, or (b) I have not been notified by the Internal Revenue Service (IRS) that I am subject to backup withholding as a result of a failure to report all interest or dividends, or (c) the IRS has notified me that I am no longer subject to backup withholding; and
- 3. I am a U.S. citizen or other U.S. person (defined below); and
- 4. The FATCA code(s) entered on this form (if any) indicating that I am exempt from FATCA reporting is correct.

Certification instructions. You must cross out item 2 above if you have been notified by the IRS that you are currently subject to backup withholding because you have failed to report all interest and dividends on your tax return. For real estate transactions, item 2 does not apply. For mortgage interest paid, acquisition or abandonment of secured property, cancellation of debt, contributions to an individual retirement arrangement (IRA), and generally, payments other than interest and dividends, you are not required to sign the certification, but you must provide your correct TIN. See the instructions for Part II, later.

			/	
Sign Here	Signature of U.S. person ►	Warne &	intro >	
<u>^</u>				Form 1099-DIV (dividends, including those from stocks or mutual

General Instructions

Section references are to the Internal Revenue Code unless otherwise noted.

Future developments. For the latest information about developments related to Form W-9 and its instructions, such as legislation enacted after they were published, go to www.irs.gov/FormW9.

Purpose of Form

An individual or entity (Form W-9 requester) who is required to file an information return with the IRS must obtain your correct taxpayer identification number (TIN) which may be your social security number (SSN), individual taxpayer identification number (ITIN), adoption taxpayer identification number (ATIN), or employer identification number (EIN), to report on an information return the amount paid to you, or other amount reportable on an information return. Examples of information returns include, but are not limited to, the following.

Form 1099-INT (interest earned or paid)

 Form 1099-DIV (dividends, including those from stocks or mutual funds)

- Form 1099-MISC (various types of income, prizes, awards, or gross proceeds)
- Form 1099-B (stock or mutual fund sales and certain other transactions by brokers)
- Form 1099-S (proceeds from real estate transactions)
- · Form 1099-K (merchant card and third party network transactions)
- Form 1098 (home mortgage interest), 1098-E (student loan interest), 1098-T (tuition)
- Form 1099-C (canceled debt)
- · Form 1099-A (acquisition or abandonment of secured property)

Use Form W-9 only if you are a U.S. person (including a resident alien), to provide your correct TIN.

If you do not return Form W-9 to the requester with a TIN, you might be subject to backup withholding. See What is backup withholding, later.

0150

Electronic Filing: Received, Clerk's Office 11/5/2020 Women and Minority Business Enterprises Form

The Illinois EPA is required to report State and Federal funds paid to Women's Business Enterprises (WBE) and Minority Business Enterprises (MBE). Therefore, please provide their required information for all Prime Consultants/Contractors and Subcontractors used to perform the work for this billing:

Name of LUST Site:	Evelyn Pa	ge Trust		Incident No.	20170100
The work for this billi	ng was performed from: _	2/1/11	to:	5/17/1	1
Prime Consultant:	Midwest Environmental (Consulting and	Remediatio	n Services, Ir	nc. (MECRS)
FIRM'S NAME, ADD TELEPHONE NUME	BER I	FIRM A WI WBE OR OF	WBE OR M HAT IS ITS FILLINOIS	STATE	AMOUNT PAID OR DUE THIS BILLING (\$)

	IMRE3.	VENDOR NUMBER?	
MECRS, 22200 IL Rt. 9, Tremont, IL 309-925-5551	no		\$6,464.99
PDC Laboratories, Inc., 2231 W. Altorfer Dr., Peoria, IL, 692-9688	no		\$1,855.00
IOME, Inc., 850 Brenkman Dr., Pekin, IL 61554	no		\$14,030.00

BILLING TOTAL \$22,349.99

The Illinois EPA is authorized to request this information under Environmental Protection act, 415 ILCS 5/1 et seq. (formerly III Rev. Stat. Ch 111 1/2, 1001 et seq.). Disclosure of this information is required. Failure to properly complete this form in its entirety may result in the delay or denial of any payment requested hereunder. This form has been approved by the Forms Management Center.

Electronic Filing: Received, Clerk's Office 11/5/2020 Midwest Environmental Consulting &

AIZAM

Midwest Environmental Con Remediation Services Inc 22200 Illinois Route 9 P.O. Box 614 Tremont, IL 61568-0614

BIL	17	FO1
0.0	-	~

WAYNE PAGE 24 RUTLEDGE AVE. BARTONVILLE, IL 61607

				TERMS	PROJECT	SITE L	OCATION
				UPON RECEIPT		TR	JVOLI
ITEM	DATE	QTY.	RATE				AMOUNT
PROJECT MANAG	3/1/17	3		E.ACTION;20 DAY/45 DA	AY;REPORTS;PERMIT	S	337.02
PROJECT MANAG	3/2/17	2.5	112.34	E.ACTION; REPORTS			280.85
ROJECT MANAG	3/3/17	1.5		E.ACTION; REPORTS			168.51
R. ENV MANAG	3/7/17	1.25		E.ACTION			151.86
PROJECT MANAG	3/7/17	2.5	112.34	E.ACTION; REPORTS		1	280.85
R. ENV MANAG	3/8/17	1	121.49	E.ACTION			121.49
ROJECT MANAG	3/8/17	1	112.34	E.ACTION;REPORTS		and the second	112.34
R. ENV MANAG	3/10/17	4.75	121.49	E.ACTION;SITE;UST PU	LL; SAMPLING; MAPS;	REPORTS	577.08
/IILEAGE	3/10/17	6.6	5.80				38.28
PID	3/10/17	1	75.00				75.00
NCORE SAMPLE	3/10/17	6	12.52	Contraction of the second s			75.12
ROJECT MANAG	3/13/17	2	112,34	E.A.; REPORTS			224.68
R. ENV MANAG	3/14/17	2		E.ACTION;SITE;UST PU	LL; SAMPLING:MAPS	REPORTS	242.98
ROJECT MANAG	3/14/17	2		E.A.;REPORTS			224.68
ROJECT MANAG	3/21/17	2		E.ACTION; REPORTS			224.68
R. ENV MANAG	3/21/17	1		E.ACTION			121.49
ROJECT MANAG	3/22/17	3.5		E.ACTION; REPORTS			393.19
R. ENV MANAG	3/22/17	1		E.ACTION			121.49
ROJECT MANAG	3/23/17	1.5		REPORTS			168.51
ROJECT MANAG	3/24/17	1.5		REPORTS			168.51
R. ENV MANAG	3/29/17	1		E.ACTION			121.49
R. ENV MANAG	3/30/17	1.5		E.ACTION			182.24
R. ENV MANAG	4/5/17	2.5		E.ACTION			303.73
R. ENV MANAG	4/6/17	1.5		E.ACTION;REPORTS;M/	APS:CACR		182.24
R. ENV MANAG	4/7/17	2		E.ACTION;REPORTS;MA			242.98
R. ENV MANAG	4/10/17	1.5		E.ACTION;REPORTS;M/			182.24
R. ENV MANAG	4/12/17	1		E.ACTION;REPORTS;MA			121.49
eimb Group							\$ 1,855.0
centro Group	4/14/17	45	2.076.34	LAB ANALYSIS SOIL			2.076.34
	0.0.7		2,010101	Total Reimbursable Expen	ses		2.076.34
		1	12.00%	Markup		K	22 10 249.16
			12,0070	Total Reimbursable Expen	ses	H ×	2.325.50
							#2077.60
							0301160
THANK YOU!	-					Er-	1697 1
PLEASE CALL WITH	ANY OUEST	IONS			Total	P,	1200.60
(309) 925-5551	ANY QUEST	IUNS.			Total		\$7,770.

0152

DATE INVOICE NO. 4/14/17 6700B

Invoice

PDC LABORATORIES, INC. P.O. Box 9071 Electr Peoria, Illinois 61612-9071 (309) 692-9688	onic Filing: Received,	Invoice Number Clerk's Offic		S
Account: FIRST STUDENT	Account Number: 0211732	Terms: NET 30	Invoice Date:	04/15/17
	#TESTS	UNIT COST	EXT. COST	
ACCOUNT: 0211732 MIDWEST ENVIRONMEN FIRST STUDENT * 7032606 * Rcvd 03/1				
5035 Kit	7.00	.00	.00	
M8260 BTEX	7.00	78.00	546.00	
M8310	7.00	175.00	1,225.00	
Solids-TS	7.00	12.00	84.00	
	TOTAL FOR INVOIC	E 860599S:		1,855.00

2° 10' 34

Please retain this original portion for your records. A delinquency charge will be added

Remit to: PDC LABORATORIES, INC. P.O. Box 9071 Peoria, Illinois 61612-9071

> MIDWEST ENVIRONMENTAL PO BOX 614 TREMONT, IL 61568

of 1.5% per month - 18% per annum.

Account Number: 0211732 Invoice Number: 860599S Terms: NET 30

Invoice Date: 04/15/17

Balance Due: 1,855.00

Amount Paid: _____

Midwest Environmental Consulting & Remediation Services Inc 22200 Illinois Route 9 P.O. Box 614 Tremont, IL 61568-0614

	n		NI	10	0
		VV	\cup	C	G
~		-	- C - C - C - C - C - C - C - C - C - C	-	-

DATE	INVOICE NO.
5/18/17	6704B

BILL TO

WAYNE PAGE 24 RUTLEDGE AVE. BARTONVILLE, IL 61607

				TERMS	PROJECT	SITE L	OCATION
				UPON RECEIPT		FARM	MINGTON
ITEM	DATE	QTY.	RATE			-	AMOUNT
P.G PROJECT MANAG RENV MANAG PROJECT MANAG ROJECT MANAG ROJECT MANAG RENV MANAG RENV MANAG RENV MANAG RENV MANAG Reimb Group	4/10/17 4/13/17 4/13/17 4/14/17 4/14/17 4/19/17 5/2/17 5/11/17 5/17/17 5/10/17	1 2 0.5 0.75 1 1.25 1 0.5 (55 5 5 5 5 5 5 5 5 5 5 5 5	112.34 121.49 112.34 121.49 112.34 121.49 121.49 121.49	45 DAY;PG CERT EA;REPORTS REPORTS;REIMB EA;REPORTS REPORTS;REIMB EA;REPORTS REIMB;REPORTS REIMB POSTAGE Total Reimbursable Expen- Markup Total Reimbursable Expen-			133,64 224,68 60,75 56,17 91,12 112,34 151,86 121,49 60,75 7,20 7,20 7,20 7,20 0,86 8,06

EVEL.YN M. PAGE REV LIVING TRUST W. PAGE K. PAGE L. MARSH CO. TTEES 24 BUTLEDGE AVE. BARTONVILLE, IL 61607-2609	6-16-201	773(7 Dațe
Pay to the INTYRSIATE (HE O Order of Inters Const of Urnle Jurndred Fitters const of P.O. Box 1715, Peoria, IL 61656-1715 For WASTE REPORT	nicon 500 Lingung	\$915 Dollars
 Secure (Balans exerce club) Secure (Balans exerce club) Matter (Balans exerce club) Matter (Balans) exerce club) 	20170719 >031000053< PNC Bank DEP. TO CR. PAYEE ABS. OF END. GTD. >031000053<	2931412 HECK HERE IF MOLILI DO HOT WHITE, STAMP OF SIGN LELD DO HOT WHITE, STAMP OF SIGN SIGN LELD
Die wief one hief • Light for hie phone helter ann de tro met sing, et oppene admite • Sundare feit die buie to sig mit of heid nör oppene admite • Bindle starte and calored oppene up, but on helte heit beit beit • Oppene		ILF DEPOSI

Electronic Endorsements

.

`

 Seq# Record Type
 Description ID
 BusDate
 Seq#
 RT# Truncated
 Converted
 Corrected
 Return Code

 1
 A
 BOFD
 1
 07/19/2017
 599001011140
 31000053
 Y
 Å

.



Tradebe Environmental Services, LLC

1433 E 83rd Ave, Suite 200 Mernilville, IN 46410 www.tradebeusa.com

CERTIFICATE OF RECYCLE

To whom this may concern

This certificate is to verify that the waste described below, is handled in accordance with local, state, and federal regulations.

Generator:

Name: Estate of Evelyn M. Page

Address: 23907 West Farmington Farmington , IL 61531

Sales Order: 1441595

Facility TTR East Chicago 4343 Kennedy Avenue East Chicago, IN 46312 EPA ID: IND000646943

Profile	Manifest / Page / Line	Quantity	Hcode
17060096	016662830JJK 00001/001	1.000	H020
17060097	016562830JJK 00001/002	2.000 DM	H020

Robert O'Brien Executive Vice President of Operations

TRADEBE TREATMENT AND RECYCLING LLC

Date:06/23/2017

On behalf of its subsidiary: Tradebe Treatment and Recycling, LLC

RESPONSIBLE SM RECYCLING A commitment to our generators our employees and our community.

		-	Elec	tronic F	iling: Re	ceived,	Clerk's O	ffice 1	1/5/202	20		<i>.</i> .
~		· · · · · · · · · · · · · · · · · · ·	,				· / · /	* / \$		-		
		ต์ or type. (Form desig ORM HAZARDOUS	1. Generator ID Num		nter.)	2. Page 1 of	3. Emergency Respons	se Phone	4. Manifest	Tracking N	umber	DMB No. 2050-0039
	W	ASTE MANIFEST	n <u>e</u>				is màric		01	<u>896</u>	<u>2830</u>	<u>) JJK</u>
		nerator's Name and Maili State of Existence	•		• .	, <u>– 14.</u>	Generator's Site Addres	s (if different l	than mailing addre	ess)		_
		Sangara na panang										
	Gener	ator's Phone:	·	<u> </u>								
		nsporter 1 Company Nan							U.S. EPÁ IĎ	Number		
		<u>ురి శ్వధరి</u> nsporter 2 Company Nan				-			U.S. EPA ID	Number	<u> </u>	
												·
	1	signated Facility Name an			. .				U.S. EPA ID	Number		
		al (Enned) Art of Card										
	Facilit	y's Phone: 310 21	17. 3051						<u> </u>	, - :	<u></u>	· ·
	9a. HM	9b. U.S. DOT Descripti and Packing Group (if a		hipping Name, Haza	ard Class, ID Numbe	r.	10. Conta No.	iners Type	11. Total Quantity	12. Unit Wt./Vol.	13. W	aste Codes
		1.	a Casali e						1		• #	
ATO	×		ы д тэр б у (246)				001	DF	055			
GENERATOR		2.	· · · · · · · · · · · · · · · · · · ·					-Las Laring				
ŝ	y.	Turke zu indere Sinder	್ ೈಚಿತ್ರಕ ಬಿಳ				- O	心啊	3		4	
		3,	·			<u></u>	002	· ••••••	110			
		э.										
•												
•		4.										
									ļ			
	14. Sp	ecial Handling Instruction	s and Additional Inform	nation *x:1	I STOCAME	1 Ingmus p	Right 28 2107 -	TREAL	# 170B66097	ERG#1	26	
										i .		
ļ										1		
	15. G	ENERATOR'S/OFFERO	R'S CERTIFICATION	: I hereby declare the pects in proper con-	hat the contents of the	is consignment a	re fully and accurately di able international and na	escribed abov tional poverni	ve by the proper st mental regulations	hipping name	e, and are class	ified, packaged,
) 6	exporter, I certify that the occurring that the occurring that the waste min	contents of this consig	nment conform to th	e terms of the attacl	ned EPA Acknowl	edgment of Consent.	-	-	n expanses		
		ator's/Offeror's Printed/Ty	ped Name	<u></u>			lature	(Monil	n Day Year
ţ	18 101	emational Shipments	<u>) (())</u>		.	\`	23.32	· .	<u>4 8.4</u>	<u></u>		
INT	1	porter signature (for expo	Import to U (U): ts only):	.S.	L	Export from U		ntry/exit: /ing U.S.:				
-	17. Tra	Insporter Acknowledgmen	t of Receipt of Material	s								
ORT	Transp ∮	orter 1 Printed/Typed Nar	ne Á Í			Sigr	ature				Month Le Sec	Day Year
TRANSPORTER	Transp	orter 2 Printed/Typel/Nai	<u> </u>	10367		l Sigr	atūre	**************************************		··	C's Monti	Day Year
R R					,							
1		crepancy					- <u></u>					
	18a. D	iscrepancy Indication Spa	ice Quantity	y	Ц] Туре		Residue		Partial Rej	jection	L	Full Rejection
1							Manifest Reference	e Number.				
	18b. Al	ternate Facility (or Gener	alor)						U.S. EPA ID	Number		
FACI	Facility	's Phone:		- -					Ì			
띮		ignature of Alternate Facil	ity (or Generator)		<u> </u>	······	<u> </u>				Mon	lh Day Year
DESIGNATED FACILITY	10 11-		nonomical Michael A	dag (i é	howardows weeks '	oimpet dic '	and mountine out the 1					
5	19, 19	zardous Waste Report Ma			nazaroous waste tre	aiment, disposal 3.	and recycling systems)	<u></u>	4.	·		······
Щ	1.		2	•								
8	1.			<u> </u>								
8	1. 20. De	signated Facility Owner o		<u> </u>	rdous materials cove	ered by the manif Sigr Q157		m 18a			Mont	h Day Year

.

Electronic Filing: Received, Clerk's Office 11/5/2020 Invoice



OIL MARKETING EQUIPMENT, Inc. 1-800-447-2611 850 Brenkman Drive, Pekin, IL 61554

Sold To: Wayne Page Evelyn Page Trust 24 Rutledge Ave. Peoria, IL 61607

Confirm To: Customer PO:

Invoice Date: 3/31/2017 Invoice Number: 0113973-INbrk Job Number: 0050413 Customer Number: 0005326 Salesperson: PB

23907 West Farmington Rd. Farmington, IL 61531

Ship To: First Student

Terms: Net 10

Tank Removal Breakdown:

DOT Drums, oil dry, removal material (tax Inci.)	=\$ 354.09
Labor	= \$ 5,574.06
Excavation	= \$ 3,997.50
Trucking and backfill 126 yds	= \$ 3,809.35
OSFM Permit	=\$ 205.00
Mileage 100 x .90	= <u>\$ 90.00</u>
Remove Tank as per Bid	= \$14,030.00

Thank you for your Business. Please remit to: 850 Brenkman Drive - Pekin, IL 61554

We accept VISA and Mastercard. Processing fees apply to installation invoices. 1 1/2% (18% Annual) Finance Charge will be added after 45 days.

All products and components carry the manufacturer's warranty which is passed on to purchaser according to manufacturer's policy. No other warranties are either expressed on implied.

14,030.00 Net Invoice: Sales Tax: Shipping & Handling:

Invoice Total:

14,030.00

0.00

0.00

Page:

1



850 Brenkman Drive o Pekin, IL 61554 Phone: 309-347-1819 ° Fax: 309-347-1881 E-mail: sales@iome.com . Home Page: www.iome.com

February 1, 2017

Attn: Al Green Midwest Environmental PO Box 614 Tremont, IL Zip

Job Description: Tank Removal@ Former First Student 23907 West Farmington Road Farmington, IL 61568 Quote #P170123Mrev

Gentlemen,

We are pleased to quote on the following:

Illinois Oil Marketing Equipment, Inc. is registered with the state of Illinois for removal, installation, testing, and repair of underground tanks containing volatile fuels.

Secure state of Illinois and city tank removal permits.

Make arrangements for state and local tank removal inspections.

Secure no soil samples. All environmental work to be performed by others Midwest Environmental. All environmental sampling is required to be completed by a registered professional engineer per new OSFM regulations. None of this activity is included within this proposal.

If it is determined at the time of the tank removal or during the soil sample analysis that contaminated soil is present, we will advise you of this. There will be an additional charge to further identify the contamination. If any clean-up is required, we then proceed on a revised contract basis or a time and material basis. Our labor and services for additional work will be invoiced at our usual rates for the service provided. Depending on exact circumstances at each location, clean-up expenses, after a deductible, may be reimbursable by the state of Illinois EPA clean-up fund. One hundred percent of clean-up expenses will not be reimbursable.

Tanks to be emptied by others.

If the tank is not empty, we will empty fuel only from the tank for \$.89 per gal. plus pumping and hauling charges of \$95.00 per hour.

We will pump any remaining sludge, fuels and/or water mixture into 1 drum. The cost of these drums is contained within our proposal. These drums and the product contained inside these drums remain the property of the tank owner and/or the waste generator. These drums must remain on your property until a waste generator's number is obtained, analytical testing is complete, and the quantity of waste is known. We recommend contacting @ (309) 264-5115.

Page 1 of 3

P170123Mrev



For additional department of transportation approved drums, if more than 1 drums are needed to contain the waste inside your tanks, add \$90.00 per drum. This includes the drum and pumping charges.

Provide barricades for adequate safety protection during the work process.

Remove concrete/blacktop at the surface grade over the areas to be excavated.

Within this bid, we have figured to leave in place any tank anchors that are below the tank. If there is any concrete below the surface grade, but poured over or around the tank as tank anchors or for any other purpose, there will be an additional charge to remove and dispose of this concrete.

Excavate and remove 1 tank, up to 10,000 gallon in capacity.

If the tank to be removed is larger than 10,000 gallons in aggregate capacity, add .45/gallon for additional capacity of tank(s) removed. If additional tanks within the same excavation are to be removed, add \$950.00 per additional tank plus .45/gallon of additional storage removed.

Fill the excavation with broken concrete from the driveway and sand, well compacted.

If the excavation is found to be contaminated by the inspector of the office of the state fire marshal, we will place all fill back into the excavation, line the excavation with visqueen, and fill the remainder of the excavation with the specified material. There will be a flat fee of \$1,000.00, in addition to our bid, for this service.

Sod/blacktop/concrete to be replaced by others.


De-gas and clean the tanks at the site location. This requirement is now being enforced by the state of Illinois EPA.

Clean and dispose of the tanks, as recommended by api-1604 and of the Illinois red book code, title 41. We assume the tanks to be removed are standard, single wall tanks. There may be an additional charge if the tanks are railroad cars or of special construction, or have been coated inside or outside with a fiberglas epoxy or other special coating. If the tank contents is other than that listed on this proposal, there may be an additional charge for tank cleaning.

Tank Removal	\$ 13,830.00		
State of IL tank removal inspection fee	\$ 200.00		
Total price	= \$	====== 14,030.00	

Page 2 of 3 .

P170123Mrev



This removal is proposed according to state regulations as of the date of the proposal. Any new regulations put into effect after this date may change the price of our quotation. If you choose our proposal, we will notify you before we begin work if we are made aware of any changes in regulations.

If you would like us to proceed with this work on the basis stated, please affix an authorized signature of acceptance to one copy of this proposal. Return it to us with your check for \$200.00 to cover prepaid inspection fees.

Any alteration or change from original proposed specifications involving extra costs will be executed only upon written orders, and will become an extra charge item over and above the proposal.

Terms - net 30 days in full after substantial completion of work. On-going work will be billed on a monthly basis. The customer agrees to pay one and one half percent per month on past due balances. This represents an annual rate of eighteen percent. Purchaser agrees to pay seller reasonable attorney's fees and court costs if his account is placed in the hands of an attorney for collection.

Thank you for the opportunity to be of service. We look forward to the receipt of your order.

Respectfully Submitted,

シアン Toli Enertheas

Pete Bradshaw Accepted By: _____

Title: _____

Date: _____

mecrs

From:	"Kim Fairchild" <kim.fairchild@totalpetroleum.net></kim.fairchild@totalpetroleum.net>
Date:	Monday, January 30, 2017 2:28 PM
To:	<mdwstenv@frontier.com></mdwstenv@frontier.com>
Attach:	Quote #17015T Midwest EnvTank Removal - First Student - Farmington.pdf
Subject:	FW: Tank Removal - First Student - Farmington

From: Kim Fairchild [mailto:kim.fairchild@totalpetroleum.net]
Sent: Monday, January 30, 2017 1:47 PM
To: 'midwestenv@frontier.com'
Cc: tom.oltman@totalpetroleum.net
Subject: Tank Removal - First Student - Farmington


Hi Al,

Please find attached the quote for tank removal in Farmington. Please call with any questions. Thank you,

Kim Fairchild Total Petroleum Service Company 309-694-8224



(309) 694-8224



2421 Washington Road

Washington, IL 61571

1

January 30, 2017 Quote #17015T

Midwest Environmental 22200 IL Rte. 9 Tremont, IL 61568 Attn: Al Green

Re: First Student, Farmington, IL Tank Removal

Scope of Work:

We propose to obtain the necessary OSFM permits pertaining only to underground storage tank work. Excavate to the top of (1) 10,000 gallon fiberglass diesel tank. All excavated materials will be used as fill. Remove the tank top equipment and dispose of properly. Check the explosion levels in the tank and purge with air as needed. Power wash the interior of the tank and pump out the residuals. The liquids will be placed in (1) 55 gallon DOT approved barrel and left on site for analysis and disposal by others. Remove the tank from the excavation. Re-check the explosion levels. Cut the ends from the tank and check for proper cleaning. Load, off haul and dispose of the tank. Backfill with original materials and bring to grade with approximately 100 tons of gravel.

FOR THE SUM OF: \$14,250.00

In addition to our standard terms and conditions page, this quote does not include:

- Any union labor.
- Any contaminated soil or water issues.
- Any City of Farmington permits.
- Any piping removal.
- Any hauling of spoils.
- Any repairs to utilities in the excavation area.
- Any disposal of barrels for residuals.

THANK YOU FOR THE OPPORTUNITY TO QUOTE THIS PROJECT !!





2421 Washington Road

Washington, IL 6157

DATE: January 30, 2017 QUOTE #17015T AMOUNT OF BID: \$14,250.00 _____(Initial)

This estimate is based on normal excavating conditions. Any excessive water, rock, frozen or caving ground, encountered will be invoiced as an extra charge. Any unforeseen underground obstructions such as footings, foundations, conduits, sewers or other utilities encountered will be invoiced as an extra charge. Performing work in extremely hot, cold or wet conditions may increase estimate amount.

This estimate is based on tanks and piping being empty of all liquids and sludges. Additional charges will be invoiced for the removal and disposal of any liquids or sludges. If during the performance of work, it is determined the tanks sizes are larger than quoted or if tanks are internally lined, there will be additional charges invoiced.

If contaminated materials are present, there will be additional charges for testing, handling and disposal of these materials if required. If any unexpected developments occur which must be met due to Federal, State or Local Fire department or EPA regulations, there may me additional charges.

Any work being performed by others, not contracted by TPS shall in no way interfere with progress or completion of project by TPS.

TPS is not responsible for delays due to owner neglect or by delays authorized by owner due to changes in scope of work. TPS is not responsible for delays due to labor disputes, equipment deliveries, casualties, extreme weather or damage by others to petroleum equipment/materials or other causes beyond TPS control.

In the event that any of the above conditions arise or a request for additional work is made, the owner will be contacted for approval of additional costs and scheduled changes if required. Owner approval of contract changes is acceptable by change order signature, e-mail or fax to TPS office. Any additional work requested other than shown on this scope of work, will be invoiced at time and material rates, as an extra cost to the contract, unless other arrangements are in place. TPS will retain ownership of all materials and equipment until payment in full is received for same.

If payment is not received per the "Payment Terms", TPS shall have the right to enter the purchaser's premises at any time, remove the equipment/materials and proceed by all legal means to collect for all unpaid expenses incurred due to default of payment, including legal fees.

PAYMENT TERMS

Invoices Due Net/10 Days

A service charge of 1.5% (18% APR) will be charged on all accounts over 30 days. Accounts past due may be turned over for collection. All legal and collection fees will be the responsibility of the debtor.

ACCEPTANCE OF TERMS AND CONDITIONS


The above terms and conditions are satisfactory and hereby accepted. You are authorized to do the work specified. Payments will be made as outlined above.

NAME	DATE
------	------

COMPANY_____

4

WE LOOK FORWARD TO WORKING WITH YOU ON THIS PROJECT





Office of the Illinois State Fire Marshal

4/7/2017

Evelyn Page Trust 24 Rutledge Avenue Bartonville, IL 61607

> In Re: Facility No. 3000721 IEMA Incident No. 20170100 Evelyn Page Trust 23907 W. Farmington Rd. Farmington, Fulton, IL 61531

Dear Applicant:

The Reimbursement Eligibility and Deductible Application received on April 06, 2017 for the above referenced occurrence has been reviewed. The following determinations have been made based upon this review.

It has been determined that you are eligible to seek payment of costs in excess of \$5,000. The costs must be in response to the occurrence referenced above and associated with the following tanks:

Eligible Tanks

Tank 2 10000 gallon Diesel Fuel

You must contact the Illinois Environmental Protection Agency to receive a packet of Agency billing forms for submitting your request for payment.

An owner or operator is eligible to access the Underground Storage Tank Fund if the eligibility requirements are satisfied:

- 1. Neither the owner nor the operator is the United States Government,
- 2. The tank does not contain fuel which is exempt from the Motor Fuel Tax Law,
- 3. The costs were incurred as a result of a confirmed release of any of the following substances:

"Fuel", as defined in Section 1.19 of the Motor Fuel Tax Law

Aviation fuel

Heating oil

Kerosene

Used oil, which has been refined from crude oil used in a motor vehicle, as defined in Section 1.3 of the Motor Fuel Tax Law.

- 4. The owner or operator registered the tank and paid all fees in accordance with the statutory and regulatory requirements of the Gasoline Storage Act.
- 5. The owner or operator notified the Illinois Emergency Management Agency of a confirmed release, the costs were incurred after the notification and the costs were a result of a release of a substance listed in this Section. Costs of corrective action or indemnification incurred before providing that notification shall not be eligible for payment.
- 6. The costs have not already been paid to the owner or operator under a private insurance policy, other written agreement, or court order.
- 7. The costs were associated with "corrective action".

This constitutes the final decision as it relates to your eligibility and the set deductible. We reserve the right to change the deductible determination should additional information that would change the determination become available. An underground storage tank owner or operator may appeal the decision to the Illinois Pollution Control Board (Board), pursuant to Section 57.9 (c) (2). An owner or operator who seeks to appeal the decision shall file a petition for a hearing before the Board within 35 days of the date of issuance of the final decision, (35 Illinois Administrative Code 105.504(b)).

For information regarding the filing of an appeal, please contact:

Clerk Illinois Pollution Control Board State of Illinois Center 100 West Randolph, Suite 11-500 Chicago, Illinois 60601 (312) 814-3620

The following tanks are also listed for this site:

Tank 1 10000 gallon Gasoline

Your application indicates that there has not been a release from these tanks under this incident number. You may be eligible to seek payment of corrective action costs associated with these tanks if it is determined that there has been a release from one or more of these tanks. Once it is determined that there has been a release from one or more of these tanks you may submit a separate application for an eligibility determination to seek corrective action costs associated with this/these tanks.

If you have any questions, please contact our Office at (217) 785-1020.

Sincerely,

August Block

Deanne Lock Division of Petroleum and Chemical Safety

Electronic Filing: Received, Clerk's Office 11/5/2020. ILLINOIS ENVIRONMENTAL PROTECTION AGENCY



1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397 BRUCE RAUNER, GOVERNOR ALEC MESSINA, DIRECTOR

CERTIFIED MAIL # 7017 2680 0001 0214 8139

JUL 2 5 2018

Evelyn M. Page Trust Attn: Midwest Environmental Consulting & Remediation Services, Inc. 22200 Illinois Route 9, P.O. Box 614 Tremont, IL 61568

LPC #1438185006 -- Peoria County Re: Trivoli / Evelyn M. Page Trust 23907 West Farmington Road Incident-Claim No.: 20170100 -- 69179 Queue Date: April 2, 2018 Leaking UST Fiscal File

Dear Mr. Page:

The Illinois Environmental Protection Agency (Illinois EPA) has completed the review of your application for payment from the Underground Storage Tank (UST) Fund for the abovereferenced Leaking UST incident pursuant to Section 57.8(a) of the Environmental Protection Act (415 ILCS 5) (Act) and 35 Illinois Administrative Code (35 Ill. Adm. Code) 734.Subpart F.

This information is dated March 1, 2018 and was received by the Illinois EPA on April 2, 2018. The application for payment covers the period from February 7, 2017 to May 17, 2017. The amount requested is \$23,488.45.

On April 2, 2018, the Illinois EPA received your application for payment for this claim. As a result of Illinois EPA's review of this application for payment, a voucher for \$7,691.40 will be prepared for submission to the Comptroller's Office for payment as funds become available based upon the date the Illinois EPA received your complete request for payment of this application for payment. Subsequent applications for payment that have been/are submitted will be processed based upon the date complete subsequent application for payment requests are received by the Illinois EPA. This constitutes the Illinois EPA's final action with regard to the above application(s) for payment.

The deductible amount of \$5,000.00 was withheld from your payment. Pursuant to Section 57.8(a)(4) of the Act, any deductible, as determined pursuant to the Office of the State Fire Marshal's eligibility and deductibility final determination in accordance with Section 57.9 of the Act, shall be subtracted from any payment invoice paid to an eligible owner or operator.

There are costs from this claim that are not being paid. Listed in Attachment A are the costs that are not being paid and the reasons these costs are not being paid.

Page 2

An underground storage tank system owner or operator may appeal this decision to the Illinois Pollution Control Board. Appeal rights are attached.

If you have any questions or require further assistance, please contact Melissa Owens of my staff at (217)785-9351.

Sincerely,

Tregoy we

Gregory W. Dunn, Manager Leaking Underground Storage Tank Section Division of Remediation Management Bureau of Land

GWD:mad

Attachments

c: Evelyn M. Page Trust Leaking UST Claims Unit

Appeal Rights

An underground storage tank owner or operator may appeal this final decision to the Illinois Pollution Control Board pursuant to Sections 40 and 57.7(c)(4) of the Act by filing a petition for a hearing within 35 days after the date of issuance of the final decision. However, the 35-day period may be extended for a period of time not to exceed 90 days by written notice from the owner or operator and the Illinois EPA within the initial 35-day appeal period. If the owner or operator wishes to receive a 90-day extension, a written request that includes a statement of the date the final decision was received, along with a copy of this decision, must be sent to the Illinois EPA as soon as possible.

For information regarding the filing of an appeal, please contact:

Clerk of the Board Illinois Pollution Control Board James R. Thompson Center 100 West Randolph, Suite 11-500 Chicago, IL 60601 312/814-3620

For information regarding the filing of an extension, please contact:

Illinois Environmental Protection Agency Division of Legal Counsel 1021 North Grand Avenue East Post Office Box 19276 Springfield, IL 62794-9276 217/782-5544

Attachment A Deductions

Re: LPC #1438185006 -- Peoria County Trivoli / Evelyn M. Page Trust 23907 West Farmington Road Incident-Claim No.: 20170100 -- 69179 Queue Date: April 2, 2018 Leaking UST FISCAL FILE

Citations in this attachment are from the Environmental Protection Act (415 ILCS 5) (Act) and 35 Illinois Administrative Code (35 Ill. Adm. Code).

Item # Description of Deductions

\$2.97 for costs for vehicle charges, which lack supporting documentation. Such costs are ineligible for payment from the Fund pursuant to 35 Ill. Adm. Code 734.630(cc). Since there is no supporting documentation of costs, the Illinois EPA cannot determine that costs will not be used for activities in excess of those necessary to meet the minimum requirements of Title XVI of the Act. Therefore, such costs are not approved pursuant to Section 57.7(c)(3) of the Act because they may be used for site investigation or corrective action activities in excess of those required to meet the minimum requirements of Title XVI of the Act.

Pursuant to 35 Ill. Adm. Code 734.850(b) costs associated with activities that do not have a maximum payment amount set forth pursuant to 35 Ill. Adm. Code 734 Subpart H must be determined on a site specific basis and the owner/operator must demonstrate to the Agency the amounts sought for reimbursement are reasonable. The Agency has requested additional documentation to support the rate requested for vehicle charges pursuant to 35 Ill. Adm. Code 734.505(a). The documentation was either not provided or fails to provide sufficient information for the Agency to make a site specific reasonableness determination.

In addition, without supporting documentation the rate requested for vehicle costs is not reasonable as submitted. Such costs are ineligible for payment from the Fund pursuant to Section 57.7(c)(3) of the Act and 35 Ill. Adm. Code 734.630(dd).

The Illinois EPA will reimburse for mileage at a rate of \$0.535 when sufficient documentation has not been submitted for vehicle charges. 66 miles are being adjusted from \$0.58 per mile to \$0.535 per mile.

 \$7.20, deduction for costs for Consultant', which lack supporting documentation. Such costs are ineligible for payment from the Fund pursuant to 35 Ill. Adm. Code 734.630(cc). Since there is no supporting documentation of costs, the Illinois EPA cannot determine that costs will not be used for activities in excess of those necessary to meet the minimum requirements of Title XVI of the Act. Therefore, such costs are not approved pursuant to Section 57.7(c)(3) of the Act because they may be used for site investigation or corrective action activities in excess of those required to meet the minimum requirements of Title XVI of the Act.

No documentation is provided for postage.

3. \$144.82, deduction for a reduction in the personnel title listed in Section 734.APPENDIX E Personnel Titles and Rates. Pursuant to Section 734.850(b) personnel costs must not exceed the amounts set forth in Appendix E and the personnel costs must be based on the work performed, regardless the title of the person performing the work. The Project Manager rate has been reduced to a Senior Account Technician rate of \$144.82 per hour.

The costs exceed the maximum payment amounts set forth in Subpart H, Appendix D, and/or Appendix E of 35 Ill. Adm. Code 734. Such costs are ineligible for payment from the Fund pursuant to 35 Ill. Adm. Code 734.630(zz). In addition, such costs are not approved pursuant to Section 57.7(c)(3) of the Act because they are not reasonable and 35 Ill. Adm. Code 734.630(dd).

2.75 hours for Fetterolf have been adjusted from the Project Manager rate of \$112.34 to the Senior Account Technician rate of \$68.83.

4. Costs incurred after April 7, 2017 are not reimbursable. To be considered for reimbursement, early action activities must be performed within 45 days after initial notification to the Illinois Emergency Management Agency of a release plus 14 days. The costs in question were not incurred within the time allowed for reimbursement. Such costs are ineligible for payment from the Fund pursuant to 35 Ill. Adm. Code 734.210(g). In addition, such costs are not approved pursuant to Section 57.7(c)(3) of the Act because they are not site investigation or corrective action costs.

Based upon the above, a deduction of \$774.39 was made for Consulting Personnel, which consists of 1.5 hours on April 10th for \$182.24, 1 hour on April 12th for \$121.49. 1 hour of April 10th for \$133.64, 2 hours on April 13th for \$224.68, and 1 hour on April 19th for \$112.34.

5. Costs incurred after April 7, 2017 are not eligible for reimbursement. To be considered for reimbursement, early action activities must be performed within 45 days after initial notification to the Illinois Emergency Management Agency of a release plus 14 days. The costs in question were not incurred within the time allowed for reimbursement. Such costs are ineligible for payment from the Fund pursuant to 35 Ill. Adm. Code 734.210(g). In addition, such costs are not approved pursuant to Section 57.7(c)(3) of the Act because they are not site investigation or corrective action costs.

Based upon the above, a deduction of \$915.00 was made for drum disposal.

6. \$8,951.81, deduction for costs for UST Removal, which lack supporting documentation. Such costs are ineligible for payment from the Fund pursuant to 35 III. Adm. Code 734.630(cc). Since there is no supporting documentation of costs, the Illinois EPA cannot determine that costs will not be used for activities in excess of those necessary to meet the minimum requirements of Title XVI of the Act. Therefore, such costs are not approved pursuant to Section 57.7(c)(3) of the Act because they may be used for site investigation or corrective action activities in excess of those required to meet the minimum requirements of Title XVI of the Act.

In addition, 35 Ill. Adm. Code 734.800(a)(2) states that, as an alternative to using the amounts set forth in Sections 734.810 through 734.850 of this Part, the second method for determining the maximum amounts that can be paid for one or more tasks is bidding in accordance with Section 734.855 of this part. None of the guidelines for this method were followed. The owner/operator has failed to demonstrate that the bidding regulations of 35 Ill. Adm. Code 734.855 have been satisfied.

The subpart H rate for removal of a 10,000 gallon tank in the amount of \$3,942.33 plus backfill costs of 45.38 cubic yards at \$25.03 per cubic yard for a total of \$5,078.19 are being reimbursed.

7. \$0.86, deduction for handling charges for subcontractor costs when the contractor has not submitted proof of payment for subcontractor costs. Such costs are ineligible for payment from the Fund pursuant to 35 Ill. Adm. Code 734.630 (ii). In addition, such costs are not approved pursuant to Section 57.7(c)(3) of the Act because they are not reasonable.

Handling on postage is being cut because proof of payment was not provided.

mao



	1		
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY		
Complete items 1, 2, and 3. LCU 24	A. Signature		
Print your name and address of the everse	$X \bigcirc 0 $ \mathcal{H} \Box Agent		
so that the card www	B. Received by (Printed Name) C. Date of Delivery		
Attach this card to the back of the mailpiece, or on the front if space permits.	2. Received by (Finned Hame)		
1. Article Addressed to:	D. Is delivery address different from item 1? Yes Yes		
Evelyn M. Page Trust	If YES, enter delivery address below:		
c/o Midwest Environmental Consulting			
& Remediation Services, Inc.			
22200 Illinois Rt. 9, P. O. Box 614			
Tremont, IL 61568			
	3. Service Type □ Priority Mall Express®		
A THE REAL PROPERTY AND A	Adult Signature Restricted Delivery Delivery Delivery Delivery		
9590 9402 3341 7227 9129 59	Certified Mail Restricted Delivery		
2. Article Number (Transfer from service [abel]	□ Collect on Delivery Restricted Delivery □ Signature Confirmation™		
7017 2680 0001 0214 8139	Insured Mail Insured Mail Insured Mail Insured Mail Restricted Delivery Restricted Delivery		
	(over \$500)		
PS Form 3811, July 2015 PSN 7530-02-000-9053	Domestic Return Receipt		